



Micrel / Microchip Technology

## SY58034UMG

Tau Wae:

SY58034UMG

Kaihanga / Waitohu:

Micrel / Microchip Technology

Whakaahuatanga hua

IC CLK BUFFER 2:6 7.5GHZ 32MLF

Ngā Rauemi:

SY58034UMG.pdf

RoHS Tūnga

Whakahaerehia te kore utu / RoHS

Waehe Stock

9072 pcs stock

Tuhinga mai i

Hong Kong

Te Ara Tuhi

DHL/Fedex/TNT/UPS/EMS

**TONO MO TE WHAKAHUA**

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

### Ngā whakaaturanga o SY58034UMG

TAU WAE	SY58034UMG
KAIHANGA	Micrel / Microchip Technology
WHAKAAHUATANGA	IC CLK BUFFER 2:6 7.5GHZ 32MLF
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
HE RAHINGA KEI TE WĀTEA	9072 pcs
PEPA RARAUNGA	SY58034UMG.pdf
TUHINGA O MUA	2.375 V ~ 3.6 V
MOMO	Fanout Buffer (Distribution), Multiplexer
PŪRERE PŪRERE WHAKARATO	32-MLF® (5x5)
RAUPAPA	Precision Edge®
RATONGA - WHAKAURU: WHAKAPUTA	2:6
PACKAGING	Tube
PAA / CASE	32-VFQFN Exposed Pad, 32-MLF®
WHAKAPUTA	CML
ĒTAHI INGOA	576-1391
TAE MAHI	-40°C ~ 85°C
TUHINGA O MUA	1
MOMO TAE	Surface Mount
TAUMATA WHAKAARO MOE (MSL)	2 (1 Year)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
WHAKAURU	CML, LVDS, PECL
TAUTANGA - MAX	7.5GHz
MOTUHAKA - WHAKAURU: WHAKAPUTA	Yes/Yes
WHAKAAHUATANGA TAIPITOPITO	Clock Fanout Buffer (Distribution), Multiplexer IC 2:6 7.5GHz 32-VFQFN Exposed Pad, 32-MLF®
TAU WAE TUAKIRI	SY58034

### Ngā tūtohu e hāngai ana

Micrel / Microchip Technology SY58034UMG	SY58034UMG Kaiwhiwhi	SY58034UMG Kaiwhakarato
SY58034UMG Utu	SY58034UMG Pikitia	SY58034UMG Whakaahua
SY58034UMG PDF Datasheet	SY58034UMG Download Datasheet	Tuhinga SY58034UMG
SY58034UMG Stock	Hokona SY58034UMG	Hokona Micrel / Microchip Technology SY58034UMG
Micrel / Microchip Technology SY58034UMG	Micrel / Microchip Technology Kaiwhakarato	Micrel / Microchip Technology Kaiwhiwhi
Micrel / Microchip Technology SY58034UMG	Microchip Technology SY58034UMG	Roving Networks / Microchip Technology SY58034UMG

### Ngā Hua e hāngai ana

<p><b>SY58032UMI-TR</b> Kaihanga: Micrel / Microchip Technology Whakaahuatanga: IC CLK BUFFER 1:8 4GHZ 32MLF I roto i te taonga: 14352 pcs</p> <p><b>RFQ</b></p>	<p><b>SY58035UMG-TR</b> Kaihanga: Micrel / Microchip Technology Whakaahuatanga: IC CLK BUFFER 2:6 5.5GHZ 32MLF I roto i te taonga: 14039 pcs</p> <p><b>RFQ</b></p>
<p><b>SY58033UMI-TR</b> Kaihanga: Micrel / Microchip Technology Whakaahuatanga: IC CLK BUFFER 1:8 5.5GHZ 32MLF I roto i te taonga: 13166 pcs</p> <p><b>RFQ</b></p>	<p><b>SY58035UMI</b> Kaihanga: Micrel / Microchip Technology Whakaahuatanga: IC CLK BUFFER 2:6 5.5GHZ 32MLF I roto i te taonga: 9774 pcs</p> <p><b>RFQ</b></p>
<p><b>SY58032UMI</b> Kaihanga: Micrel / Microchip Technology Whakaahuatanga: IC CLK BUFFER 1:8 4GHZ 32MLF I roto i te taonga: 10542 pcs</p> <p><b>RFQ</b></p>	<p><b>SY58033UMG-TR</b> Kaihanga: Micrel / Microchip Technology Whakaahuatanga: IC CLK BUFFER 1:8 5.5GHZ 32MLF I roto i te taonga: 11094 pcs</p> <p><b>RFQ</b></p>
<p><b>SY58034UMG-TR</b> Kaihanga: Micrel / Microchip Technology Whakaahuatanga: IC CLK BUFFER 2:6 7.5GHZ 32MLF I roto i te taonga: 14418 pcs</p> <p><b>RFQ</b></p>	<p><b>SY58033UMI</b> Kaihanga: Micrel / Microchip Technology Whakaahuatanga: IC CLK BUFFER 1:8 5.5GHZ 32MLF I roto i te taonga: 10087 pcs</p> <p><b>RFQ</b></p>
<p><b>SY58034UMI-TR</b> Kaihanga: Micrel / Microchip Technology Whakaahuatanga: IC CLK BUFFER 2:6 7.5GHZ 32MLF I roto i te taonga: 12963 pcs</p> <p><b>RFQ</b></p>	<p><b>SY58034UMI</b> Kaihanga: Micrel / Microchip Technology Whakaahuatanga: IC CLK BUFFER 2:6 7.5GHZ 32MLF I roto i te taonga: 8966 pcs</p> <p><b>RFQ</b></p>
<p><b>SY58033UMG</b> Kaihanga: Micrel / Microchip Technology Whakaahuatanga: IC CLK BUFFER 1:8 5.5GHZ 32MLF I roto i te taonga: 9135 pcs</p> <p><b>RFQ</b></p>	<p><b>SY58035UMG</b> Kaihanga: Micrel / Microchip Technology Whakaahuatanga: IC CLK BUFFER 2:6 5.5GHZ 32MLF I roto i te taonga: 8185 pcs</p> <p><b>RFQ</b></p>