

BOURNS®	Bourns, Inc.
----------------	---------------------



PEC09-2215F-T0012

Tau Wae:	PEC09-2215F-T0012
Kaihanga / Waitohu:	Bourns, Inc.
Whakaahuatanga hua	ROTARY ENCODER MECHANICAL 12PPR
Ngā Rauemi:	PEC09-2215F-T0012.pdf
RoHS Tūnga	Whakahaerehia te kore utu / RoHS
Waehere Stock	57222 pcs stock
Tuhinga mai i	Hong Kong
Te Ara Tuhi	DHL/Fedex/TNT/UPS/EMS

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o PEC09-2215F-T0012

TAU WAE	PEC09-2215F-T0012
KAIHANGA	Bourns, Inc.
WHAKAAHUATANGA	ROTARY ENCODER MECHANICAL 12PPR
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
HE RAHINGA KEI TE WĀTEA	57222 pcs
PEPA RARAUNGA	PEC09-2215F-T0012.pdf
TUHINGA O MUA	-
KĀHUA WHAKAMUTUNGA	PC Pin
RAUPAPA	PEC09
KO TE ROTATIONAL LIFE (CYCLES MIN)	30K
PULSES IA REVOLUTION	12
MOMO PUTANGA	Quadrature (Incremental)
WHAKATAKOTORANGA	Right Angle
MOMO TAE	Panel, PCB Through Hole
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
MOMO KUPUTUHI	Mechanical
TUHINGA	Yes
HANGAIA KI TE WHAKAWHITI	Yes
MOMO KAIHOKO	6mm Dia Flatted End

Ngā tūtohu e hāngai ana

Bourns, Inc. PEC09-2215F-T0012	PEC09-2215F-T0012 Kaiwhiwhi	PEC09-2215F-T0012 Kaiwhakarato
PEC09-2215F-T0012 Utu	PEC09-2215F-T0012 Pikitia	PEC09-2215F-T0012 Whakaahua
PEC09-2215F-T0012 PDF Datasheet	PEC09-2215F-T0012 Download Datasheet	Tuhinga PEC09-2215F-T0012
PEC09-2215F-T0012 Stock	Hokona PEC09-2215F-T0012	Hokona Bourns, Inc. PEC09-2215F-T0012
Bourns, Inc. PEC09-2215F-T0012	Bourns, Inc. Kaiwhakarato	Bourns, Inc. Kaiwhiwhi
Bourns, Inc. PEC09-2215F-T0012	Bourns Inc. PEC09-2215F-T0012	J.W. Miller / Bourns PEC09-2215F-T0012

Ngā Hua e hāngai ana

<p>PEC09-2220F-S0012 Kaihanga: Bourns, Inc. Whakaahuatanga: ROTARY ENCODER MECHANICAL 12PPR I roto i te taonga: 25071 pcs</p> <p>RFQ</p>	<p>PEC09-2125K-N0012 Kaihanga: Bourns, Inc. Whakaahuatanga: ROTARY ENCODER MECHANICAL 12PPR I roto i te taonga: 75285 pcs</p> <p>RFQ</p>
<p>PEC09-2115K-S0012 Kaihanga: Bourns, Inc. Whakaahuatanga: ROTARY ENCODER MECHANICAL 12PPR I roto i te taonga: 49849 pcs</p> <p>RFQ</p>	<p>PEC09-2120F-S0012 Kaihanga: Bourns, Inc. Whakaahuatanga: ROTARY ENCODER MECHANICAL 12PPR I roto i te taonga: 32171 pcs</p> <p>RFQ</p>
<p>PEC09-2120K-T0012 Kaihanga: Bourns, Inc. Whakaahuatanga: ROTARY ENCODER MECHANICAL 12PPR I roto i te taonga: 50849 pcs</p> <p>RFQ</p>	<p>PEC09-2225K-N0012 Kaihanga: Bourns, Inc. Whakaahuatanga: ROTARY ENCODER MECHANICAL 12PPR I roto i te taonga: 84800 pcs</p> <p>RFQ</p>
<p>PEC09-2220K-S0012 Kaihanga: Bourns, Inc. Whakaahuatanga: ROTARY ENCODER MECHANICAL 12PPR I roto i te taonga: 47033 pcs</p> <p>RFQ</p>	<p>PEC09-2120K-S0012 Kaihanga: Bourns, Inc. Whakaahuatanga: ROTARY ENCODER I roto i te taonga: 50570 pcs</p> <p>RFQ</p>
<p>PEC09-2315F-N0015 Kaihanga: Bourns, Inc. Whakaahuatanga: ROTARY ENCODER MECHANICAL 12PPR I roto i te taonga: 79697 pcs</p> <p>RFQ</p>	<p>PEC09-2215K-N0012 Kaihanga: Bourns, Inc. Whakaahuatanga: ROTARY ENCODER MECHANICAL 12PPR I roto i te taonga: 81144 pcs</p> <p>RFQ</p>
<p>PEC09-2215F-N0012 Kaihanga: Bourns, Inc. Whakaahuatanga: ROTARY ENCODER MECHANICAL 12PPR I roto i te taonga: 60350 pcs</p> <p>RFQ</p>	<p>PEC09-2215K-T0012 Kaihanga: Bourns, Inc. Whakaahuatanga: ROTARY ENCODER MECHANICAL 12PPR I roto i te taonga: 56373 pcs</p> <p>RFQ</p>