

N/A

### DGS35-LK202048

Tau Wae:	DGS35-LK202048
Kaihanga / Waitohu:	N/A
Whakaahuatanga hua	ROTARY ENCODR INCREMENT 2048PPR
Ngā Rauemi:	
Waehere Stock	174 pcs stock
Tuhinga mai i	Hong Kong
Te Ara Tuhi	DHL/Fedex/TNT/UPS/EMS

**TONO MO TE WHAKAHUA**

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

#### Ngā whakaaturanga o DGS35-LK202048

TAU WAE	DGS35-LK202048
KAIHANGA	N/A
WHAKAAHUATANGA	ROTARY ENCODR INCREMENT 2048PPR
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	
HE RAHINGA KEI TE WĀTEA	174 pcs
PEPA RARAUNGA	
TUHINGA O MUA	5V
KĀHUA WHAKAMUTUNGA	Cable
RAUPAPA	-
KO TE ROTATIONAL LIFE (CYCLES MIN)	-
PULSES IA REVOLUTION	2048
MOMO PUTANGA	-
ĒTAHI INGOA	1085294
WHAKATAKOTORANGA	User Selectable
MOMO TAE	Chassis Mount
MOMO KUPUTUHI	Incremental
TUHINGA	No
HANGAIA KI TE WHAKAWHITI	No
MOMO KAIHOKO	Hole for Shaft

#### Ngā tūtohu e hāngai ana

DGS35-LK202048	DGS35-LK202048 Kaiwhiwhi	DGS35-LK202048 Kaiwhakarato
DGS35-LK202048 Utu	DGS35-LK202048 Pikitia	DGS35-LK202048 Whakaahua
DGS35-LK202048 PDF Datasheet	DGS35-LK202048 Download Datasheet	Tuhinga DGS35-LK202048
DGS35-LK202048 Stock	Hokona DGS35-LK202048	Hokona DGS35-LK202048
DGS35-LK202048	Kaiwhakarato	Kaiwhiwhi

#### Ngā Hua e hāngai ana

	<p><b>DGS35-YH208192</b></p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 8192PPR I roto i te taonga: 194 pcs</p> <p><b>RFQ</b></p>		<p><b>DGS35-LLK02048</b></p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 2048PPR I roto i te taonga: 181 pcs</p> <p><b>RFQ</b></p>
	<p><b>DGS35-YH401024</b></p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 1024PPR I roto i te taonga: 249 pcs</p> <p><b>RFQ</b></p>		<p><b>DGS35-LKK01024</b></p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 1024PPR I roto i te taonga: 210 pcs</p> <p><b>RFQ</b></p>
	<p><b>DGS35-LHK02500</b></p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 2500PPR I roto i te taonga: 194 pcs</p> <p><b>RFQ</b></p>		<p><b>DGS35-LLK03600</b></p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 3600PPR I roto i te taonga: 209 pcs</p> <p><b>RFQ</b></p>
	<p><b>DGS35-LH402500</b></p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 2500PPR I roto i te taonga: 201 pcs</p> <p><b>RFQ</b></p>		<p><b>DGS35-LJ402048</b></p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 2048PPR I roto i te taonga: 198 pcs</p> <p><b>RFQ</b></p>
	<p><b>DGS35-LH401024</b></p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 1024PPR I roto i te taonga: 232 pcs</p> <p><b>RFQ</b></p>		<p><b>DGS35-LHK02048</b></p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 2048PPR I roto i te taonga: 196 pcs</p> <p><b>RFQ</b></p>
	<p><b>DGS35-LKK02500</b></p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 2500PPR I roto i te taonga: 211 pcs</p> <p><b>RFQ</b></p>		<p><b>DGS35-LH404096</b></p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 4096PPR I roto i te taonga: 210 pcs</p> <p><b>RFQ</b></p>

