

N/A

### DGS35-4K401024

Tau Wae:	DGS35-4K401024
Kaihanga / Waitohu:	N/A
Whakaahuatanga hua	ROTARY ENCODR INCREMENT 1024PPR
Ngā Rauemi:	
Waehere Stock	203 pcs stock
Tuhinga mai i	Hong Kong
Te Ara Tuhi	DHL/Fedex/TNT/UPS/EMS

**TONO MO TE WHAKAHUA**

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

#### Ngā whakaaturanga o DGS35-4K401024

TAU WAE	DGS35-4K401024
KAIHANGA	N/A
WHAKAAHUATANGA	ROTARY ENCODR INCREMENT 1024PPR
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	
HE RAHINGA KEI TE WĀTEA	203 pcs
PEPA RARAUNGA	
TUHINGA O MUA	8 V ~ 24 V
KĀHUA WHAKAMUTUNGA	Connector
RAUPAPA	-
KO TE ROTATIONAL LIFE (CYCLES MIN)	-
PULSES IA REVOLUTION	1024
MOMO PUTANGA	-
ĒTAHI INGOA	1057985
WHAKATAKOTORANGA	User Selectable
MOMO TAE	Chassis Mount
MOMO KUPUTUHI	Incremental
TUHINGA	No
HANGAIA KI TE WHAKAWHITI	No
MOMO KAIHOKO	Hole for Shaft

#### Ngā tūtohu e hāngai ana

DGS35-4K401024	DGS35-4K401024 Kaiwhiwhi	DGS35-4K401024 Kaiwhakarato
DGS35-4K401024 Utu	DGS35-4K401024 Pikitia	DGS35-4K401024 Whakaahua
DGS35-4K401024 PDF Datasheet	DGS35-4K401024 Download Datasheet	Tuhinga DGS35-4K401024
DGS35-4K401024 Stock	Hokona DGS35-4K401024	Hokona DGS35-4K401024
DGS35-4K401024	Kaiwhakarato	Kaiwhiwhi

#### Ngā Hua e hāngai ana

	<p><b>DGS35-4KL16384</b></p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 16384PPR I roto i te taonga: 171 pcs</p> <p><b>RFQ</b></p>		<p><b>DGS35-4KL01024</b></p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 1024PPR I roto i te taonga: 186 pcs</p> <p><b>RFQ</b></p>
	<p><b>DGS35-4H402500</b></p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 2500PPR I roto i te taonga: 229 pcs</p> <p><b>RFQ</b></p>		<p><b>DGS35-4H402048</b></p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 2048PPR I roto i te taonga: 228 pcs</p> <p><b>RFQ</b></p>
	<p><b>DGS35-4H404096</b></p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 4096PPR I roto i te taonga: 189 pcs</p> <p><b>RFQ</b></p>		<p><b>DGS35-4J416384</b></p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 16384PPR I roto i te taonga: 156 pcs</p> <p><b>RFQ</b></p>
	<p><b>DGS35-4KM10000</b></p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 10000PPR I roto i te taonga: 154 pcs</p> <p><b>RFQ</b></p>		<p><b>DGS35-4HM01024</b></p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 1024PPR I roto i te taonga: 225 pcs</p> <p><b>RFQ</b></p>
	<p><b>DGS35-4KK04096</b></p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 4096PPR I roto i te taonga: 190 pcs</p> <p><b>RFQ</b></p>		<p><b>DGS35-4K416384</b></p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 16384PPR I roto i te taonga: 138 pcs</p> <p><b>RFQ</b></p>
	<p><b>DGS35-4KK01024</b></p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 1024PPR I roto i te taonga: 229 pcs</p> <p><b>RFQ</b></p>		<p><b>DGS35-4HK16384</b></p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 16384PPR I roto i te taonga: 189 pcs</p> <p><b>RFQ</b></p>