



Leader Tech Inc.

## 58-CBSA-1.25X3.75X0.5

Tau Wae:	58-CBSA-1.25X3.75X0.5
Kaihanga / Waitohu:	Leader Tech Inc.
Whakaahuatanga hua	58 SERIES CBS SHIELD ASSEMBLY -
Ngā Rauemi:	58-CBSA-1.25X3.75X0.5.pdf
RoHS Tūnga	Whakahaerehia te kore utu / RoHS
Waehe Stock	4790 pcs stock
Tuhinga mai i	Hong Kong
Te Ara Tuhi	DHL/Fedex/TNT/UPS/EMS

**TONO MO TE WHAKAHUA**

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

### Ngā whakaaturanga o 58-CBSA-1.25X3.75X0.5

TAU WAE	58-CBSA-1.25X3.75X0.5
KAIHANGA	Leader Tech Inc.
WHAKAAHUATANGA	58 SERIES CBS SHIELD ASSEMBLY -
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
HE RAHINGA KEI TE WĀTEA	4790 pcs
PEPA RARAUNGA	58-CBSA-1.25X3.75X0.5.pdf
WHĀNUI - WHĀNUI	1.250" (31.75mm)
TUHINGA O MUA	Vent Holes in Pattern
MOMO	Shield, 2-Piece
RAUPAPA	50-CBS
PACKAGING	Bulk
ĒTAHI INGOA	58-CBSA-1.25X3.75X0.4 58-CBSA-1.25X3.75X0.4-ND
MOMO TAE	Through Hole
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
TE ROA - WHĀNUI	3.750" (95.25mm)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
TEITEI - WHĀNUI	0.500" (12.70mm)
WHAKAAHUATANGA TAIPITOPITO	RF Shield Shield, 2-Piece 1.250" (31.75mm) X 3.750" (95.25mm) Vent Holes in Pattern Through Hole

### Ngā tūtohu e hāngai ana

Leader Tech Inc. 58-CBSA-1.25X3.75X0.5	58-CBSA-1.25X3.75X0.5 Kaihiwhi	58-CBSA-1.25X3.75X0.5 Kaiwhakarato
58-CBSA-1.25X3.75X0.5 Utu	58-CBSA-1.25X3.75X0.5 Pikitia	58-CBSA-1.25X3.75X0.5 Whakaahua
58-CBSA-1.25X3.75X0.5 PDF Datasheet	58-CBSA-1.25X3.75X0.5 Download Datasheet	Tuhinga 58-CBSA-1.25X3.75X0.5
58-CBSA-1.25X3.75X0.5 Stock	Hokona 58-CBSA-1.25X3.75X0.5	Hokona Leader Tech Inc. 58-CBSA-1.25X3.75X0.5
Leader Tech Inc. 58-CBSA-1.25X3.75X0.5	Leader Tech Inc. Kaiwhakarato	Leader Tech Inc. Kaihiwhi
Leader Tech Inc. 58-CBSA-1.25X3.75X0.5		

### Ngā Hua e hāngai ana

<p><b>58-CBSA-1.25X3.25X0.5</b> Kaihanga: Leader Tech Inc. Whakaahuatanga: 58 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 4236 pcs</p> <p><b>RFQ</b></p>	<p><b>58-CBSA-1.25X3.5X0.5</b> Kaihanga: Leader Tech Inc. Whakaahuatanga: 58 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 3941 pcs</p> <p><b>RFQ</b></p>
<p><b>58-CBSA-1.25X4.5X0.5</b> Kaihanga: Leader Tech Inc. Whakaahuatanga: 58 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 4722 pcs</p> <p><b>RFQ</b></p>	<p><b>58-CBSA-1.25X2.5X0.5</b> Kaihanga: Leader Tech Inc. Whakaahuatanga: 58 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 4865 pcs</p> <p><b>RFQ</b></p>
<p><b>58-CBSA-1.25X4.0X0.5</b> Kaihanga: Leader Tech Inc. Whakaahuatanga: 58 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 4701 pcs</p> <p><b>RFQ</b></p>	<p><b>58-CBSA-1.25X2.75X0.5</b> Kaihanga: Leader Tech Inc. Whakaahuatanga: 58 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 4653 pcs</p> <p><b>RFQ</b></p>
<p><b>58-CBSA-1.25X4.25X0.5</b> Kaihanga: Leader Tech Inc. Whakaahuatanga: 58 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 3737 pcs</p> <p><b>RFQ</b></p>	<p><b>58-CBSA-1.25X5.25X0.5</b> Kaihanga: Leader Tech Inc. Whakaahuatanga: 58 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 3697 pcs</p> <p><b>RFQ</b></p>
<p><b>58-CBSA-1.25X5.0X0.5</b> Kaihanga: Leader Tech Inc. Whakaahuatanga: 58 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 3961 pcs</p> <p><b>RFQ</b></p>	<p><b>58-CBSA-1.25X4.75X0.5</b> Kaihanga: Leader Tech Inc. Whakaahuatanga: 58 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 3765 pcs</p> <p><b>RFQ</b></p>
<p><b>58-CBSA-1.25X2.25X0.5</b> Kaihanga: Leader Tech Inc. Whakaahuatanga: 58 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 5031 pcs</p> <p><b>RFQ</b></p>	<p><b>58-CBSA-1.25X3.0X0.5</b> Kaihanga: Leader Tech Inc. Whakaahuatanga: 58 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 5304 pcs</p> <p><b>RFQ</b></p>