



AVX Corporation

### CP0805B1880AWTR

Tau Wae:	CP0805B1880AWTR
Kaihanga / Waitohu:	AVX Corporation
Whakaahuatanga hua	RF DIR COUPLER 1.85-1.91GHZ 0805
Ngā Rauemi:	CP0805B1880AWTR.pdf
RoHS Tūnga	Kei roto nga rangatira / RoHS kaore i te ture
Waehere Stock	252234 pcs stock
Tuhinga mai i	Hong Kong
Te Ara Tuhi	DHL/Fedex/TNT/UPS/EMS

**TONO MO TE WHAKAHUA**

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

#### Ngā whakaaturanga o CP0805B1880AWTR

TAU WAE	CP0805B1880AWTR
KAIHANGA	AVX Corporation
WHAKAAHUATANGA	RF DIR COUPLER 1.85-1.91GHZ 0805
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Kei roto nga rangatira / RoHS kaore i te ture
HE RAHINGA KEI TE WĀTEA	252234 pcs
PEPA RARAUNGA	CP0805B1880AWTR.pdf
PŪRERE PŪRERE WHAKARATO	0805
RAUPAPA	-
HOKI HOKI	-26dB
MANA - MAX	3W
PACKAGING	Tape & Reel (TR)
PAA / CASE	0805 (2012 Metric)
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Contains lead / RoHS non-compliant
WHAKAMOTU	-23dB
TE HAINATANGA WHAKATAUNGA	0.3dB
RAUTANGA	1.85GHz ~ 1.91GHz
WHAKAAHUATANGA TAIPITOPITO	RF Directional Coupler PCS 1.85GHz ~ 1.91GHz 15 ± 1dB 3W 0805 (2012 Metric)
HONONGA TAE	15 ± 1dB
HE MOMO HOAHOA	Standard
NGA TONO	PCS

#### Ngā tūtohu e hāngai ana

AVX Corporation CP0805B1880AWTR	CP0805B1880AWTR Kaihiwhi	CP0805B1880AWTR Kaiwhakarato
CP0805B1880AWTR Utu	CP0805B1880AWTR Pikitia	CP0805B1880AWTR Whakaahua
CP0805B1880AWTR PDF Datasheet	CP0805B1880AWTR Download Datasheet	Tuhinga CP0805B1880AWTR
CP0805B1880AWTR Stock	Hokona CP0805B1880AWTR	Hokona AVX Corporation CP0805B1880AWTR
AVX Corporation CP0805B1880AWTR	AVX Corporation Kaiwhakarato	AVX Corporation Kaihiwhi
AVX Corporation CP0805B1880AWTR	AVX Corporation [MIL] CP0805B1880AWTR	

#### Ngā Hua e hāngai ana

<p><b>CP0805B1890CWTR</b> Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.88-1.9GHZ 0805 I roto i te taonga: 236269 pcs</p> <p><b>RFQ</b></p>	<p><b>CP0805B1765AWTR</b> Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.765GHZ 0805 I roto i te taonga: 260989 pcs</p> <p><b>RFQ</b></p>
<p><b>CP0805B1842CWTR</b> Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.805-1.88GHZ 0805 I roto i te taonga: 244149 pcs</p> <p><b>RFQ</b></p>	<p><b>CP0805B1842BWTR</b> Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.805-1.88GHZ 0805 I roto i te taonga: 303740 pcs</p> <p><b>RFQ</b></p>
<p><b>CP0805B1747BWTR</b> Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.71-1.785GHZ 0805 I roto i te taonga: 310234 pcs</p> <p><b>RFQ</b></p>	<p><b>CP0805B1890BWTR</b> Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.88-1.9GHZ 0805 I roto i te taonga: 286791 pcs</p> <p><b>RFQ</b></p>
<p><b>CP0805B1842AWTR</b> Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.805-1.88GHZ 0805 I roto i te taonga: 242457 pcs</p> <p><b>RFQ</b></p>	<p><b>CP0805B1747CWTR</b> Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.71-1.785GHZ 0805 I roto i te taonga: 268194 pcs</p> <p><b>RFQ</b></p>
<p><b>CP0805B1907AWTR</b> Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.895-1.92GHZ 0805 I roto i te taonga: 275429 pcs</p> <p><b>RFQ</b></p>	<p><b>CP0805B1880BWTR</b> Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.85-1.91GHZ 0805 I roto i te taonga: 306200 pcs</p> <p><b>RFQ</b></p>
<p><b>CP0805B1880CWTR</b> Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.85-1.91GHZ 0805 I roto i te taonga: 254080 pcs</p> <p><b>RFQ</b></p>	<p><b>CP0805B1890AWTR</b> Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.88-1.9GHZ 0805 I roto i te taonga: 307146 pcs</p> <p><b>RFQ</b></p>