



Micrel / Microchip Technology

SY58034UMI

Tau Wae:

SY58034UMI

Kaihanga / Waitohu:

Micrel / Microchip Technology

Whakaahuatanga hua

IC CLK BUFFER 2:6 7.5GHZ 32MLF

Ngā Rauemi:

SY58034UMI.pdf

RoHS Tūnga

Kei roto nga rangatira / RoHS kaore i te ture

Waeheere Stock

8966 pcs stock

Tuhinga mai i

Hong Kong

Te Ara Tuhi

DHL/Fedex/TNT/UPS/EMS

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o SY58034UMI

| | |
|---|---|
| TAU WAE | SY58034UMI |
| KAIHANGA | Micrel / Microchip Technology |
| WHAKAAHUATANGA | IC CLK BUFFER 2:6 7.5GHZ 32MLF |
| WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA | Kei roto nga rangatira / RoHS kaore i te ture |
| HE RAHINGA KEI TE WĀTEA | 8966 pcs |
| PEPA RARAUNGA | SY58034UMI.pdf |
| TUHINGA O MUA | 2.375 V ~ 3.6 V |
| MOMO | Fanout Buffer (Distribution), Multiplexer |
| PŪRERE PŪRERE WHAKARATO | 32-MLF® (5x5) |
| RAUPAPA | Precision Edge® |
| RATONGA - WHAKAURU: WHAKAPUTA | 2:6 |
| PACKAGING | Tube |
| PAA / CASE | 32-VFQFN Exposed Pad, 32-MLF® |
| WHAKAPUTA | CML |
| TAE MAHI | -40°C ~ 85°C |
| TUHINGA O MUA | 1 |
| MOMO TAE | Surface Mount |
| TAUMATA WHAKAARO MOE (MSL) | 1 (Unlimited) |
| WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA | Contains lead / RoHS non-compliant |
| WHAKAURU | CML, LVDS, PECL |
| TAUTANGA - MAX | 7.5GHz |
| MOTUHAKE - WHAKAURU: WHAKAPUTA | Yes/Yes |
| WHAKAAHUATANGA TAIPITOPITO | Clock Fanout Buffer (Distribution), Multiplexer IC 2:6 7.5GHz 32-VFQFN Exposed Pad, 32-MLF® |
| TAU WAE TUAKIRI | SY58034 |

Ngā tūtohu e hāngai ana

| | | |
|--|--|---|
| Micrel / Microchip Technology SY58034UMI | SY58034UMI Kaiwhiwhi | SY58034UMI Kaiwhakarato |
| SY58034UMI Utu | SY58034UMI Pikitia | SY58034UMI Whakaahua |
| SY58034UMI PDF Datasheet | SY58034UMI Download Datasheet | Tuhinga SY58034UMI |
| SY58034UMI Stock | Hokona SY58034UMI | Hokona Micrel / Microchip Technology SY58034UMI |
| Micrel / Microchip Technology SY58034UMI | Micrel / Microchip Technology Kaiwhakarato | Micrel / Microchip Technology Kaiwhiwhi |
| Micrel / Microchip Technology SY58034UMI | Microchip Technology SY58034UMI | Roving Networks / Microchip Technology SY58034UMI |

Ngā Hua e hāngai ana

| | |
|--|--|
| <p>SY58033UMI-TR Kaihanga: Micrel / Microchip Technology Whakaahuatanga: IC CLK BUFFER 1:8 5.5GHZ 32MLF I roto i te taonga: 13166 pcs</p> <p>RFQ</p> | <p>SY58033UMG Kaihanga: Micrel / Microchip Technology Whakaahuatanga: IC CLK BUFFER 1:8 5.5GHZ 32MLF I roto i te taonga: 9135 pcs</p> <p>RFQ</p> |
| <p>SY58035UMI Kaihanga: Micrel / Microchip Technology Whakaahuatanga: IC CLK BUFFER 2:6 5.5GHZ 32MLF I roto i te taonga: 9774 pcs</p> <p>RFQ</p> | <p>SY58035UMG Kaihanga: Micrel / Microchip Technology Whakaahuatanga: IC CLK BUFFER 2:6 5.5GHZ 32MLF I roto i te taonga: 8185 pcs</p> <p>RFQ</p> |
| <p>SY58035UMG-TR Kaihanga: Micrel / Microchip Technology Whakaahuatanga: IC CLK BUFFER 2:6 5.5GHZ 32MLF I roto i te taonga: 14039 pcs</p> <p>RFQ</p> | <p>SY58036UMG Kaihanga: Micrel / Microchip Technology Whakaahuatanga: IC CLK BUFFER 2:6 7GHZ 32MLF I roto i te taonga: 9223 pcs</p> <p>RFQ</p> |
| <p>SY58034UMI-TR Kaihanga: Micrel / Microchip Technology Whakaahuatanga: IC CLK BUFFER 2:6 7.5GHZ 32MLF I roto i te taonga: 12963 pcs</p> <p>RFQ</p> | <p>SY58034UMG Kaihanga: Micrel / Microchip Technology Whakaahuatanga: IC CLK BUFFER 2:6 7.5GHZ 32MLF I roto i te taonga: 9072 pcs</p> <p>RFQ</p> |
| <p>SY58033UMG-TR Kaihanga: Micrel / Microchip Technology Whakaahuatanga: IC CLK BUFFER 1:8 5.5GHZ 32MLF I roto i te taonga: 11094 pcs</p> <p>RFQ</p> | <p>SY58035UMI-TR Kaihanga: Micrel / Microchip Technology Whakaahuatanga: IC CLK BUFFER 2:6 5.5GHZ 32MLF I roto i te taonga: 11293 pcs</p> <p>RFQ</p> |
| <p>SY58034UMG-TR Kaihanga: Micrel / Microchip Technology Whakaahuatanga: IC CLK BUFFER 2:6 7.5GHZ 32MLF I roto i te taonga: 14418 pcs</p> <p>RFQ</p> | <p>SY58033UMI Kaihanga: Micrel / Microchip Technology Whakaahuatanga: IC CLK BUFFER 1:8 5.5GHZ 32MLF I roto i te taonga: 10087 pcs</p> <p>RFQ</p> |

