



Hirose

HDH-01703CH(40)

Tau Wae:

HDH-01703CH(40)

Kaihanga / Waitohu:

Hirose

Whakaahuatanga hua

RF DIR COUPLER 1.7GHZ

1.HDH-01703CH(40).pdf

2.HDH-01703CH(40).pdf

Ngā Rauemi:

Whakahaerehia te kore utu / RoHS

RoHS Tūnga

273 pcs stock

Waehe Stock

Hong Kong

Tuhinga mai i

DHL/Fedex/TNT/UPS/EMS

Te Ara Tuhi

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o HDH-01703CH(40)

TAU WAE	HDH-01703CH(40)
KAIHANGA	Hirose
WHAKAAHUATANGA	RF DIR COUPLER 1.7GHZ
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
HE RAHINGA KEI TE WĀTEA	273 pcs
PEPA RARAUNGA	1.HDH-01703CH(40).pdf 2.HDH-01703CH(40).pdf
PŪRERE PŪRERE WHAKARATO	-
RAUPAPA	HDH
HOKI HOKI	20.8dB
MANA - MAX	50W
PACKAGING	Bulk
PAA / CASE	-
ĒTAHI INGOA	*HDH-01703CH(40)-ND
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
WHAKAMOTU	23dB
TE HAINATANGA WHAKATAUNGA	-
RAUTANGA	1.7GHz
WHAKAAHUATANGA TAIPITOPITO	RF Directional Coupler General Purpose 1.7GHz 3dB 50W
HONONGA TAE	3dB
HE MOMO HOAHOA	Standard
NGA TONO	General Purpose

Ngā tūtohu e hāngai ana

Hirose HDH-01703CH(40)	HDH-01703CH(40) Kaiwhiwhi	HDH-01703CH(40) Kaiwhakarato
HDH-01703CH(40) Utu	HDH-01703CH(40) Pikitia	HDH-01703CH(40) Whakaahua
HDH-01703CH(40) PDF Datasheet	HDH-01703CH(40) Download Datasheet	Tuhinga HDH-01703CH(40)
HDH-01703CH(40) Stock	Hokona HDH-01703CH(40)	Hokona Hirose HDH-01703CH(40)
Hirose HDH-01703CH(40)	Hirose Kaiwhakarato	Hirose Kaiwhiwhi
Hirose HDH-01703CH(40)	Hirose Electric Co Ltd HDH-01703CH(40)	

Ngā Hua e hāngai ana

<p>HDH-01706CID(40) Kaihanga: Hirose Whakaahuatanga: RF DIR COUPLER 1.7GHZ I roto i te taonga: 238 pcs</p> <p>RFQ</p>	<p>HDH-01537CI(40) Kaihanga: Hirose Whakaahuatanga: RF DIR COUPLER 1.5GHZ I roto i te taonga: 6018 pcs</p> <p>RFQ</p>
<p>HDH-01510GID(40) Kaihanga: Hirose Whakaahuatanga: RF DIR COUPLER 1.5GHZ I roto i te taonga: 264 pcs</p> <p>RFQ</p>	<p>HDH-01710CID(40) Kaihanga: Hirose Whakaahuatanga: RF DIR COUPLER 1.7GHZ I roto i te taonga: 242 pcs</p> <p>RFQ</p>
<p>HDH-01720CID(40) Kaihanga: Hirose Whakaahuatanga: RF DIR COUPLER 1.7GHZ I roto i te taonga: 225 pcs</p> <p>RFQ</p>	<p>HDH-01530CI(40) Kaihanga: Hirose Whakaahuatanga: RF DIR COUPLER 1.5GHZ I roto i te taonga: 6087 pcs</p> <p>RFQ</p>
<p>HDH-01510GID(31) Kaihanga: Hirose Whakaahuatanga: RF DIR COUPLER 1GHZ-2GHZ MODULE I roto i te taonga: 5309 pcs</p> <p>RFQ</p>	<p>HDH-01520GID(31) Kaihanga: Hirose Whakaahuatanga: RF DIR COUPLER 1GHZ-2GHZ MODULE I roto i te taonga: 4023 pcs</p> <p>RFQ</p>
<p>HDH-01703CHD(40) Kaihanga: Hirose Whakaahuatanga: RF DIR COUPLER 1.7GHZ I roto i te taonga: 230 pcs</p> <p>RFQ</p>	<p>HDH-01703CHD(31) Kaihanga: Hirose Whakaahuatanga: RF DIR COUPLER 1.5GHZ-1.9GHZ MOD I roto i te taonga: 6289 pcs</p> <p>RFQ</p>
<p>HDH-01520GID(40) Kaihanga: Hirose Whakaahuatanga: RF DIR COUPLER 1.5GHZ I roto i te taonga: 262 pcs</p> <p>RFQ</p>	<p>HDH-01730CID(40) Kaihanga: Hirose Whakaahuatanga: RF DIR COUPLER 1.7GHZ I roto i te taonga: 263 pcs</p> <p>RFQ</p>