



MaxBotix Inc.

## MB7364-100

Tau Wae:

MB7364-100

Kaihanga / Waitohu:

MaxBotix Inc.

Whakaahuatanga hua

ULTRASONIC SENSOR HRXL-MAXSONAR

Ngā Rauemi:

MB7364-100.pdf

RoHS Tūnga

RoHS Compliant

Waehere Stock

633 pcs stock

Tuhinga mai i

Hong Kong

Te Ara Tuhi

DHL/Fedex/TNT/UPS/EMS

**TONO MO TE WHAKAHUA**

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

### Ngā whakaaturanga o MB7364-100

TAU WAE	MB7364-100
KAIHANGA	MaxBotix Inc.
WHAKAAHUATANGA	ULTRASONIC SENSOR HRXL-MAXSONAR
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	RoHS Compliant
HE RAHINGA KEI TE WĀTEA	633 pcs
PEPA RARAUNGA	MB7364-100.pdf
PUTANGA - KUA TOHUA	2.5 V ~ 5.5 V
RAUPAPA	HRXL-MaxSonar-WRS
ROHS TŪNGA	RoHS Compliant
PACKAGING	Bulk
ĒTAHI INGOA	1863-1062
TAE MAHI	-40°C ~ 65°C (TA)
RAUTANGA	42kHz
WHAKAAHUATANGA TAIPITOPITO	Ultrasonic Sensor 42kHz
TE PEE MAAMA	23°

### Ngā tūtohu e hāngai ana

MaxBotix Inc. MB7364-100	MB7364-100 Kaiwhiwhi	MB7364-100 Kaiwhakarato
MB7364-100 Utu	MB7364-100 Pikitia	MB7364-100 Whakaahua
MB7364-100 PDF Datasheet	MB7364-100 Download Datasheet	Tuhinga MB7364-100
MB7364-100 Stock	Hokona MB7364-100	Hokona MaxBotix Inc. MB7364-100
MaxBotix Inc. MB7364-100	MaxBotix Inc. Kaiwhakarato	MaxBotix Inc. Kaiwhiwhi
MaxBotix Inc. MB7364-100		

### Ngā Hua e hāngai ana

<p><b>MB7364-111</b> Kaihanga: MaxBotix Inc. Whakaahuatanga: ULTRASONIC SENSOR HRXL-MAXSONAR I roto i te taonga: 351 pcs</p> <p><b>RFQ</b></p>	<p><b>MB7364-110</b> Kaihanga: MaxBotix Inc. Whakaahuatanga: ULTRASONIC SENSOR HRXL-MAXSONAR I roto i te taonga: 514 pcs</p> <p><b>RFQ</b></p>
<p><b>MB7363-830</b> Kaihanga: MaxBotix Inc. Whakaahuatanga: ULTRASONIC SENSOR HRXL-MAXSONAR I roto i te taonga: 360 pcs</p> <p><b>RFQ</b></p>	<p><b>MB7364-120</b> Kaihanga: MaxBotix Inc. Whakaahuatanga: ULTRASONIC SENSOR HRXL-MAXSONAR I roto i te taonga: 554 pcs</p> <p><b>RFQ</b></p>
<p><b>MB7363-831</b> Kaihanga: MaxBotix Inc. Whakaahuatanga: ULTRASONIC SENSOR HRXL-MAXSONAR I roto i te taonga: 301 pcs</p> <p><b>RFQ</b></p>	<p><b>MB7364-130</b> Kaihanga: MaxBotix Inc. Whakaahuatanga: ULTRASONIC SENSOR HRXL-MAXSONAR I roto i te taonga: 410 pcs</p> <p><b>RFQ</b></p>
<p><b>MB7363-811</b> Kaihanga: MaxBotix Inc. Whakaahuatanga: ULTRASONIC SENSOR HRXL-MAXSONAR I roto i te taonga: 358 pcs</p> <p><b>RFQ</b></p>	<p><b>MB7363-820</b> Kaihanga: MaxBotix Inc. Whakaahuatanga: ULTRASONIC SENSOR HRXL-MAXSONAR I roto i te taonga: 486 pcs</p> <p><b>RFQ</b></p>
<p><b>MB7363-821</b> Kaihanga: MaxBotix Inc. Whakaahuatanga: ULTRASONIC SENSOR HRXL-MAXSONAR I roto i te taonga: 395 pcs</p> <p><b>RFQ</b></p>	<p><b>MB7364-121</b> Kaihanga: MaxBotix Inc. Whakaahuatanga: ULTRASONIC SENSOR HRXL-MAXSONAR I roto i te taonga: 325 pcs</p> <p><b>RFQ</b></p>
<p><b>MB7364-101</b> Kaihanga: MaxBotix Inc. Whakaahuatanga: ULTRASONIC SENSOR HRXL-MAXSONAR I roto i te taonga: 376 pcs</p> <p><b>RFQ</b></p>	<p><b>MB7363-810</b> Kaihanga: MaxBotix Inc. Whakaahuatanga: ULTRASONIC SENSOR HRXL-MAXSONAR I roto i te taonga: 456 pcs</p> <p><b>RFQ</b></p>

