



Leader Tech Inc.

50-CBSA-4.75X6.0X0.5

Tau Wae:	50-CBSA-4.75X6.0X0.5
Kaihanga / Waitohu:	Leader Tech Inc.
Whakaahuatanga hua	50 SERIES CBS SHIELD ASSEMBLY -
Ngā Rauemi:	50-CBSA-4.75X6.0X0.5.pdf
RoHS Tūnga	Whakahaerehia te kore utu / RoHS
Waehere Stock	3015 pcs stock
Tuhinga mai i	Hong Kong
Te Ara Tuhi	DHL/Fedex/TNT/UPS/EMS

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o 50-CBSA-4.75X6.0X0.5

TAU WAE	50-CBSA-4.75X6.0X0.5
KAIHANGA	Leader Tech Inc.
WHAKAAHUATANGA	50 SERIES CBS SHIELD ASSEMBLY -
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
HE RAHINGA KEI TE WĀTEA	3015 pcs
PEPA RARAUNGA	50-CBSA-4.75X6.0X0.5.pdf
WHĀNUI - WHĀNUI	4.750" (120.65mm)
TUHINGA O MUA	Vent Holes in Pattern
MOMO	Shield, 2-Piece
RAUPAPA	50-CBS
PACKAGING	Bulk
ĒTAHI INGOA	50-CBSA-4.75X6.0X0.4 50-CBSA-4.75X6.0X0.4-ND
MOMO TAE	Surface Mount
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
TE ROA - WHĀNUI	6.000" (152.40mm)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
TEITEI - WHĀNUI	0.500" (12.70mm)
WHAKAAHUATANGA TAIPITOPITO	RF Shield Shield, 2-Piece 4.750" (120.65mm) X 6.000" (152.40mm) Vent Holes in Pattern Surface Mount

Ngā tūtohu e hāngai ana

Leader Tech Inc. 50-CBSA-4.75X6.0X0.5	50-CBSA-4.75X6.0X0.5 Kaiwhiwhi	50-CBSA-4.75X6.0X0.5 Kaiwhakarato
50-CBSA-4.75X6.0X0.5 Utu	50-CBSA-4.75X6.0X0.5 Pikitia	50-CBSA-4.75X6.0X0.5 Whakaahua
50-CBSA-4.75X6.0X0.5 PDF Datasheet	50-CBSA-4.75X6.0X0.5 Download Datasheet	Tuhinga 50-CBSA-4.75X6.0X0.5
50-CBSA-4.75X6.0X0.5 Stock	Hokona 50-CBSA-4.75X6.0X0.5	Hokona Leader Tech Inc. 50-CBSA-4.75X6.0X0.5
Leader Tech Inc. 50-CBSA-4.75X6.0X0.5	Leader Tech Inc. Kaiwhakarato	Leader Tech Inc. Kaiwhiwhi
Leader Tech Inc. 50-CBSA-4.75X6.0X0.5		

Ngā Hua e hāngai ana

<p>50-CBSA-5.0X5.0X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 50 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 3399 pcs</p> <p>RFQ</p>	<p>50-CBSA-4.75X5.25X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 50 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 3345 pcs</p> <p>RFQ</p>
<p>50-CBSA-5.25X5.25X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 50 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 3290 pcs</p> <p>RFQ</p>	<p>50-CBSA-4.75X5.75X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 50 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 3371 pcs</p> <p>RFQ</p>
<p>50-CBSA-5.0X6.0X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 50 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 3290 pcs</p> <p>RFQ</p>	<p>50-CBSA-5.0X5.75X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 50 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 3615 pcs</p> <p>RFQ</p>
<p>50-CBSA-4.75X5.5X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 50 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 3743 pcs</p> <p>RFQ</p>	<p>50-CBSA-5.0X5.5X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 50 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 2967 pcs</p> <p>RFQ</p>
<p>50-CBSA-5.0X5.25X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 50 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 3644 pcs</p> <p>RFQ</p>	<p>50-CBSA-4.75X4.75X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 50 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 3668 pcs</p> <p>RFQ</p>
<p>50-CBSA-4.75X5.0X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 50 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 2856 pcs</p> <p>RFQ</p>	<p>50-CBSA-4.5X6.0X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 50 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 3830 pcs</p> <p>RFQ</p>