



42-CBSA-2.75X5.75X0.4

Tau Wae:	42-CBSA-2.75X5.75X0.4
Kaihanga / Waitohu:	Leader Tech Inc.
Whakaahuatanga hua	42 SERIES CBS SHIELD ASSEMBLY
Ngā Rauemi:	42-CBSA-2.75X5.75X0.4.pdf
RoHS Tūnga	Whakahaerehia te kore utu / RoHS
Waehere Stock	3898 pcs stock
Tuhinga mai i	Hong Kong
Te Ara Tuhi	DHL/Fedex/TNT/UPS/EMS

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o 42-CBSA-2.75X5.75X0.4

TAU WAE	42-CBSA-2.75X5.75X0.4
KAIHANGA	Leader Tech Inc.
WHAKAAHUATANGA	42 SERIES CBS SHIELD ASSEMBLY
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
HE RAHINGA KEI TE WĀTEA	3898 pcs
PEPA RARAUNGA	42-CBSA-2.75X5.75X0.4.pdf
WHĀNUI - WHĀNUI	2.750" (69.85mm)
TUHINGA O MUA	Vent Holes in Pattern
MOMO	Shield, 2-Piece
RAUPAPA	40-CBS
PACKAGING	Bulk
MOMO TAE	Through Hole
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
TE ROA - WHĀNUI	5.750" (146.05mm)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
TEITEI - WHĀNUI	0.400" (10.16mm)
WHAKAAHUATANGA TAIPITOPITO	RF Shield Shield, 2-Piece 2.750" (69.85mm) X 5.750" (146.05mm) Vent Holes in Pattern Through Hole

Ngā tūtohu e hāngai ana

Leader Tech Inc. 42-CBSA-2.75X5.75X0.4	42-CBSA-2.75X5.75X0.4 Kaiwhiwhi	42-CBSA-2.75X5.75X0.4 Kaiwhakarato
42-CBSA-2.75X5.75X0.4 Utu	42-CBSA-2.75X5.75X0.4 Pikitia	42-CBSA-2.75X5.75X0.4 Whakaahua
42-CBSA-2.75X5.75X0.4 PDF Datasheet	42-CBSA-2.75X5.75X0.4 Download Datasheet	Tuhinga 42-CBSA-2.75X5.75X0.4
42-CBSA-2.75X5.75X0.4 Stock	Hokona 42-CBSA-2.75X5.75X0.4	Hokona Leader Tech Inc. 42-CBSA-2.75X5.75X0.4
Leader Tech Inc. 42-CBSA-2.75X5.75X0.4	Leader Tech Inc. Kaiwhakarato	Leader Tech Inc. Kaiwhiwhi
Leader Tech Inc. 42-CBSA-2.75X5.75X0.4		

Ngā Hua e hāngai ana

<p>42-CBSA-3.0X3.5X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 42 SERIES CBS SHIELD ASSEMBLY I roto i te taonga: 4691 pcs</p> <p>RFQ</p>	<p>42-CBSA-3.0X4.0X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 42 SERIES CBS SHIELD ASSEMBLY I roto i te taonga: 4251 pcs</p> <p>RFQ</p>
<p>42-CBSA-2.75X5.5X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 42 SERIES CBS SHIELD ASSEMBLY I roto i te taonga: 3913 pcs</p> <p>RFQ</p>	<p>42-CBSA-3.0X3.75X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 42 SERIES CBS SHIELD ASSEMBLY I roto i te taonga: 3534 pcs</p> <p>RFQ</p>
<p>42-CBSA-3.0X3.25X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 42 SERIES CBS SHIELD ASSEMBLY I roto i te taonga: 4264 pcs</p> <p>RFQ</p>	<p>42-CBSA-2.75X5.0X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 42 SERIES CBS SHIELD ASSEMBLY I roto i te taonga: 3346 pcs</p> <p>RFQ</p>
<p>42-CBSA-2.75X5.25X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 42 SERIES CBS SHIELD ASSEMBLY I roto i te taonga: 3224 pcs</p> <p>RFQ</p>	<p>42-CBSA-2.75X6.0X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 42 SERIES CBS SHIELD ASSEMBLY I roto i te taonga: 3244 pcs</p> <p>RFQ</p>
<p>42-CBSA-2.75X4.75X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 42 SERIES CBS SHIELD ASSEMBLY I roto i te taonga: 3832 pcs</p> <p>RFQ</p>	<p>42-CBSA-2.75X4.25X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 42 SERIES CBS SHIELD ASSEMBLY I roto i te taonga: 4293 pcs</p> <p>RFQ</p>
<p>42-CBSA-3.0X3.0X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 42 SERIES CBS SHIELD ASSEMBLY I roto i te taonga: 4408 pcs</p> <p>RFQ</p>	<p>42-CBSA-2.75X4.5X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 42 SERIES CBS SHIELD ASSEMBLY I roto i te taonga: 3827 pcs</p> <p>RFQ</p>