



Yageo

DPX2012LL85R2455A

Tau Wae:	DPX2012LL85R2455A
Kaihanga / Waitohu:	Yageo
Whakaahuatanga hua	RF DIPLEXER 2.45/5.425GHZ 0805
Ngā Rauemi:	DPX2012LL85R2455A.pdf
RoHS Tūnga	Whakahaerehia te kore utu / RoHS
Waehere Stock	179376 pcs stock
Tuhinga mai i	Hong Kong
Te Ara Tuhi	DHL/Fedex/TNT/UPS/EMS

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o DPX2012LL85R2455A

TAU WAE	DPX2012LL85R2455A
KAIHANGA	Yageo
WHAKAAHUATANGA	RF DIPLEXER 2.45/5.425GHZ 0805
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
HE RAHINGA KEI TE WĀTEA	179376 pcs
PEPA RARAUNGA	DPX2012LL85R2455A.pdf
RAUPAPA	DPX
KO TE HOKI HOKI (ROA RAWA / HAINA NUI)	9.5dB / 9.5dB
PACKAGING	Cut Tape (CT)
PAA / CASE	0805 (2012 Metric), 8 PC Pad
ĒTAHI INGOA	311-1567-1
MOMO TAE	Surface Mount
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
TAE WHAKAMURI RAWA (MIN / MAX DB)	20.00dB / -
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
TAE WHAKATEITEI NUI (MIN / MAX DB)	20.00dB / -
NGĀ RŌPŪ TAEKE (RARO / TEITEI)	2.4GHz ~ 2.5GHz / 4.9GHz ~ 5.95GHz
WHAKAAHUATANGA TAIPITOPITO	RF Diplexor 2.4GHz ~ 2.5GHz / 4.9GHz ~ 5.95GHz 0805 (2012 Metric), 8 PC Pad

Ngā tūtohu e hāngai ana

Yageo DPX2012LL85R2455A	DPX2012LL85R2455A Kaiwhiwhi	DPX2012LL85R2455A Kaiwhakarato
DPX2012LL85R2455A Utu	DPX2012LL85R2455A Pikitia	DPX2012LL85R2455A Whakaahua
DPX2012LL85R2455A PDF Datasheet	DPX2012LL85R2455A Download Datasheet	Tuhinga DPX2012LL85R2455A
DPX2012LL85R2455A Stock	Hokona DPX2012LL85R2455A	Hokona Yageo DPX2012LL85R2455A
Yageo DPX2012LL85R2455A	Yageo Kaiwhakarato	Yageo Kaiwhiwhi
Yageo DPX2012LL85R2455A	YAGEO Corporation DPX2012LL85R2455A	

Ngā Hua e hāngai ana

<p>DPX201990DT-4151A2 Kaihanga: TDK Corporation Whakaahuatanga: RF DIPLEXER 872.5MZ/1.78GHZ 0805 I roto i te taonga: 286649 pcs</p> <p>RFQ</p>	<p>DPX201990DT-4014A2 Kaihanga: TDK Corporation Whakaahuatanga: RF DIPLEXER 859MHZ/1.92GHZ 0805 I roto i te taonga: 307283 pcs</p> <p>RFQ</p>
<p>DPX165950DT-8126A1 Kaihanga: TDK Corporation Whakaahuatanga: RF DIPLEXER 2.45/5.425GHZ 0603 I roto i te taonga: 280291 pcs</p> <p>RFQ</p>	<p>DPX201990DT-4011D1 Kaihanga: TDK Corporation Whakaahuatanga: RF DIPLEXER 892MHZ/1.85GHZ 0805 I roto i te taonga: 94672 pcs</p> <p>RFQ</p>
<p>DPX2012LL89R2455A Kaihanga: Yageo Whakaahuatanga: RF DIPLEXER 2.45/5.425GHZ 0805 I roto i te taonga: 523956 pcs</p> <p>RFQ</p>	<p>DPX2-20745-8 Kaihanga: Cannon Whakaahuatanga: RP DPX STRAIGHT JUNCTION SHEL I roto i te taonga: 714 pcs</p> <p>RFQ</p>
<p>DPX165950DT-8144A1 Kaihanga: TDK Corporation Whakaahuatanga: RF DIPLEXER 0603 6 PC PAD I roto i te taonga: 63461 pcs</p> <p>RFQ</p>	<p>DPX165950DT-8118A1 Kaihanga: TDK Corporation Whakaahuatanga: RF DIPLEXER 2.45/5.425GHZ 0603 I roto i te taonga: 714 pcs</p> <p>RFQ</p>
<p>DPX165950DT-8130A1 Kaihanga: TDK Corporation Whakaahuatanga: RF DIPLEXER 2.45/5.425GHZ 0603 I roto i te taonga: 325254 pcs</p> <p>RFQ</p>	<p>DPX201990DT-4051A2 Kaihanga: TDK Corporation Whakaahuatanga: RF DIPLEXER 872.5MZ/1.78GHZ 0805 I roto i te taonga: 309120 pcs</p> <p>RFQ</p>
<p>DPX165950DT-8148A1 Kaihanga: TDK Corporation Whakaahuatanga: RF DIPLEXER 2.45/5.425GHZ 0603 I roto i te taonga: 256554 pcs</p> <p>RFQ</p>	<p>DPX202170DT-4021A1 Kaihanga: TDK Corporation Whakaahuatanga: RF DIPLEXER 857.5MZ/2.045GHZ 0805 I roto i te taonga: 179006 pcs</p> <p>RFQ</p>