



TDK Corporation

HHM1603A1

Tau Wae:

HHM1603A1

Kaihanga / Waitohu:

TDK Corporation

Whakaahuatanga hua

BALUN 2.3GHZ-2.7GHZ 50/100 4SMD

Ngā Rauemi:

HHM1603A1.pdf

RoHS Tūnga

Whakahaerehia te kore utu / RoHS

Waeheere Stock

120843 pcs stock

Tuhinga mai i

Hong Kong

Te Ara Tuhi

DHL/Fedex/TNT/UPS/EMS

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o HHM1603A1

TAU WAE	HHM1603A1
KAIHANGA	TDK Corporation
WHAKAAHUATANGA	BALUN 2.3GHZ-2.7GHZ 50/100 4SMD
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
HE RAHINGA KEI TE WĀTEA	120843 pcs
PEPA RARAUNGA	HHM1603A1.pdf
RAUPAPA	-
HOKI HOKI (MIN)	10dB
RAWEHANGA PUTANGA	180° ±10°
PACKAGING	Cut Tape (CT)
PAA / CASE	4-SMD
ĒTAHI INGOA	445-173060-1
MOMO TAE	Surface Mount
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
KO TE WHAKAKORE I TE MAHINGA (MAX)	0.5dB
HAAPAPA - NGA HAUARO / WHAKATIKA	50 / 100 Ohm
MAHINGA RAWE	2.3GHz ~ 2.7GHz
WHAKAAHUATANGA TAIPITOPITO	RF Balun 2.3GHz ~ 2.7GHz 50 / 100 Ohm 4-SMD

Ngā tūtohu e hāngai ana

TDK Corporation HHM1603A1	HHM1603A1 Kaiwhiwhi	HHM1603A1 Kaiwhakarato
HHM1603A1 Utu	HHM1603A1 Pikitia	HHM1603A1 Whakaahua
HHM1603A1 PDF Datasheet	HHM1603A1 Download Datasheet	Tuhinga HHM1603A1
HHM1603A1 Stock	Hokona HHM1603A1	Hokona TDK Corporation HHM1603A1
TDK Corporation HHM1603A1	TDK Corporation Kaiwhakarato	TDK Corporation Kaiwhiwhi
TDK Corporation HHM1603A1		

Ngā Hua e hāngai ana

<p>HHM1591D1 Kaihanga: TDK Corporation Whakaahuatanga: BALUN 350MHZ-470MHZ 50/100 0805 I roto i te taonga: 466597 pcs</p> <p>RFQ</p>	<p>HHM1596A1 Kaihanga: TDK Corporation Whakaahuatanga: BALUN 3.1GHZ-4.9GHZ 50/100 0805 I roto i te taonga: 493437 pcs</p> <p>RFQ</p>
<p>HHM1589B1 Kaihanga: TDK Corporation Whakaahuatanga: BALUN 470MHZ-710MHZ 6SMD I roto i te taonga: 234016 pcs</p> <p>RFQ</p>	<p>HHM17139B1 Kaihanga: TDK Corporation Whakaahuatanga: BALUN 2.4GHZ-2.5GHZ 50/50 0603 I roto i te taonga: 255709 pcs</p> <p>RFQ</p>
<p>HHM1583B1 Kaihanga: TDK Corporation Whakaahuatanga: BALUN 3.1GHZ-4.9GHZ 50/100 0805 I roto i te taonga: 404898 pcs</p> <p>RFQ</p>	<p>HHM1595A1 Kaihanga: TDK Corporation Whakaahuatanga: BALUN 3GHZ-8GHZ 50/100 0805 I roto i te taonga: 163352 pcs</p> <p>RFQ</p>
<p>HHM1711D1 Kaihanga: TDK Corporation Whakaahuatanga: BALUN 2.4GHZ-2.5GHZ 50/100 0603 I roto i te taonga: 180690 pcs</p> <p>RFQ</p>	<p>HHM1710D1 Kaihanga: TDK Corporation Whakaahuatanga: BALUN 2.4GHZ-2.5GHZ 50/50 0603 I roto i te taonga: 460907 pcs</p> <p>RFQ</p>
<p>HHM17125D1 Kaihanga: TDK Corporation Whakaahuatanga: BALUN 2.4GHZ-2.5GHZ 50/50 0603 I roto i te taonga: 496156 pcs</p> <p>RFQ</p>	<p>HHM1589E1 Kaihanga: TDK Corporation Whakaahuatanga: BALUN 350MHZ-470MHZ 50/200 0805 I roto i te taonga: 435579 pcs</p> <p>RFQ</p>
<p>HHM1711Q1 Kaihanga: TDK Corporation Whakaahuatanga: BALUN 2.3GHZ-3.8GHZ 50/100 0603 I roto i te taonga: 836875 pcs</p> <p>RFQ</p>	<p>HHM1711E1 Kaihanga: TDK Corporation Whakaahuatanga: BALUN 2.3GHZ-2.7GHZ 50/100 0603 I roto i te taonga: 796296 pcs</p> <p>RFQ</p>