



TDK Corporation

## HHM17139B2

Tau Wae:

HHM17139B2

Kaihanga / Waitohu:

TDK Corporation

Whakaahuatanga hua

BALUN 2.4GHZ-2.6GHZ 50/50 0603

Ngā Rauemi:

[HHM17139B2.pdf](#)

RoHS Tūnga

Whakahaerehia te kore utu / RoHS

Waehere Stock

823244 pcs stock

Tuhinga mai i

Hong Kong

Te Ara Tuhi

DHL/Fedex/TNT/UPS/EMS

**TONO MO TE WHAKAHUA**

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

### Ngā whakaaturanga o HHM17139B2

TAU WAE	HHM17139B2
KAIHANGA	TDK Corporation
WHAKAAHUATANGA	BALUN 2.4GHZ-2.6GHZ 50/50 0603
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
HE RAHINGA KEI TE WĀTEA	823244 pcs
PEPA RARAUNGA	<a href="#">HHM17139B2.pdf</a>
RAUPAPA	-
HOKI HOKI (MIN)	-
RAWEHANGA PUTANGA	178°
PACKAGING	Tape & Reel (TR)
PAA / CASE	0603 (1608 Metric), 6 PC Pad
ĒTAHI INGOA	445-174760-2
MOMO TAE	Surface Mount
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
KO TE WHAKAKORE I TE MAHINGA (MAX)	0.4dB
HAAPAPA - NGA HAUARO / WHAKATIKA	50 / 50 Ohm
MAHINGA RAWE	2.4GHz ~ 2.6GHz
WHAKAAHUATANGA TAIPITOPITO	RF Balun 2.4GHz ~ 2.6GHz 50 / 50 Ohm 0603 (1608 Metric), 6 PC Pad

### Ngā tūtohu e hāngai ana

TDK Corporation HHM17139B2	HHM17139B2 Kaiwhiwhi	HHM17139B2 Kaiwhakarato
HHM17139B2 Utu	HHM17139B2 Pikitia	HHM17139B2 Whakaahua
HHM17139B2 PDF Datasheet	HHM17139B2 Download Datasheet	Tuhinga HHM17139B2
HHM17139B2 Stock	Hokona HHM17139B2	Hokona TDK Corporation HHM17139B2
TDK Corporation HHM17139B2	TDK Corporation Kaiwhakarato	TDK Corporation Kaiwhiwhi
TDK Corporation HHM17139B2		

### Ngā Hua e hāngai ana

<p><b>HHM17125D1</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 2.4GHZ-2.5GHZ 50/50 0603 I roto i te taonga: 496156 pcs</p> <p><b>RFQ</b></p>	<p><b>HHM1711D1</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 2.4GHZ-2.5GHZ 50/100 0603 I roto i te taonga: 180690 pcs</p> <p><b>RFQ</b></p>
<p><b>HHM1710D1</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 2.4GHZ-2.5GHZ 50/50 0603 I roto i te taonga: 460907 pcs</p> <p><b>RFQ</b></p>	<p><b>HHM17144A1</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 791MHZ-960MHZ 50/100 0603 I roto i te taonga: 862583 pcs</p> <p><b>RFQ</b></p>
<p><b>HHM17139B1</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 2.4GHZ-2.5GHZ 50/50 0603 I roto i te taonga: 255709 pcs</p> <p><b>RFQ</b></p>	<p><b>HHM17165A1</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 2.4GHZ-2.8GHZ 50/50 0603 I roto i te taonga: 273962 pcs</p> <p><b>RFQ</b></p>
<p><b>HHM1711Q1</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 2.3GHZ-3.8GHZ 50/100 0603 I roto i te taonga: 836875 pcs</p> <p><b>RFQ</b></p>	<p><b>HHM1711E1</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 2.3GHZ-2.7GHZ 50/100 0603 I roto i te taonga: 796296 pcs</p> <p><b>RFQ</b></p>
<p><b>HHM17152A1</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 698MHZ-894MHZ 50/100 0603 I roto i te taonga: 506941 pcs</p> <p><b>RFQ</b></p>	<p><b>HHM17153A2</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 698MHZ-894MHZ 50/50 0603 I roto i te taonga: 387125 pcs</p> <p><b>RFQ</b></p>
<p><b>HHM1715E1</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 3.3GHZ-3.9GHZ 50/100 0603 I roto i te taonga: 54435 pcs</p> <p><b>RFQ</b></p>	<p><b>HHM17146A1</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 1.92GHZ-2.17GHZ 50/50 0603 I roto i te taonga: 920864 pcs</p> <p><b>RFQ</b></p>