



AVX Corporation

CP0402A1880ELTR

Tau Wae:	CP0402A1880ELTR
Kaihanga / Waitohu:	AVX Corporation
Whakaahuatanga hua	RF DIR COUPLER 1.85-1.91GHZ 0402
Ngā Rauemi:	CP0402A1880ELTR.pdf
RoHS Tūnga	Kei roto nga rangatira / RoHS kaore i te ture
Waehere Stock	415023 pcs stock
Tuhinga mai i	Hong Kong
Te Ara Tuhi	DHL/Fedex/TNT/UPS/EMS

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o CP0402A1880ELTR

TAU WAE	CP0402A1880ELTR
KAIHANGA	AVX Corporation
WHAKAAHUATANGA	RF DIR COUPLER 1.85-1.91GHZ 0402
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Kei roto nga rangatira / RoHS kaore i te ture
HE RAHINGA KEI TE WĀTEA	415023 pcs
PEPA RARAUNGA	CP0402A1880ELTR.pdf
PŪRERE PŪRERE WHAKARATO	0402
RAUPAPA	-
HOKI HOKI	26dB
MANA - MAX	3W
PACKAGING	Tape & Reel (TR)
PAA / CASE	0402 (1005 Metric)
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Contains lead / RoHS non-compliant
WHAKAMOTU	-44dB
TE HAINATANGA WHAKATAUNGA	0.25dB
RAUTANGA	1.85GHz ~ 1.91GHz
WHAKAAHUATANGA TAIPITOPITO	RF Directional Coupler PCS 1.85GHz ~ 1.91GHz 20dB 3W 0402 (1005 Metric)
HONONGA TAE	20dB
HE MOMO HOAHOA	Standard
NGA TONO	PCS

Ngā tūtohu e hāngai ana

AVX Corporation CP0402A1880ELTR	CP0402A1880ELTR Kaiwhiwhi	CP0402A1880ELTR Kaiwhakarato
CP0402A1880ELTR Utu	CP0402A1880ELTR Pikitia	CP0402A1880ELTR Whakaahua
CP0402A1880ELTR PDF Datasheet	CP0402A1880ELTR Download Datasheet	Tuhinga CP0402A1880ELTR
CP0402A1880ELTR Stock	Hokona CP0402A1880ELTR	Hokona AVX Corporation CP0402A1880ELTR
AVX Corporation CP0402A1880ELTR	AVX Corporation Kaiwhakarato	AVX Corporation Kaiwhiwhi
AVX Corporation CP0402A1880ELTR	AVX Corporation [MIL] CP0402A1880ELTR	

Ngā Hua e hāngai ana

<p>CP0402A1880BNTTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.85-1.91GHZ 0402 I roto i te taonga: 436936 pcs</p> <p>RFQ</p>	<p>CP0402A1950ALTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.9GHZ 0402 I roto i te taonga: 414676 pcs</p> <p>RFQ</p>
<p>CP0402A1950CLTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.9GHZ 0402 I roto i te taonga: 486772 pcs</p> <p>RFQ</p>	<p>CP0402A1880CLTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.85-1.91GHZ 0402 I roto i te taonga: 432171 pcs</p> <p>RFQ</p>
<p>CP0402A1880BLTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.85-1.91GHZ 0402 I roto i te taonga: 429093 pcs</p> <p>RFQ</p>	<p>CP0402A1890ALTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.88-1.9GHZ 0402 I roto i te taonga: 502970 pcs</p> <p>RFQ</p>
<p>CP0402A1880ENTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.85-1.91GHZ 0402 I roto i te taonga: 479821 pcs</p> <p>RFQ</p>	<p>CP0402A1880DNTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.85-1.91GHZ 0402 I roto i te taonga: 435221 pcs</p> <p>RFQ</p>
<p>CP0402A1880DLTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.85-1.91GHZ 0402 I roto i te taonga: 459126 pcs</p> <p>RFQ</p>	<p>CP0402A1890ELTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.88-1.9GHZ 0402 I roto i te taonga: 459521 pcs</p> <p>RFQ</p>
<p>CP0402A1880CNTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.85-1.91GHZ 0402 I roto i te taonga: 460616 pcs</p> <p>RFQ</p>	<p>CP0402A1950BLTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.9GHZ 0402 I roto i te taonga: 487993 pcs</p> <p>RFQ</p>

