



Aeroflex (MACOM Technology Solutions)

## MACP-011034

Tau Wae:

MACP-011034

Kaihanga / Waitohu:

Aeroflex (MACOM Technology Solutions)

Whakaahuatanga hua

RF DIR COUPLER 5MHZ-1.2GHZ 6SMD

Ngā Rauemi:

MACP-011034.pdf

RoHS Tūnga

Whakahaerehia te kore utu / RoHS

Waeheere Stock

34659 pcs stock

Tuhinga mai i

Hong Kong

Te Ara Tuhi

DHL/Fedex/TNT/UPS/EMS

**TONO MO TE WHAKAHUA**

### Solutions



Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

### Ngā whakaaturanga o MACP-011034

TAU WAE	MACP-011034
KAIHANGA	Aeroflex (MACOM Technology Solutions)
WHAKAAHUATANGA	RF DIR COUPLER 5MHZ-1.2GHZ 6SMD
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
HE RAHINGA KEI TE WĀTEA	34659 pcs
PEPA RARAUNGA	MACP-011034.pdf
PŪRERE PŪRERE WHAKARATO	6-SMD
RAUPAPA	-
HOKI HOKI	-20dB
MANA - MAX	0.5W
PACKAGING	Cut Tape (CT)
PAA / CASE	6-SMD
ĒTAHI INGOA	1465-1807-1
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
WHAKAMOTU	30dB
TE HAINATANGA WHAKATAUNGA	-
RAUTANGA	5MHz ~ 1.2GHz
WHAKAAHUATANGA TAIPITOPITO	RF Directional Coupler General Purpose 5MHz ~ 1.2GHz 10dB 0.5W 6-SMD
HONONGA TAE	10dB
HE MOMO HOAHOA	Standard
NGA TONO	General Purpose

### Ngā tūtohu e hāngai ana

Aeroflex (MACOM Technology Solutions) MACP-011034	MACP-011034 Kaihiwhi	MACP-011034 Kaiwhakarato
MACP-011034 Utu	MACP-011034 Pikitia	MACP-011034 Whakaahua
MACP-011034 PDF Datasheet	MACP-011034 Download Datasheet	Tuhinga MACP-011034
MACP-011034 Stock	Hokona MACP-011034	Hokona Aeroflex (MACOM Technology Solutions) MACP-011034
Aeroflex (MACOM Technology Solutions) MACP-011034	Aeroflex (MACOM Technology Solutions) Kaiwhakarato	Aeroflex (MACOM Technology Solutions) Kaihiwhi
Aeroflex (MACOM Technology Solutions) MACP-011034	Aeroflex Circuit Technology MACP-011034	Aeroflex MACP-011034
Aeroflex (MACOM Technology Solutions) MACP-011034	Aeroflex Metelics, Division of MACOM MACP-011034	M/A-Com Technology Solutions MACP-011034
Metelics (MACOM Technology Solutions) MACP-011034	MACOM Technology Solutions MACP-011034	

### Ngā Hua e hāngai ana

<p><b>MACP-011032</b> Kaihanga: Aeroflex (MACOM Technology Solutions) Whakaahuatanga: RF DIR COUPLER 5MHZ-1.2GHZ 6SMD I roto i te taonga: 33983 pcs</p> <p><b>RFQ</b></p>	<p><b>MACP-011036</b> Kaihanga: Aeroflex (MACOM Technology Solutions) Whakaahuatanga: RF DIR COUPLER 5MHZ-1.2GHZ 6SMD I roto i te taonga: 4034 pcs</p> <p><b>RFQ</b></p>
<p><b>MACP-010563-TR1000</b> Kaihanga: Aeroflex (MACOM Technology Solutions) Whakaahuatanga: RF DIR COUPLER 10GHZ-30GHZ 6TDFN I roto i te taonga: 4446 pcs</p> <p><b>RFQ</b></p>	<p><b>MACPCT0030</b> Kaihanga: Aeroflex (MACOM Technology Solutions) Whakaahuatanga: RF DIR COUPLER 5MHZ-1.2GHZ 6SMD I roto i te taonga: 27402 pcs</p> <p><b>RFQ</b></p>
<p><b>MACP-011015</b> Kaihanga: Aeroflex (MACOM Technology Solutions) Whakaahuatanga: RF DIR COUPLER 40MHZ-1.25GHZ 5SMD I roto i te taonga: 24969 pcs</p> <p><b>RFQ</b></p>	<p><b>MACP-011035</b> Kaihanga: Aeroflex (MACOM Technology Solutions) Whakaahuatanga: RF DIR COUPLER 5MHZ-1.2GHZ 6SMD I roto i te taonga: 31816 pcs</p> <p><b>RFQ</b></p>
<p><b>MACP-010563-001SMB</b> Kaihanga: Aeroflex (MACOM Technology Solutions) Whakaahuatanga: EVAL BOARD FOR MACP-010563-TR100 I roto i te taonga: 4608 pcs</p> <p><b>RFQ</b></p>	<p><b>MACP-011038</b> Kaihanga: Aeroflex (MACOM Technology Solutions) Whakaahuatanga: RF DIR COUPLER 5MHZ-1.2GHZ 6SMD I roto i te taonga: 5028 pcs</p> <p><b>RFQ</b></p>
<p><b>MACP-011010</b> Kaihanga: Aeroflex (MACOM Technology Solutions) Whakaahuatanga: RF DIR COUPLER 5MHZ-1.2GHZ 6SMD I roto i te taonga: 69745 pcs</p> <p><b>RFQ</b></p>	<p><b>MACP-011033</b> Kaihanga: Aeroflex (MACOM Technology Solutions) Whakaahuatanga: RF DIR COUPLER 5MHZ-1.2GHZ 6SMD I roto i te taonga: 34032 pcs</p> <p><b>RFQ</b></p>
<p><b>MACP-011013</b> Kaihanga: Aeroflex (MACOM Technology Solutions) Whakaahuatanga: RF DIR COUPLER 5MHZ-1.5GHZ 6SMD I roto i te taonga: 75305 pcs</p> <p><b>RFQ</b></p>	<p><b>MACP-011014</b> Kaihanga: Aeroflex (MACOM Technology Solutions) Whakaahuatanga: RF DIR COUPLER 5MHZ-1.5GHZ 6SMD I roto i te taonga: 34558 pcs</p> <p><b>RFQ</b></p>

