



TDK Corporation

## HHM1749S1

Tau Wae:

HHM1749S1

Kaihanga / Waitohu:

TDK Corporation

Whakaahuatanga hua

BALUN 1.71-1.99GHZ 50/100 0603

Ngā Rauemi:

[HHM1749S1.pdf](#)

RoHS Tūnga

Whakahaerehia te kore utu / RoHS

Waehere Stock

800377 pcs stock

Tuhinga mai i

Hong Kong

Te Ara Tuhi

DHL/Fedex/TNT/UPS/EMS

**TONO MO TE WHAKAHUA**

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

### Ngā whakaaturanga o HHM1749S1

TAU WAE	HHM1749S1
KAIHANGA	TDK Corporation
WHAKAAHUATANGA	BALUN 1.71-1.99GHZ 50/100 0603
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
HE RAHINGA KEI TE WĀTEA	800377 pcs
PEPA RARAUNGA	<a href="#">HHM1749S1.pdf</a>
RAUPAPA	-
HOKI HOKI (MIN)	-10dB
RAWEHANGA PUTANGA	180° ±10°
PACKAGING	Tape & Reel (TR)
PAA / CASE	0603 (1608 Metric), 6 PC Pad
ĒTAHI INGOA	445-172638-2
MOMO TAE	Surface Mount
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
KO TE WHAKAKORE I TE MAHINGA (MAX)	1.1dB
HAAPAPA - NGA HAUARO / WHAKATIKA	50 / 100 Ohm
MAHINGA RAWE	1.71GHz ~ 1.99GHz
WHAKAAHUATANGA TAIPITOPITO	RF Balun 1.71GHz ~ 1.99GHz 50 / 100 Ohm 0603 (1608 Metric), 6 PC Pad

### Ngā tūtohu e hāngai ana

TDK Corporation HHM1749S1	HHM1749S1 Kaiwhiwhi	HHM1749S1 Kaiwhakarato
HHM1749S1 Utu	HHM1749S1 Pikitia	HHM1749S1 Whakaahua
HHM1749S1 PDF Datasheet	HHM1749S1 Download Datasheet	Tuhinga HHM1749S1
HHM1749S1 Stock	Hokona HHM1749S1	Hokona TDK Corporation HHM1749S1
TDK Corporation HHM1749S1	TDK Corporation Kaiwhakarato	TDK Corporation Kaiwhiwhi
TDK Corporation HHM1749S1		

### Ngā Hua e hāngai ana

<p><b>HHM1776B3</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 880MHZ-960MHZ 50/50 0603 I roto i te taonga: 188262 pcs</p> <p><b>RFQ</b></p>	<p><b>HHM1732B1</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 4.9GHZ-5.95GHZ 50/100 0603 I roto i te taonga: 273182 pcs</p> <p><b>RFQ</b></p>
<p><b>HHM1763B2</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 880MHZ-960MHZ 50/150 0603 I roto i te taonga: 72443 pcs</p> <p><b>RFQ</b></p>	<p><b>HHM1752A2</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 4.9GHZ-5.95GHZ 50/200 0603 I roto i te taonga: 115644 pcs</p> <p><b>RFQ</b></p>
<p><b>HHM1726N1</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 824MHZ-915MHZ 50/100 0603 I roto i te taonga: 769871 pcs</p> <p><b>RFQ</b></p>	<p><b>HHM1775D1</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 3.1GHZ-4.9GHZ 50/100 0805 I roto i te taonga: 261546 pcs</p> <p><b>RFQ</b></p>
<p><b>HHM1727D1</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 3.3GHZ-3.9GHZ 50/50 0603 I roto i te taonga: 238503 pcs</p> <p><b>RFQ</b></p>	<p><b>HHM1733B1</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 4.9GHZ-5.95GHZ 50/50 0603 I roto i te taonga: 144005 pcs</p> <p><b>RFQ</b></p>
<p><b>HHM1776B2</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 824MHZ-894MHZ 50/50 0603 I roto i te taonga: 57084 pcs</p> <p><b>RFQ</b></p>	<p><b>HHM1779B1</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 2.11-2.17GHZ 50/100 0603 I roto i te taonga: 261529 pcs</p> <p><b>RFQ</b></p>
<p><b>HHM1726P1</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 880MHZ-960MHZ 50/100 0603 I roto i te taonga: 981103 pcs</p> <p><b>RFQ</b></p>	<p><b>HHM1731F1</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 1.71-1.88GHZ 50/200 0603 I roto i te taonga: 821085 pcs</p> <p><b>RFQ</b></p>

