



45-CBSA-1.0X5.5X0.4

Tau Wae:	45-CBSA-1.0X5.5X0.4
Kaihanga / Waitohu:	Leader Tech Inc.
Whakaahuatanga hua	45 SERIES CBS SHIELD ASSEMBLY
Ngā Rauemi:	45-CBSA-1.0X5.5X0.4.pdf
RoHS Tūnga	Whakahaerehia te kore utu / RoHS
Waehere Stock	4488 pcs stock
Tuhinga mai i	Hong Kong
Te Ara Tuhi	DHL/Fedex/TNT/UPS/EMS

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o 45-CBSA-1.0X5.5X0.4

TAU WAE	45-CBSA-1.0X5.5X0.4
KAIHANGA	Leader Tech Inc.
WHAKAAHUATANGA	45 SERIES CBS SHIELD ASSEMBLY
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
HE RAHINGA KEI TE WĀTEA	4488 pcs
PEPA RARAUNGA	45-CBSA-1.0X5.5X0.4.pdf
WHĀNUI - WHĀNUI	1.000" (25.40mm)
TUHINGA O MUA	Vent Holes in Pattern
MOMO	Shield, 2-Piece
RAUPAPA	40-CBS
PACKAGING	Bulk
MOMO TAE	Through Hole
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
TE ROA - WHĀNUI	5.500" (139.70mm)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
TEITEI - WHĀNUI	0.400" (10.16mm)
WHAKAAHUATANGA TAIPITOPITO	RF Shield Shield, 2-Piece 1.000" (25.40mm) X 5.500" (139.70mm) Vent Holes in Pattern Through Hole

Ngā tūtohu e hāngai ana

Leader Tech Inc. 45-CBSA-1.0X5.5X0.4	45-CBSA-1.0X5.5X0.4 Kaiwhiwhi	45-CBSA-1.0X5.5X0.4 Kaiwhakarato
45-CBSA-1.0X5.5X0.4 Utu	45-CBSA-1.0X5.5X0.4 Pikitia	45-CBSA-1.0X5.5X0.4 Whakaahua
45-CBSA-1.0X5.5X0.4 PDF Datasheet	45-CBSA-1.0X5.5X0.4 Download Datasheet	Tuhinga 45-CBSA-1.0X5.5X0.4
45-CBSA-1.0X5.5X0.4 Stock	Hokona 45-CBSA-1.0X5.5X0.4	Hokona Leader Tech Inc. 45-CBSA-1.0X5.5X0.4
Leader Tech Inc. 45-CBSA-1.0X5.5X0.4	Leader Tech Inc. Kaiwhakarato	Leader Tech Inc. Kaiwhiwhi
Leader Tech Inc. 45-CBSA-1.0X5.5X0.4		

Ngā Hua e hāngai ana

<p>45-CBSA-1.0X4.5X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 45 SERIES CBS SHIELD ASSEMBLY I roto i te taonga: 4401 pcs</p> <p>RFQ</p>	<p>45-CBSA-1.25X1.75X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 45 SERIES CBS SHIELD ASSEMBLY I roto i te taonga: 5768 pcs</p> <p>RFQ</p>
<p>45-CBSA-1.0X4.25X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 45 SERIES CBS SHIELD ASSEMBLY I roto i te taonga: 4876 pcs</p> <p>RFQ</p>	<p>45-CBSA-1.0X4.75X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 45 SERIES CBS SHIELD ASSEMBLY I roto i te taonga: 4608 pcs</p> <p>RFQ</p>
<p>45-CBSA-1.25X1.25X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 45-CBSA-1.25X1.25X0.4--45S79--CI I roto i te taonga: 8262 pcs</p> <p>RFQ</p>	<p>45-CBSA-1.0X6.0X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 45 SERIES CBS SHIELD ASSEMBLY I roto i te taonga: 4130 pcs</p> <p>RFQ</p>
<p>45-CBSA-1.25X1.5X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 45 SERIES CBS SHIELD ASSEMBLY I roto i te taonga: 5965 pcs</p> <p>RFQ</p>	<p>45-CBSA-1.0X5.75X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 45 SERIES CBS SHIELD ASSEMBLY I roto i te taonga: 3885 pcs</p> <p>RFQ</p>
<p>45-CBSA-1.25X2.0X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 45 SERIES CBS SHIELD ASSEMBLY I roto i te taonga: 4955 pcs</p> <p>RFQ</p>	<p>45-CBSA-1.0X5.25X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 45 SERIES CBS SHIELD ASSEMBLY I roto i te taonga: 3716 pcs</p> <p>RFQ</p>
<p>45-CBSA-1.0X5.0X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 45 SERIES CBS SHIELD ASSEMBLY I roto i te taonga: 4027 pcs</p> <p>RFQ</p>	<p>45-CBSA-1.0X4.0X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 45 SERIES CBS SHIELD ASSEMBLY I roto i te taonga: 4660 pcs</p> <p>RFQ</p>