

Renesas Electronics America

R5F104BAAFP#V0

Tau Wae: R5F104BAAFP#V0
 Kaihanga / Waitohu: Renesas Electronics America
 Whakaahuatanga hua: IC MCU 16BIT 16KB FLASH 32LQFP
 1.R5F104BAAFP#V0.pdf
 2.R5F104BAAFP#V0.pdf
 3.R5F104BAAFP#V0.pdf
 Ngā Rauemi:
 RoHs Tūnga: Whakahaerehia te kore utu / RoHS
 Waehere Stock: 35874 pcs stock
 Tuhinga mai i: Hong Kong
 Te Ara Tuhi: DHL/Fedex/TNT/UPS/EMS

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o R5F104BAAFP#V0

TAU WAE	R5F104BAAFP#V0
KAIHANGA	Renesas Electronics America
WHAKAAHUATANGA	IC MCU 16BIT 16KB FLASH 32LQFP
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
HE RAHINGA KEI TE WĀTEA	35874 pcs
PEPA RARAUNGA	1.R5F104BAAFP#V0.pdf 2.R5F104BAAFP#V0.pdf 3.R5F104BAAFP#V0.pdf
NGAOHIHI - WHAKAAETANGA (VCC / VDD)	1.6 V ~ 5.5 V
PŪRERE PŪRERE WHAKARATO	32-LQFP (7x7)
TERE	32MHz
RAUPAPA	RL78/G14
RAHI RAM	2.5K x 8
MOMO MOMO RATONGA	FLASH
RAHI MOTU RATONGA	16KB (16K x 8)
NGA PAPA HANGA REO	DMA, LVD, POR, PWM, WDT
PACKAGING	Tray
PAA / CASE	32-LQFP
ĒTAHI INGOA	R5F104BAAFPV0
OSCILLATOR MOMO	Internal
TAE MAHI	-40°C ~ 85°C (TA)
TAU O I / O	22
TAUMATA WHAKAARO MOE (MSL)	3 (168 Hours)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
RAE EEPROM	4K x 8
WHAKAAHUATANGA TAIPITOPITO	RL78 RL78/G14 Microcontroller IC 16-Bit 32MHz 16KB (16K x 8) FLASH 32-LQFP (7x7)
RARAUNGA RARAUNGA	A/D 8x8/10b
NUI RAHI	16-Bit
TE TUKATUKA CORE	RL78
HONONGA	CSI, I ² C, LINbus, UART/USART
TAU WAE TUAKIRI	R5F104

Ngā tūtohu e hāngai ana

Renesas Electronics America R5F104BAAFP#V0	R5F104BAAFP#V0 Kaihiwhi	R5F104BAAFP#V0 Kaiwhakarato
R5F104BAAFP#V0 Utu	R5F104BAAFP#V0 Pikitia	R5F104BAAFP#V0 Whakaahua
R5F104BAAFP#V0 PDF Datasheet	R5F104BAAFP#V0 Download Datasheet	Tuhinga R5F104BAAFP#V0
R5F104BAAFP#V0 Stock	Hokona R5F104BAAFP#V0	Hokona Renesas Electronics America R5F104BAAFP#V0
Renesas Electronics America R5F104BAAFP#V0	Renesas Electronics America Kaiwhakarato	Renesas Electronics America Kaihiwhi
Renesas Electronics America R5F104BAAFP#V0	Renesas Technology Corp R5F104BAAFP#V0	Renesas R5F104BAAFP#V0

Ngā Hua e hāngai ana

<p>R5F104BADFP#V0 Kaihanga: Renesas Electronics America Whakaahuatanga: IC MCU 16BIT I roto i te taonga: 4783 pcs RFQ</p>	<p>R5F104BADFP#X0 Kaihanga: Renesas Electronics America Whakaahuatanga: IC MCU 16BIT I roto i te taonga: 4720 pcs RFQ</p>
<p>R5F104BAANA#U0 Kaihanga: Renesas Electronics America Whakaahuatanga: IC MCU 16BIT 16KB FLASH 32HWQFN I roto i te taonga: 43102 pcs RFQ</p>	<p>R5F104AEASP#X0 Kaihanga: Renesas Electronics America Whakaahuatanga: IC MCU 16BIT 64KB FLASH 30LSSOP I roto i te taonga: 80890 pcs RFQ</p>
<p>R5F104AGASP#X0 Kaihanga: Renesas Electronics America Whakaahuatanga: IC MCU 16BIT 128KB FLASH 30LSSOP I roto i te taonga: 61780 pcs RFQ</p>	<p>R5F104AFASP#X0 Kaihanga: Renesas Electronics America Whakaahuatanga: IC MCU 16BIT 96KB FLASH 30LSSOP I roto i te taonga: 64444 pcs RFQ</p>
<p>R5F104BCAFP#V0 Kaihanga: Renesas Electronics America Whakaahuatanga: IC MCU 16BIT 32KB FLASH 32LQFP I roto i te taonga: 30119 pcs RFQ</p>	<p>R5F104BAGFP#V0 Kaihanga: Renesas Electronics America Whakaahuatanga: IC MCU 16BIT I roto i te taonga: 4245 pcs RFQ</p>
<p>R5F104AFASP#V0 Kaihanga: Renesas Electronics America Whakaahuatanga: IC MCU 16BIT 96KB FLASH 30LSSOP I roto i te taonga: 55970 pcs RFQ</p>	<p>R5F104AGASP#V0 Kaihanga: Renesas Electronics America Whakaahuatanga: IC MCU 16BIT 128KB FLASH 30LSSOP I roto i te taonga: 27089 pcs RFQ</p>
<p>R5F104AEASP#V0 Kaihanga: Renesas Electronics America Whakaahuatanga: IC MCU 16BIT 64KB FLASH 30LSSOP I roto i te taonga: 30395 pcs RFQ</p>	<p>R5F104BAAFP#X0 Kaihanga: Renesas Electronics America Whakaahuatanga: IC MCU 16BIT I roto i te taonga: 3540 pcs RFQ</p>