



49-CBSA-1.0X1.75X0.4

Tau Wae:	49-CBSA-1.0X1.75X0.4
Kaihanga / Waitohu:	Leader Tech Inc.
Whakaahuatanga hua	49 SERIES CBS SHIELD ASSEMBLY
Ngā Rauemi:	49-CBSA-1.0X1.75X0.4.pdf
RoHs Tūnga	Whakahaerehia te kore utu / RoHS
Waehere Stock	5403 pcs stock
Tuhinga mai i	Hong Kong
Te Ara Tuhi	DHL/Fedex/TNT/UPS/EMS

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o 49-CBSA-1.0X1.75X0.4

TAU WAE	49-CBSA-1.0X1.75X0.4
KAIHANGA	Leader Tech Inc.
WHAKAAHUATANGA	49 SERIES CBS SHIELD ASSEMBLY
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
HE RAHINGA KEI TE WĀTEA	5403 pcs
PEPA RARAUNGA	49-CBSA-1.0X1.75X0.4.pdf
WHĀNUI - WHĀNUI	1.000" (25.40mm)
TUHINGA O MUA	Vent Holes in Pattern
MOMO	Shield, 2-Piece
RAUPAPA	40-CBS
PACKAGING	Bulk
MOMO TAE	Through Hole
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
TE ROA - WHĀNUI	1.750" (44.45mm)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
TEITEI - WHĀNUI	0.400" (10.16mm)
WHAKAAHUATANGA TAIPITOPITO	RF Shield Shield, 2-Piece 1.000" (25.40mm) X 1.750" (44.45mm) Vent Holes in Pattern Through Hole

Ngā tūtohu e hāngai ana

Leader Tech Inc. 49-CBSA-1.0X1.75X0.4	49-CBSA-1.0X1.75X0.4 Kaiwhiwhi	49-CBSA-1.0X1.75X0.4 Kaiwhakarato
49-CBSA-1.0X1.75X0.4 Utu	49-CBSA-1.0X1.75X0.4 Pikitia	49-CBSA-1.0X1.75X0.4 Whakaahua
49-CBSA-1.0X1.75X0.4 PDF Datasheet	49-CBSA-1.0X1.75X0.4 Download Datasheet	Tuhinga 49-CBSA-1.0X1.75X0.4
49-CBSA-1.0X1.75X0.4 Stock	Hokona 49-CBSA-1.0X1.75X0.4	Hokona Leader Tech Inc. 49-CBSA-1.0X1.75X0.4
Leader Tech Inc. 49-CBSA-1.0X1.75X0.4	Leader Tech Inc. Kaiwhakarato	Leader Tech Inc. Kaiwhiwhi
Leader Tech Inc. 49-CBSA-1.0X1.75X0.4		

Ngā Hua e hāngai ana

<p>49-CBSA-0.75X5.5X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 49 SERIES CBS SHIELD ASSEMBLY I roto i te taonga: 4508 pcs</p> <p>RFQ</p>	<p>49-CBSA-1.0X3.0X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 49 SERIES CBS SHIELD ASSEMBLY I roto i te taonga: 5051 pcs</p> <p>RFQ</p>
<p>49-CBSA-1.0X1.25X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 49 SERIES CBS SHIELD ASSEMBLY I roto i te taonga: 4848 pcs</p> <p>RFQ</p>	<p>49-CBSA-0.75X6.0X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 49 SERIES CBS SHIELD ASSEMBLY I roto i te taonga: 4370 pcs</p> <p>RFQ</p>
<p>49-CBSA-1.0X2.25X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 49 SERIES CBS SHIELD ASSEMBLY I roto i te taonga: 4995 pcs</p> <p>RFQ</p>	<p>49-CBSA-1.0X2.5X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 49 SERIES CBS SHIELD ASSEMBLY I roto i te taonga: 5384 pcs</p> <p>RFQ</p>
<p>49-CBSA-0.75X5.75X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 49 SERIES CBS SHIELD ASSEMBLY I roto i te taonga: 3673 pcs</p> <p>RFQ</p>	<p>49-CBSA-1.0X2.0X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 49 SERIES CBS SHIELD ASSEMBLY I roto i te taonga: 5335 pcs</p> <p>RFQ</p>
<p>49-CBSA-1.0X1.0X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 49 SERIES CBS SHIELD ASSEMBLY I roto i te taonga: 5585 pcs</p> <p>RFQ</p>	<p>49-CBSA-1.0X3.25X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 49 SERIES CBS SHIELD ASSEMBLY I roto i te taonga: 4238 pcs</p> <p>RFQ</p>
<p>49-CBSA-1.0X2.75X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 49 SERIES CBS SHIELD ASSEMBLY I roto i te taonga: 5164 pcs</p> <p>RFQ</p>	<p>49-CBSA-1.0X1.5X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 49-CBSA-1.0X1.5X0.4--49S16--CIRC I roto i te taonga: 4984 pcs</p> <p>RFQ</p>