



44-CBSA-2.0X2.75X0.4

Tau Wae:	44-CBSA-2.0X2.75X0.4
Kaihanga / Waitohu:	Leader Tech Inc.
Whakaahuatanga hua	44 SERIES CBS SHIELD ASSEMBLY
Ngā Rauemi:	44-CBSA-2.0X2.75X0.4.pdf
RoHS Tūnga	Whakahaerehia te kore utu / RoHS
Waeheere Stock	5183 pcs stock
Tuhinga mai i	Hong Kong
Te Ara Tuhi	DHL/Fedex/TNT/UPS/EMS

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o 44-CBSA-2.0X2.75X0.4

TAU WAE	44-CBSA-2.0X2.75X0.4
KAIHANGA	Leader Tech Inc.
WHAKAAHUATANGA	44 SERIES CBS SHIELD ASSEMBLY
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
HE RAHINGA KEI TE WĀTEA	5183 pcs
PEPA RARAUNGA	44-CBSA-2.0X2.75X0.4.pdf
WHĀNUI - WHĀNUI	2.000" (50.80mm)
TUHINGA O MUA	Vent Holes in Pattern
MOMO	Shield, 2-Piece
RAUPAPA	40-CBS
PACKAGING	Bulk
MOMO TAE	Through Hole
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
TE ROA - WHĀNUI	2.750" (69.85mm)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
TEITEI - WHĀNUI	0.400" (10.16mm)
WHAKAAHUATANGA TAIPITOPITO	RF Shield Shield, 2-Piece 2.000" (50.80mm) X 2.750" (69.85mm) Vent Holes in Pattern Through Hole

Ngā tūtohu e hāngai ana

Leader Tech Inc. 44-CBSA-2.0X2.75X0.4	44-CBSA-2.0X2.75X0.4 Kaiwhiwhi	44-CBSA-2.0X2.75X0.4 Kaiwhakarato
44-CBSA-2.0X2.75X0.4 Utu	44-CBSA-2.0X2.75X0.4 Pikitia	44-CBSA-2.0X2.75X0.4 Whakaahua
44-CBSA-2.0X2.75X0.4 PDF Datasheet	44-CBSA-2.0X2.75X0.4 Download Datasheet	Tuhinga 44-CBSA-2.0X2.75X0.4
44-CBSA-2.0X2.75X0.4 Stock	Hokona 44-CBSA-2.0X2.75X0.4	Hokona Leader Tech Inc. 44-CBSA-2.0X2.75X0.4
Leader Tech Inc. 44-CBSA-2.0X2.75X0.4	Leader Tech Inc. Kaiwhakarato	Leader Tech Inc. Kaiwhiwhi
Leader Tech Inc. 44-CBSA-2.0X2.75X0.4		

Ngā Hua e hāngai ana

<p>44-CBSA-2.0X2.0X0.55 Kaihanga: Leader Tech Inc. Whakaahuatanga: 44-CBSA-2.0X2.0X0.55--44S73--CIR I roto i te taonga: 5026 pcs</p> <p>RFQ</p>	<p>44-CBSA-2.0X3.75X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 44 SERIES CBS SHIELD ASSEMBLY I roto i te taonga: 3865 pcs</p> <p>RFQ</p>
<p>44-CBSA-2.0X4.0X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 44 SERIES CBS SHIELD ASSEMBLY I roto i te taonga: 4271 pcs</p> <p>RFQ</p>	<p>44-CBSA-2.0X2.0X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 44-CBSA-2.0X2.0X0.5--44S220--CI I roto i te taonga: 4243 pcs</p> <p>RFQ</p>
<p>44-CBSA-2.0X2.0X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 44-CBSA-2.0X2.0X0.4--44S72--CIRC I roto i te taonga: 4516 pcs</p> <p>RFQ</p>	<p>44-CBSA-2.0X2.5X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 44 SERIES CBS SHIELD ASSEMBLY I roto i te taonga: 5894 pcs</p> <p>RFQ</p>
<p>44-CBSA-2.0X3.5X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 44 SERIES CBS SHIELD ASSEMBLY I roto i te taonga: 4633 pcs</p> <p>RFQ</p>	<p>44-CBSA-1.75X6.0X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 44 SERIES CBS SHIELD ASSEMBLY I roto i te taonga: 4045 pcs</p> <p>RFQ</p>
<p>44-CBSA-2.0X3.25X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 44 SERIES CBS SHIELD ASSEMBLY I roto i te taonga: 4749 pcs</p> <p>RFQ</p>	<p>44-CBSA-2.0X4.25X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 44 SERIES CBS SHIELD ASSEMBLY I roto i te taonga: 4040 pcs</p> <p>RFQ</p>
<p>44-CBSA-2.0X2.25X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 44 SERIES CBS SHIELD ASSEMBLY I roto i te taonga: 5048 pcs</p> <p>RFQ</p>	<p>44-CBSA-2.0X3.0X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 44-CBSA-2.0X3.0X0.4--44S175--CIR I roto i te taonga: 5487 pcs</p> <p>RFQ</p>