



TDK Corporation

## HHM17139B1

Tau Wae:

HHM17139B1

Kaihanga / Waitohu:

TDK Corporation

Whakaahuatanga hua

BALUN 2.4GHZ-2.5GHZ 50/50 0603

Ngā Rauemi:

HHM17139B1.pdf

RoHS Tūnga

Whakahaerehia te kore utu / RoHS

Waeheere Stock

255709 pcs stock

Tuhinga mai i

Hong Kong

Te Ara Tuhi

DHL/Fedex/TNT/UPS/EMS

**TONO MO TE WHAKAHUA**

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

### Ngā whakaaturanga o HHM17139B1

TAU WAE	HHM17139B1
KAIHANGA	TDK Corporation
WHAKAAHUATANGA	BALUN 2.4GHZ-2.5GHZ 50/50 0603
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
HE RAHINGA KEI TE WĀTEA	255709 pcs
PEPA RARAUNGA	HHM17139B1.pdf
RAUPAPA	-
HOKI HOKI (MIN)	-10dB
RAWEHANGA PUTANGA	180° ±10°
PACKAGING	Cut Tape (CT)
PAA / CASE	0603 (1608 Metric), 6 PC Pad
ĒTAHI INGOA	445-172633-1
MOMO TAE	Surface Mount
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
KO TE WHAKAKORE I TE MAHINGA (MAX)	0.7dB
HAAPAPA - NGA HAUARO / WHAKATIKA	50 / 50 Ohm
MAHINGA RAWE	2.4GHz ~ 2.5GHz
WHAKAAHUATANGA TAIPITOPITO	RF Balun 2.4GHz ~ 2.5GHz 50 / 50 Ohm 0603 (1608 Metric), 6 PC Pad

### Ngā tūtohu e hāngai ana

TDK Corporation HHM17139B1	HHM17139B1 Kaiwhiwhi	HHM17139B1 Kaiwhakarato
HHM17139B1 Utu	HHM17139B1 Pikitia	HHM17139B1 Whakaahua
HHM17139B1 PDF Datasheet	HHM17139B1 Download Datasheet	Tuhinga HHM17139B1
HHM17139B1 Stock	Hokona HHM17139B1	Hokona TDK Corporation HHM17139B1
TDK Corporation HHM17139B1	TDK Corporation Kaiwhakarato	TDK Corporation Kaiwhiwhi
TDK Corporation HHM17139B1		

### Ngā Hua e hāngai ana

<p><b>HHM17139B2</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 2.4GHZ-2.6GHZ 50/50 0603 I roto i te taonga: 823244 pcs</p> <p><b>RFQ</b></p>	<p><b>HHM1711Q1</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 2.3GHZ-3.8GHZ 50/100 0603 I roto i te taonga: 836875 pcs</p> <p><b>RFQ</b></p>
<p><b>HHM17144A1</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 791MHZ-960MHZ 50/100 0603 I roto i te taonga: 862583 pcs</p> <p><b>RFQ</b></p>	<p><b>HHM17125D1</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 2.4GHZ-2.5GHZ 50/50 0603 I roto i te taonga: 496156 pcs</p> <p><b>RFQ</b></p>
<p><b>HHM1711E1</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 2.3GHZ-2.7GHZ 50/100 0603 I roto i te taonga: 796296 pcs</p> <p><b>RFQ</b></p>	<p><b>HHM17153A2</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 698MHZ-894MHZ 50/50 0603 I roto i te taonga: 387125 pcs</p> <p><b>RFQ</b></p>
<p><b>HHM1715E1</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 3.3GHZ-3.9GHZ 50/100 0603 I roto i te taonga: 54435 pcs</p> <p><b>RFQ</b></p>	<p><b>HHM17146A1</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 1.92GHZ-2.17GHZ 50/50 0603 I roto i te taonga: 920864 pcs</p> <p><b>RFQ</b></p>
<p><b>HHM17152A1</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 698MHZ-894MHZ 50/100 0603 I roto i te taonga: 506941 pcs</p> <p><b>RFQ</b></p>	<p><b>HHM1711D1</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 2.4GHZ-2.5GHZ 50/100 0603 I roto i te taonga: 180690 pcs</p> <p><b>RFQ</b></p>
<p><b>HHM1603A1</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 2.3GHZ-2.7GHZ 50/100 4SMD I roto i te taonga: 120843 pcs</p> <p><b>RFQ</b></p>	<p><b>HHM1710D1</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 2.4GHZ-2.5GHZ 50/50 0603 I roto i te taonga: 460907 pcs</p> <p><b>RFQ</b></p>