



TDK Corporation

## HHM1917A5

Tau Wae:

HHM1917A5

Kaihanga / Waitohu:

TDK Corporation

Whakaahuatanga hua

BALUN 2.4GHZ-2.5GHZ 50/50 0402

Ngā Rauemi:

HHM1917A5.pdf

RoHS Tūnga

Whakahaerehia te kore utu / RoHS

Waehere Stock

335006 pcs stock

Tuhinga mai i

Hong Kong

Te Ara Tuhi

DHL/Fedex/TNT/UPS/EMS

**TONO MO TE WHAKAHUA**

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

### Ngā whakaaturanga o HHM1917A5

TAU WAE	HHM1917A5
KAIHANGA	TDK Corporation
WHAKAAHUATANGA	BALUN 2.4GHZ-2.5GHZ 50/50 0402
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
HE RAHINGA KEI TE WĀTEA	335006 pcs
PEPA RARAUNGA	HHM1917A5.pdf
RAUPAPA	*
PACKAGING	Cut Tape (CT)
PAA / CASE	0402 (1005 Metric), 4 PC Pad
ĒTAHI INGOA	445-175600-1
MOMO TAE	Surface Mount
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
WHAKAAHUATANGA TAIPITOPITO	RF Balun 0402 (1005 Metric), 4 PC Pad

### Ngā tūtohu e hāngai ana

TDK Corporation HHM1917A5	HHM1917A5 Kaiwhiwhi	HHM1917A5 Kaiwhakarato
HHM1917A5 Utu	HHM1917A5 Pikitia	HHM1917A5 Whakaahua
HHM1917A5 PDF Datasheet	HHM1917A5 Download Datasheet	Tuhinga HHM1917A5
HHM1917A5 Stock	Hokona HHM1917A5	Hokona TDK Corporation HHM1917A5
TDK Corporation HHM1917A5	TDK Corporation Kaiwhakarato	TDK Corporation Kaiwhiwhi
TDK Corporation HHM1917A5		

### Ngā Hua e hāngai ana

<p><b>HHM1918A2</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 2.3GHZ-2.7GHZ 50/100 0402 I roto i te taonga: 1190924 pcs</p> <p><b>RFQ</b></p>	<p><b>HHM1903A4</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 2.4GHZ-2.5GHZ 50/100 0402 I roto i te taonga: 314972 pcs</p> <p><b>RFQ</b></p>
<p><b>HHM2202SA2</b> Kaihanga: TDK Corporation Whakaahuatanga: RF DIR COUPLER 1.71-1.79GHZ 0603 I roto i te taonga: 4048 pcs</p> <p><b>RFQ</b></p>	<p><b>HHM1907B1</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 2.4GHZ-5.95GHZ 50/50 0402 I roto i te taonga: 307944 pcs</p> <p><b>RFQ</b></p>
<p><b>HHM2204SA1</b> Kaihanga: TDK Corporation Whakaahuatanga: RF DIR COUPLR 1.71-1.785GHZ 0603 I roto i te taonga: 237035 pcs</p> <p><b>RFQ</b></p>	<p><b>HHM1927A4</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 1.805-2.17GHZ 50/100 0402 I roto i te taonga: 319228 pcs</p> <p><b>RFQ</b></p>
<p><b>HHM1906A1</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 4.9GHZ-5.95GHZ 50/75 0402 I roto i te taonga: 3696 pcs</p> <p><b>RFQ</b></p>	<p><b>HHM1904A1</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 2.4GHZ-2.5GHZ 50/75 0402 I roto i te taonga: 58057 pcs</p> <p><b>RFQ</b></p>
<p><b>HHM1946A1</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 2.3GHZ-2.7GHZ 50/100 0402 I roto i te taonga: 62622 pcs</p> <p><b>RFQ</b></p>	<p><b>HHM1932A2</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 862MHZ-894MHZ 50/100 0402 I roto i te taonga: 1054239 pcs</p> <p><b>RFQ</b></p>
<p><b>HHM1904C1</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 2.4GHZ-2.5GHZ 50/75 0402 I roto i te taonga: 47142 pcs</p> <p><b>RFQ</b></p>	<p><b>HHM1903A1</b> Kaihanga: TDK Corporation Whakaahuatanga: BALUN 2.4GHZ-2.5GHZ 50/100 0402 I roto i te taonga: 212246 pcs</p> <p><b>RFQ</b></p>

