



Leader Tech Inc.

50-CBSA-2.0X3.75X0.5

Tau Wae:	50-CBSA-2.0X3.75X0.5
Kaihanga / Waitohu:	Leader Tech Inc.
Whakaahuatanga hua	50 SERIES CBS SHIELD ASSEMBLY -
Ngā Rauemi:	50-CBSA-2.0X3.75X0.5.pdf
RoHS Tūnga	Whakahaerehia te kore utu / RoHS
Waeheere Stock	4463 pcs stock
Tuhinga mai i	Hong Kong
Te Ara Tuhi	DHL/Fedex/TNT/UPS/EMS

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o 50-CBSA-2.0X3.75X0.5

TAU WAE	50-CBSA-2.0X3.75X0.5
KAIHANGA	Leader Tech Inc.
WHAKAAHUATANGA	50 SERIES CBS SHIELD ASSEMBLY -
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
HE RAHINGA KEI TE WĀTEA	4463 pcs
PEPA RARAUNGA	50-CBSA-2.0X3.75X0.5.pdf
WHĀNUI - WHĀNUI	2.000" (50.80mm)
TUHINGA O MUA	Vent Holes in Pattern
MOMO	Shield, 2-Piece
RAUPAPA	50-CBS
PACKAGING	Bulk
ĒTAHI INGOA	50-CBSA-2.0X3.75X0.4 50-CBSA-2.0X3.75X0.4-ND
MOMO TAE	Surface Mount
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
TE ROA - WHĀNUI	3.750" (95.25mm)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
TEITEI - WHĀNUI	0.500" (12.70mm)
WHAKAAHUATANGA TAIPITOPITO	RF Shield Shield, 2-Piece 2.000" (50.80mm) X 3.750" (95.25mm) Vent Holes in Pattern Surface Mount

Ngā tūtohu e hāngai ana

Leader Tech Inc. 50-CBSA-2.0X3.75X0.5	50-CBSA-2.0X3.75X0.5 Kaiwhiwhi	50-CBSA-2.0X3.75X0.5 Kaiwhakarato
50-CBSA-2.0X3.75X0.5 Utu	50-CBSA-2.0X3.75X0.5 Pikitia	50-CBSA-2.0X3.75X0.5 Whakaahua
50-CBSA-2.0X3.75X0.5 PDF Datasheet	50-CBSA-2.0X3.75X0.5 Download Datasheet	Tuhinga 50-CBSA-2.0X3.75X0.5
50-CBSA-2.0X3.75X0.5 Stock	Hokona 50-CBSA-2.0X3.75X0.5	Hokona Leader Tech Inc. 50-CBSA-2.0X3.75X0.5
Leader Tech Inc. 50-CBSA-2.0X3.75X0.5	Leader Tech Inc. Kaiwhakarato	Leader Tech Inc. Kaiwhiwhi
Leader Tech Inc. 50-CBSA-2.0X3.75X0.5		

Ngā Hua e hāngai ana

<p>50-CBSA-2.0X2.25X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 50 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 5169 pcs</p> <p>RFQ</p>	<p>50-CBSA-2.0X5.0X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 50 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 4083 pcs</p> <p>RFQ</p>
<p>50-CBSA-2.0X4.0X0.8 Kaihanga: Leader Tech Inc. Whakaahuatanga: 50-CBSA-2.0X4.0X0.80--50S34--CIR I roto i te taonga: 3495 pcs</p> <p>RFQ</p>	<p>50-CBSA-2.0X4.0X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 50 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 4337 pcs</p> <p>RFQ</p>
<p>50-CBSA-2.0X2.5X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 50 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 5309 pcs</p> <p>RFQ</p>	<p>50-CBSA-2.0X3.0X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 50 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 5589 pcs</p> <p>RFQ</p>
<p>50-CBSA-2.0X3.25X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 50 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 4094 pcs</p> <p>RFQ</p>	<p>50-CBSA-2.0X3.5X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 50 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 5173 pcs</p> <p>RFQ</p>
<p>50-CBSA-2.0X4.5X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 50 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 3726 pcs</p> <p>RFQ</p>	<p>50-CBSA-2.0X2.75X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 50 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 3872 pcs</p> <p>RFQ</p>
<p>50-CBSA-2.0X4.25X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 50 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 4085 pcs</p> <p>RFQ</p>	<p>50-CBSA-2.0X4.75X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 50 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 4487 pcs</p> <p>RFQ</p>