



TDK Corporation

HHM17168B1

Tau Wae:

HHM17168B1

Kaihanga / Waitohu:

TDK Corporation

Whakaahuatanga hua

BALUN 3.4GHZ-3.8GHZ 50/50 0603

Ngā Rauemi:

HHM17168B1.pdf

RoHS Tūnga

Whakahaerehia te kore utu / RoHS

Waehere Stock

227544 pcs stock

Tuhinga mai i

Hong Kong

Te Ara Tuhi

DHL/Fedex/TNT/UPS/EMS

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o HHM17168B1

TAU WAE	HHM17168B1
KAIHANGA	TDK Corporation
WHAKAAHUATANGA	BALUN 3.4GHZ-3.8GHZ 50/50 0603
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
HE RAHINGA KEI TE WĀTEA	227544 pcs
PEPA RARAUNGA	HHM17168B1.pdf
RAUPAPA	-
HOKI HOKI (MIN)	-18.6dB
RAWEHANGA PUTANGA	182°
PACKAGING	Tape & Reel (TR)
PAA / CASE	0603 (1608 Metric), 6 PC Pad
ĒTAHI INGOA	445-173037-2
MOMO TAE	Surface Mount
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
KO TE WHAKAKORE I TE MAHINGA (MAX)	0.8dB
HAAPAPA - NGA HAUARO / WHAKATIKA	50 / 50 Ohm
MAHINGA RAWE	3.4GHz ~ 3.8GHz
WHAKAAHUATANGA TAIPITOPITO	RF Balun 3.4GHz ~ 3.8GHz 50 / 50 Ohm 0603 (1608 Metric), 6 PC Pad

Ngā tūtohu e hāngai ana

TDK Corporation HHM17168B1	HHM17168B1 Kaiwhiwhi	HHM17168B1 Kaiwhakarato
HHM17168B1 Utu	HHM17168B1 Pikitia	HHM17168B1 Whakaahua
HHM17168B1 PDF Datasheet	HHM17168B1 Download Datasheet	Tuhinga HHM17168B1
HHM17168B1 Stock	Hokona HHM17168B1	Hokona TDK Corporation HHM17168B1
TDK Corporation HHM17168B1	TDK Corporation Kaiwhakarato	TDK Corporation Kaiwhiwhi
TDK Corporation HHM17168B1		

Ngā Hua e hāngai ana

<p>HHM1733B1 Kaihanga: TDK Corporation Whakaahuatanga: BALUN 4.9GHZ-5.95GHZ 50/50 0603 I roto i te taonga: 144005 pcs</p> <p>RFQ</p>	<p>HHM1731F1 Kaihanga: TDK Corporation Whakaahuatanga: BALUN 1.71-1.88GHZ 50/200 0603 I roto i te taonga: 821085 pcs</p> <p>RFQ</p>
<p>HHM17152A1 Kaihanga: TDK Corporation Whakaahuatanga: BALUN 698MHZ-894MHZ 50/100 0603 I roto i te taonga: 506941 pcs</p> <p>RFQ</p>	<p>HHM1715E1 Kaihanga: TDK Corporation Whakaahuatanga: BALUN 3.3GHZ-3.9GHZ 50/100 0603 I roto i te taonga: 54435 pcs</p> <p>RFQ</p>
<p>HHM1727D1 Kaihanga: TDK Corporation Whakaahuatanga: BALUN 3.3GHZ-3.9GHZ 50/50 0603 I roto i te taonga: 238503 pcs</p> <p>RFQ</p>	<p>HHM1732B1 Kaihanga: TDK Corporation Whakaahuatanga: BALUN 4.9GHZ-5.95GHZ 50/100 0603 I roto i te taonga: 273182 pcs</p> <p>RFQ</p>
<p>HHM17146A1 Kaihanga: TDK Corporation Whakaahuatanga: BALUN 1.92GHZ-2.17GHZ 50/50 0603 I roto i te taonga: 920864 pcs</p> <p>RFQ</p>	<p>HHM17166A1 Kaihanga: TDK Corporation Whakaahuatanga: BALUN 1.9GHZ-2.3GHZ 50/50 0603 I roto i te taonga: 247743 pcs</p> <p>RFQ</p>
<p>HHM17153A2 Kaihanga: TDK Corporation Whakaahuatanga: BALUN 698MHZ-894MHZ 50/50 0603 I roto i te taonga: 387125 pcs</p> <p>RFQ</p>	<p>HHM17165A1 Kaihanga: TDK Corporation Whakaahuatanga: BALUN 2.4GHZ-2.8GHZ 50/50 0603 I roto i te taonga: 273962 pcs</p> <p>RFQ</p>
<p>HHM1726P1 Kaihanga: TDK Corporation Whakaahuatanga: BALUN 880MHZ-960MHZ 50/100 0603 I roto i te taonga: 981103 pcs</p> <p>RFQ</p>	<p>HHM1726N1 Kaihanga: TDK Corporation Whakaahuatanga: BALUN 824MHZ-915MHZ 50/100 0603 I roto i te taonga: 769871 pcs</p> <p>RFQ</p>