



Leader Tech Inc.

58-CBSA-2.75X4.25X0.5

Tau Wae:	58-CBSA-2.75X4.25X0.5
Kaihanga / Waitohu:	Leader Tech Inc.
Whakaahuatanga hua	58 SERIES CBS SHIELD ASSEMBLY -
Ngā Rauemi:	58-CBSA-2.75X4.25X0.5.pdf
RoHS Tūnga	Whakahaerehia te kore utu / RoHS
Waehere Stock	4299 pcs stock
Tuhinga mai i	Hong Kong
Te Ara Tuhi	DHL/Fedex/TNT/UPS/EMS

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o 58-CBSA-2.75X4.25X0.5

TAU WAE	58-CBSA-2.75X4.25X0.5
KAIHANGA	Leader Tech Inc.
WHAKAAHUATANGA	58 SERIES CBS SHIELD ASSEMBLY -
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
HE RAHINGA KEI TE WĀTEA	4299 pcs
PEPA RARAUNGA	58-CBSA-2.75X4.25X0.5.pdf
WHĀNUI - WHĀNUI	2.750" (69.85mm)
TUHINGA O MUA	Vent Holes in Pattern
MOMO	Shield, 2-Piece
RAUPAPA	50-CBS
PACKAGING	Bulk
ĒTAHI INGOA	58-CBSA-2.75X4.25X0.4 58-CBSA-2.75X4.25X0.4-ND
MOMO TAE	Through Hole
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
TE ROA - WHĀNUI	4.250" (107.95mm)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
TEITEI - WHĀNUI	0.500" (12.70mm)
WHAKAAHUATANGA TAIPITOPITO	RF Shield Shield, 2-Piece 2.750" (69.85mm) X 4.250" (107.95mm) Vent Holes in Pattern Through Hole

Ngā tūtohu e hāngai ana

Leader Tech Inc. 58-CBSA-2.75X4.25X0.5	58-CBSA-2.75X4.25X0.5 Kaihiwhi	58-CBSA-2.75X4.25X0.5 Kaiwhakarato
58-CBSA-2.75X4.25X0.5 Utu	58-CBSA-2.75X4.25X0.5 Pikitia	58-CBSA-2.75X4.25X0.5 Whakaahua
58-CBSA-2.75X4.25X0.5 PDF Datasheet	58-CBSA-2.75X4.25X0.5 Download Datasheet	Tuhinga 58-CBSA-2.75X4.25X0.5
58-CBSA-2.75X4.25X0.5 Stock	Hokona 58-CBSA-2.75X4.25X0.5	Hokona Leader Tech Inc. 58-CBSA-2.75X4.25X0.5
Leader Tech Inc. 58-CBSA-2.75X4.25X0.5	Leader Tech Inc. Kaiwhakarato	Leader Tech Inc. Kaihiwhi
Leader Tech Inc. 58-CBSA-2.75X4.25X0.5		

Ngā Hua e hāngai ana

<p>58-CBSA-2.75X3.75X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 58 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 4375 pcs</p> <p>RFQ</p>	<p>58-CBSA-2.75X5.25X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 58 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 3465 pcs</p> <p>RFQ</p>
<p>58-CBSA-2.75X2.75X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 58 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 3661 pcs</p> <p>RFQ</p>	<p>58-CBSA-2.75X4.75X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 58 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 4268 pcs</p> <p>RFQ</p>
<p>58-CBSA-2.75X5.5X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 58 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 3926 pcs</p> <p>RFQ</p>	<p>58-CBSA-2.75X4.0X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 58 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 4468 pcs</p> <p>RFQ</p>
<p>58-CBSA-2.75X3.5X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 58 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 3726 pcs</p> <p>RFQ</p>	<p>58-CBSA-2.75X3.25X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 58 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 4576 pcs</p> <p>RFQ</p>
<p>58-CBSA-2.75X5.75X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 58 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 3991 pcs</p> <p>RFQ</p>	<p>58-CBSA-2.75X5.0X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 58 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 3407 pcs</p> <p>RFQ</p>
<p>58-CBSA-2.75X4.5X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 58 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 3380 pcs</p> <p>RFQ</p>	<p>58-CBSA-2.75X3.0X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 58 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 4723 pcs</p> <p>RFQ</p>