



Pulse Electronics Corporation

CX6097

Tau Wae:	CX6097
Kaihanga / Waitohu:	Pulse Electronics Corporation
Whakaahuatanga hua	RF DIPLEXER
Ngā Rauemi:	
RoHS Tūnga	Whakahaerehia te kore utu / RoHS
Waehere Stock	3988 pcs stock
Tuhinga mai i	Hong Kong
Te Ara Tuhi	DHL/Fedex/TNT/UPS/EMS

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o CX6097

TAU WAE	CX6097
KAIHANGA	Pulse Electronics Corporation
WHAKAAHUATANGA	RF DIPLEXER
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
HE RAHINGA KEI TE WĀTEA	3988 pcs
PEPA RARAUNGA	
RAUPAPA	-
TAUMATA WHAKAARO MOE (MSL)	Vendor Undefined
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
WHAKAAHUATANGA TAIPITOPITO	RF Diplexor

Ngā tūtohu e hāngai ana

Pulse Electronics Corporation CX6097	CX6097 Kaiwhiwhi	CX6097 Kaiwhakarato
CX6097 Utu	CX6097 Pikitia	CX6097 Whakaahua
CX6097 PDF Datasheet	CX6097 Download Datasheet	Tuhinga CX6097
CX6097 Stock	Hokona CX6097	Hokona Pulse Electronics Corporation CX6097
Pulse Electronics Corporation CX6097	Pulse Electronics Corporation Kaiwhakarato	Pulse Electronics Corporation Kaiwhiwhi
Pulse Electronics Corporation CX6097	Pulse A Technitrol Company CX6097	Pulse CX6097

Ngā Hua e hāngai ana

<p>CX6045NL</p> <p>Kaihanga: Pulse Electronics Corporation Whakaahuatanga: RF DIPLEXER I roto i te taonga: 5986 pcs</p> <p>RFQ</p>	<p>CX6167NL</p> <p>Kaihanga: Pulse Electronics Corporation Whakaahuatanga: RF DIPLEXER I roto i te taonga: 6483 pcs</p> <p>RFQ</p>
<p>CX6065</p> <p>Kaihanga: Pulse Electronics Corporation Whakaahuatanga: RF DIPLEXER I roto i te taonga: 4748 pcs</p> <p>RFQ</p>	<p>CX6148</p> <p>Kaihanga: Pulse Electronics Corporation Whakaahuatanga: RF DIPLEXER I roto i te taonga: 4897 pcs</p> <p>RFQ</p>
<p>CX6085NL</p> <p>Kaihanga: Pulse Electronics Corporation Whakaahuatanga: RF DIPLEXER I roto i te taonga: 2721 pcs</p> <p>RFQ</p>	<p>CX6180NL</p> <p>Kaihanga: Pulse Electronics Corporation Whakaahuatanga: RF DIPLEXER I roto i te taonga: 5626 pcs</p> <p>RFQ</p>
<p>CX6125NL</p> <p>Kaihanga: Pulse Electronics Corporation Whakaahuatanga: RF DIPLEXER I roto i te taonga: 6749 pcs</p> <p>RFQ</p>	<p>CX6155NL</p> <p>Kaihanga: Pulse Electronics Corporation Whakaahuatanga: RF DIPLEXER I roto i te taonga: 4670 pcs</p> <p>RFQ</p>
<p>CX6046NL</p> <p>Kaihanga: Pulse Electronics Corporation Whakaahuatanga: RF DIPLEXER I roto i te taonga: 3439 pcs</p> <p>RFQ</p>	<p>CX6109</p> <p>Kaihanga: Pulse Electronics Corporation Whakaahuatanga: RF DIPLEXER I roto i te taonga: 3338 pcs</p> <p>RFQ</p>
<p>CX6052L</p> <p>Kaihanga: Pulse Electronics Corporation Whakaahuatanga: RF DIPLEXER I roto i te taonga: 4641 pcs</p> <p>RFQ</p>	<p>CX6087</p> <p>Kaihanga: Pulse Electronics Corporation Whakaahuatanga: RF DIPLEXER I roto i te taonga: 3270 pcs</p> <p>RFQ</p>

