



TDK Corporation

## DPX252500DT-5217A1

Tau Wae:	DPX252500DT-5217A1
Kaihanga / Waitohu:	TDK Corporation
Whakaahuatanga hua	RF DIPLEXER 1.575/2.45GHZ 1008
Ngā Rauemi:	DPX252500DT-5217A1.pdf
RoHS Tūnga	Whakahaerehia te kore utu / RoHS
Waeheere Stock	81828 pcs stock
Tuhinga mai i	Hong Kong
Te Ara Tuhi	DHL/Fedex/TNT/UPS/EMS

**TONO MO TE WHAKAHUA**

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

### Ngā whakaaturanga o DPX252500DT-5217A1

TAU WAE	DPX252500DT-5217A1
KAIHANGA	TDK Corporation
WHAKAAHUATANGA	RF DIPLEXER 1.575/2.45GHZ 1008
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
HE RAHINGA KEI TE WĀTEA	81828 pcs
PEPA RARAUNGA	DPX252500DT-5217A1.pdf
RAUPAPA	DPX
KO TE HOKI HOKI (ROA RAWA / HAINA NUI)	23dB / 22dB
PACKAGING	Cut Tape (CT)
PAA / CASE	1008 (2520 Metric), 8 PC Pad
ĒTAHI INGOA	445-15628-1
MOMO TAE	Surface Mount
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
TAE WHAKAMURI RAWA (MIN / MAX DB)	25.00dB / 33.00dB
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
TAE WHAKATEITEI NUI (MIN / MAX DB)	25.00dB / 54.00dB
NGĀ RŌPŪ TAEKE (RARO / TEITEI)	1.57GHz ~ 1.58GHz / 2.4GHz ~ 2.5GHz
WHAKAAHUATANGA TAIPITOPITO	RF Diplexor 1.57GHz ~ 1.58GHz / 2.4GHz ~ 2.5GHz 1008 (2520 Metric), 8 PC Pad

### Ngā tūtohu e hāngai ana

TDK Corporation DPX252500DT-5217A1	DPX252500DT-5217A1 Kaihiwhi	DPX252500DT-5217A1 Kaiwhakarato
DPX252500DT-5217A1 Utu	DPX252500DT-5217A1 Pikitia	DPX252500DT-5217A1 Whakaahua
DPX252500DT-5217A1 PDF Datasheet	DPX252500DT-5217A1 Download Datasheet	Tuhinga DPX252500DT-5217A1
DPX252500DT-5217A1 Stock	Hokona DPX252500DT-5217A1	Hokona TDK Corporation DPX252500DT-5217A1
TDK Corporation DPX252500DT-5217A1	TDK Corporation Kaiwhakarato	TDK Corporation Kaihiwhi
TDK Corporation DPX252500DT-5217A1		

### Ngā Hua e hāngai ana

<p><b>DPX205950DT-9126A1</b> Kaihanga: TDK Corporation Whakaahuatanga: RF DIPLEXER 2.45/5.425GHZ 0805 I roto i te taonga: 245163 pcs</p> <p><b>RFQ</b></p>	<p><b>DPX205950DT-9026A1</b> Kaihanga: TDK Corporation Whakaahuatanga: RF DIPLEXER 2.45/5.425GHZ 0805 I roto i te taonga: 117814 pcs</p> <p><b>RFQ</b></p>
<p><b>DPX252690DT-5121C1</b> Kaihanga: TDK Corporation Whakaahuatanga: RF DIPLEXER 1008 8 PC PAD I roto i te taonga: 65216 pcs</p> <p><b>RFQ</b></p>	<p><b>DPX252690DT-5032B1</b> Kaihanga: TDK Corporation Whakaahuatanga: RF DIPLEXER 829.5MHZ/2.2GHZ 0402 I roto i te taonga: 238553 pcs</p> <p><b>RFQ</b></p>
<p><b>DPX205950DT-9108A1</b> Kaihanga: TDK Corporation Whakaahuatanga: RF DIPLEXER 2.4GHZ/5.425GHZ 0805 I roto i te taonga: 246533 pcs</p> <p><b>RFQ</b></p>	<p><b>DPX252690DT-5021B1</b> Kaihanga: TDK Corporation Whakaahuatanga: RF DIPLEXER 829MHZ/2.2GHZ 1008 I roto i te taonga: 259224 pcs</p> <p><b>RFQ</b></p>
<p><b>DPX205950DT-9008A1</b> Kaihanga: TDK Corporation Whakaahuatanga: RF DIPLEXER 2.4GHZ/5.425GHZ 0805 I roto i te taonga: 137411 pcs</p> <p><b>RFQ</b></p>	<p><b>DPX252690DT-5031A1</b> Kaihanga: TDK Corporation Whakaahuatanga: RF DIPLEXER 829MHZ/2.2GHZ 0402 I roto i te taonga: 92131 pcs</p> <p><b>RFQ</b></p>
<p><b>DPX255950DT-5120A1</b> Kaihanga: TDK Corporation Whakaahuatanga: RF DIPLEXER 2.45/5.425GHZ 0805 I roto i te taonga: 215940 pcs</p> <p><b>RFQ</b></p>	<p><b>DPX250894DT-5025A1</b> Kaihanga: TDK Corporation Whakaahuatanga: RF DIPLEXER 1008 8 PC PAD I roto i te taonga: 101175 pcs</p> <p><b>RFQ</b></p>
<p><b>DPX205850DT-9038A1-H</b> Kaihanga: TDK Corporation Whakaahuatanga: RF DIPLEXER 2.45GHZ/5.5GHZ 0805 I roto i te taonga: 262057 pcs</p> <p><b>RFQ</b></p>	<p><b>DPX252690DT-5042B2</b> Kaihanga: TDK Corporation Whakaahuatanga: RF DIPLEXER 1008 8 PC PAD I roto i te taonga: 93253 pcs</p> <p><b>RFQ</b></p>

