



Renesas Electronics America

R5F56517BDFB#30

Tau Wae:

R5F56517BDFB#30

Kaihanga / Waitohu:

Renesas Electronics America

Whakaahuatanga hua

IC MCU 32BIT 768KB FLASH 144LQFP

1.R5F56517BDFB#30.pdf

2.R5F56517BDFB#30.pdf

3.R5F56517BDFB#30.pdf

4.R5F56517BDFB#30.pdf

Ngā Rauemi:

Whakahaerehia te kore utu / RoHS

RoHS Tūnga

7292 pcs stock

Waehere Stock

Hong Kong

Tuhinga mai i

DHL/Fedex/TNT/UPS/EMS

Te Ara Tuhi

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o R5F56517BDFB#30

TAU WAE	R5F56517BDFB#30
KAIHANGA	Renesas Electronics America
WHAKAAHUATANGA	IC MCU 32BIT 768KB FLASH 144LQFP
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
HE RAHINGA KEI TE WĀTEA	7292 pcs
PEPA RARAUNGA	1.R5F56517BDFB#30.pdf 2.R5F56517BDFB#30.pdf 3.R5F56517BDFB#30.pdf 4.R5F56517BDFB#30.pdf
NGAOHIHI - WHAKAAETANGA (VCC / VDD)	2.7 V ~ 3.6 V
PŪRERE PŪRERE WHAKARATO	144-LFQFP (20x20)
TERE	120MHz
RAUPAPA	RX651
RAHI RAM	256K x 8
MOMO MOMO RATONGA	FLASH
RAHI MOTU RATONGA	768KB (768K x 8)
NGA PAPA HANGA REO	DMA, LVD, POR, PWM, WDT
PACKAGING	Tray
PAA / CASE	144-LQFP
OSCILLATOR MOMO	Internal
TAE MAHI	-40°C ~ 85°C (TA)
TAU O I / O	111
TAUMATA WHAKAARO MOE (MSL)	3 (168 Hours)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
RAE EEPROM	-
WHAKAAHUATANGA TAIPITOPITO	RXv2 RX651 Microcontroller IC 32-Bit 120MHz 768KB (768K x 8) FLASH 144-LFQFP (20x20)
RARAUNGA RARAUNGA	A/D 29x12b, D/A 2x12b
NUI RAHI	32-Bit
TE TUKATUKA CORE	RXv2
HONONGA	CANbus, EBI/EMI, Ethernet, I ² C, LINbus, MMC/SD, QSPI, SCI, SPI, UART/USART, USB

Ngā tūtohu e hāngai ana

Renesas Electronics America R5F56517BDFB#30	R5F56517BDFB#30 Kaiwhiwhi	R5F56517BDFB#30 Kaiwhakarato
R5F56517BDFB#30 Utu	R5F56517BDFB#30 Pikitia	R5F56517BDFB#30 Whakaahua
R5F56517BDFB#30 PDF Datasheet	R5F56517BDFB#30 Download Datasheet	Tuhinga R5F56517BDFB#30
R5F56517BDFB#30 Stock	Hokona R5F56517BDFB#30	Hokona Renesas Electronics America R5F56517BDFB#30
Renesas Electronics America R5F56517BDFB#30	Renesas Electronics America Kaiwhakarato	Renesas Electronics America Kaiwhiwhi
Renesas Electronics America R5F56517BDFB#30	Renesas Technology Corp R5F56517BDFB#30	Renesas R5F56517BDFB#30

Ngā Hua e hāngai ana

<p>R5F56517ADLJ#20 Kaihanga: Renesas Electronics America Whakaahuatanga: IC MCU 32BIT 768KB FLASH 100LGA I roto i te taonga: 10842 pcs</p> <p>RFQ</p>	<p>R5F56517BDFP#30 Kaihanga: Renesas Electronics America Whakaahuatanga: IC MCU 32BIT 768KB FLASH 100LQFP I roto i te taonga: 7746 pcs</p> <p>RFQ</p>
<p>R5F56517ADFP#30 Kaihanga: Renesas Electronics America Whakaahuatanga: IC MCU 32BIT 768KB FLASH 100LQFP I roto i te taonga: 7530 pcs</p> <p>RFQ</p>	<p>R5F56519ADFP#30 Kaihanga: Renesas Electronics America Whakaahuatanga: IC MCU 32BIT 1MB FLASH 100LQFP I roto i te taonga: 8441 pcs</p> <p>RFQ</p>
<p>R5F56519ADFB#30 Kaihanga: Renesas Electronics America Whakaahuatanga: IC MCU 32BIT 1MB FLASH 144QFP I roto i te taonga: 8852 pcs</p> <p>RFQ</p>	<p>R5F56517BDLK#20 Kaihanga: Renesas Electronics America Whakaahuatanga: IC MCU 32BIT 768KB FLASH 145LGA I roto i te taonga: 11414 pcs</p> <p>RFQ</p>
<p>R5F56519ADLJ#20 Kaihanga: Renesas Electronics America Whakaahuatanga: IC MCU 32BIT 1MB FLASH 100LGA I roto i te taonga: 12140 pcs</p> <p>RFQ</p>	<p>R5F56514EDFP#30 Kaihanga: Renesas Electronics America Whakaahuatanga: IC MCU 32BIT 512KB FLASH 100LQFP I roto i te taonga: 5132 pcs</p> <p>RFQ</p>
<p>R5F56517ADLK#20 Kaihanga: Renesas Electronics America Whakaahuatanga: IC MCU 32BIT 768KB FLASH 145LGA I roto i te taonga: 10536 pcs</p> <p>RFQ</p>	<p>R5F56517BDLJ#20 Kaihanga: Renesas Electronics America Whakaahuatanga: IC MCU 32BIT 768KB FLASH 100LGA I roto i te taonga: 11947 pcs</p> <p>RFQ</p>
<p>R5F56514EDFB#30 Kaihanga: Renesas Electronics America Whakaahuatanga: IC MCU 32BIT 512KB FLASH 144LQFP I roto i te taonga: 3383 pcs</p> <p>RFQ</p>	<p>R5F56517ADFB#30 Kaihanga: Renesas Electronics America Whakaahuatanga: IC MCU 32BIT 768KB FLASH 144LQFP I roto i te taonga: 9854 pcs</p> <p>RFQ</p>

