






Leader Tech Inc.



59-CBSA-0.5X5.75X0.5

Tau Wae:	59-CBSA-0.5X5.75X0.5
Kaihanga / Waitohu:	Leader Tech Inc.
Whakaahuatanga hua	59 SERIES CBS SHIELD ASSEMBLY -  1.59-CBSA-0.5X5.75X0.5.pdf  2.59-CBSA-0.5X5.75X0.5.pdf
Ngā Rauemi:	 Whakahaerehia te kore utu / RoHS
RoHs Tūnga	3308 pcs stock
Waehe Stock	Hong Kong
Tuhinga mai i	DHL/Fedex/TNT/UPS/EMS
Te Ara Tuhi	

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.













Ngā whakaaturanga o 59-CBSA-0.5X5.75X0.5

TAU WAE	59-CBSA-0.5X5.75X0.5
KAIHANGA	Leader Tech Inc.
WHAKAAHUATANGA	59 SERIES CBS SHIELD ASSEMBLY -
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
HE RAHINGA KEI TE WĀTEA	3308 pcs
PEPA RARAUNGA	 1.59-CBSA-0.5X5.75X0.5.pdf  2.59-CBSA-0.5X5.75X0.5.pdf
WHĀNUI - WHĀNUI	0.500" (12.70mm)
TUHINGA O MUA	Vent Holes in Pattern
MOMO	Shield, 2-Piece
RAUPAPA	50-CBS
PACKAGING	Bulk
ĒTAHI INGOA	59-CBSA-0.5X5.75X0.4 59-CBSA-0.5X5.75X0.4-ND
MOMO TAE	Through Hole
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
TE ROA - WHĀNUI	5.750" (146.05mm)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
TEITEI - WHĀNUI	0.500" (12.70mm)
WHAKAAHUATANGA TAIPITOPITO	RF Shield Shield, 2-Piece 0.500" (12.70mm) X 5.750" (146.05mm) Vent Holes in Pattern Through Hole

Ngā tūtohu e hāngai ana

Leader Tech Inc. 59-CBSA-0.5X5.75X0.5	59-CBSA-0.5X5.75X0.5 Kaiwhiwhi	59-CBSA-0.5X5.75X0.5 Kaiwhakarato
59-CBSA-0.5X5.75X0.5 Utu	59-CBSA-0.5X5.75X0.5 Pikitia	59-CBSA-0.5X5.75X0.5 Whakaahua
59-CBSA-0.5X5.75X0.5 PDF Datasheet	59-CBSA-0.5X5.75X0.5 Download Datasheet	Tuhinga 59-CBSA-0.5X5.75X0.5
59-CBSA-0.5X5.75X0.5 Stock	Hokona 59-CBSA-0.5X5.75X0.5	Hokona Leader Tech Inc. 59-CBSA-0.5X5.75X0.5
Leader Tech Inc. 59-CBSA-0.5X5.75X0.5	Leader Tech Inc. Kaiwhakarato	Leader Tech Inc. Kaiwhiwhi
Leader Tech Inc. 59-CBSA-0.5X5.75X0.5		

Ngā Hua e hāngai ana

 <p>59-CBSA-0.5X6.0X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 59 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 3569 pcs</p> <p>RFQ</p>	 <p>59-CBSA-0.75X1.0X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 59 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 5141 pcs</p> <p>RFQ</p>
 <p>59-CBSA-0.75X1.25X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 59 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 6122 pcs</p> <p>RFQ</p>	 <p>59-CBSA-0.5X5.5X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 59 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 4249 pcs</p> <p>RFQ</p>
 <p>59-CBSA-0.5X4.5X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 59 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 4592 pcs</p> <p>RFQ</p>	 <p>59-CBSA-0.75X1.5X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 59 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 4858 pcs</p> <p>RFQ</p>
 <p>59-CBSA-0.5X4.75X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 59 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 4264 pcs</p> <p>RFQ</p>	 <p>59-CBSA-0.5X4.25X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 59 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 4795 pcs</p> <p>RFQ</p>
 <p>59-CBSA-0.75X1.75X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 59 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 4907 pcs</p> <p>RFQ</p>	 <p>59-CBSA-0.75X0.75X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 59 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 6105 pcs</p> <p>RFQ</p>
 <p>59-CBSA-0.5X5.25X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 59 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 4281 pcs</p> <p>RFQ</p>	 <p>59-CBSA-0.5X5.0X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 59 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 3830 pcs</p> <p>RFQ</p>