



TDK Corporation

DPX205950DT-9008A1

Tau Wae:	DPX205950DT-9008A1
Kaihanga / Waitohu:	TDK Corporation
Whakaahuatanga hua	RF DIPLEXER 2.4GHZ/5.425GHZ 0805
Ngā Rauemi:	DPX205950DT-9008A1.pdf
RoHS Tūnga	Whakahaerehia te kore utu / RoHS
Waeheere Stock	137411 pcs stock
Tuhinga mai i	Hong Kong
Te Ara Tuhi	DHL/Fedex/TNT/UPS/EMS

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o DPX205950DT-9008A1

TAU WAE	DPX205950DT-9008A1
KAIHANGA	TDK Corporation
WHAKAAHUATANGA	RF DIPLEXER 2.4GHZ/5.425GHZ 0805
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
HE RAHINGA KEI TE WĀTEA	137411 pcs
PEPA RARAUNGA	DPX205950DT-9008A1.pdf
RAUPAPA	DPX
KO TE HOKI HOKI (ROA RAWA / HAINA NUI)	20dB / 11dB
PACKAGING	Original-Reel®
PAA / CASE	0805 (2012 Metric), 6 PC Pad
ĒTAHI INGOA	445-3261-6
MOMO TAE	Surface Mount
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
TAE WHAKAMURI RAWA (MIN / MAX DB)	20.00dB / -
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
TAE WHAKATEITEI NUI (MIN / MAX DB)	20.00dB / -
NGĀ RŌPŪ TAEKE (RARO / TEITEI)	2.3GHz ~ 2.5GHz / 4.9GHz ~ 5.95GHz
WHAKAAHUATANGA TAIPITOPITO	RF Diplexor 2.3GHz ~ 2.5GHz / 4.9GHz ~ 5.95GHz 0805 (2012 Metric), 6 PC Pad

Ngā tūtohu e hāngai ana

TDK Corporation DPX205950DT-9008A1	DPX205950DT-9008A1 Kaihiwhi	DPX205950DT-9008A1 Kaiwhakarato
DPX205950DT-9008A1 Utu	DPX205950DT-9008A1 Pikitia	DPX205950DT-9008A1 Whakaahua
DPX205950DT-9008A1 PDF Datasheet	DPX205950DT-9008A1 Download Datasheet	Tuhinga DPX205950DT-9008A1
DPX205950DT-9008A1 Stock	Hokona DPX205950DT-9008A1	Hokona TDK Corporation DPX205950DT-9008A1
TDK Corporation DPX205950DT-9008A1	TDK Corporation Kaiwhakarato	TDK Corporation Kaihiwhi
TDK Corporation DPX205950DT-9008A1		

Ngā Hua e hāngai ana

<p>DPX252690DT-5021B1 Kaihanga: TDK Corporation Whakaahuatanga: RF DIPLEXER 829MHZ/2.2GHZ 1008 I roto i te taonga: 259224 pcs</p> <p>RFQ</p>	<p>DPX252500DT-5217A1 Kaihanga: TDK Corporation Whakaahuatanga: RF DIPLEXER 1.575/2.45GHZ 1008 I roto i te taonga: 81828 pcs</p> <p>RFQ</p>
<p>DPX205850DT-4052B2 Kaihanga: TDK Corporation Whakaahuatanga: RF DIPLEXER 0805 6 PC PAD I roto i te taonga: 106367 pcs</p> <p>RFQ</p>	<p>DPX250894DT-5025A1 Kaihanga: TDK Corporation Whakaahuatanga: RF DIPLEXER 1008 8 PC PAD I roto i te taonga: 101175 pcs</p> <p>RFQ</p>
<p>DPX205850DT-4154B1 Kaihanga: TDK Corporation Whakaahuatanga: RF DIPLEXER 0805 6 PC PAD I roto i te taonga: 273114 pcs</p> <p>RFQ</p>	<p>DPX205950DT-9026A1 Kaihanga: TDK Corporation Whakaahuatanga: RF DIPLEXER 2.45/5.425GHZ 0805 I roto i te taonga: 117814 pcs</p> <p>RFQ</p>
<p>DPX205950DT-9108A1 Kaihanga: TDK Corporation Whakaahuatanga: RF DIPLEXER 2.4GHZ/5.425GHZ 0805 I roto i te taonga: 246533 pcs</p> <p>RFQ</p>	<p>DPX205850DT-4055A1 Kaihanga: TDK Corporation Whakaahuatanga: RF DIPLEXER 1345M/4.125GHZ 0805 I roto i te taonga: 236414 pcs</p> <p>RFQ</p>
<p>DPX205850DT-4152B2 Kaihanga: TDK Corporation Whakaahuatanga: RF DIPLEXER 877MHZ/4.125GHZ 0805 I roto i te taonga: 256614 pcs</p> <p>RFQ</p>	<p>DPX205850DT-4155A1 Kaihanga: TDK Corporation Whakaahuatanga: RF DIPLEXER 1345M/4.125GHZ 0805 I roto i te taonga: 309240 pcs</p> <p>RFQ</p>
<p>DPX205950DT-9126A1 Kaihanga: TDK Corporation Whakaahuatanga: RF DIPLEXER 2.45/5.425GHZ 0805 I roto i te taonga: 245163 pcs</p> <p>RFQ</p>	<p>DPX205850DT-9038A1-H Kaihanga: TDK Corporation Whakaahuatanga: RF DIPLEXER 2.45GHZ/5.5GHZ 0805 I roto i te taonga: 262057 pcs</p> <p>RFQ</p>

