



40-CBSAD-1.5X1.5X0.4

Tau Wae:	40-CBSAD-1.5X1.5X0.4
Kaihanga / Waitohu:	Leader Tech Inc.
Whakaahuatanga hua	40-CBSAD-1.5X1.5X0.4--40S35--CIR
Ngā Rauemi:	40-CBSAD-1.5X1.5X0.4.pdf
Waehere Stock	6552 pcs stock
Tuhinga mai i	Hong Kong
Te Ara Tuhi	DHL/Fedex/TNT/UPS/EMS

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o 40-CBSAD-1.5X1.5X0.4

TAU WAE	40-CBSAD-1.5X1.5X0.4
KAIHANGA	Leader Tech Inc.
WHAKAAHUATANGA	40-CBSAD-1.5X1.5X0.4--40S35--CIR
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	
HE RAHINGA KEI TE WĀTEA	6552 pcs
PEPA RARAUNGA	40-CBSAD-1.5X1.5X0.4.pdf
WHĀNUI - WHĀNUI	1.500" (38.10mm)
TUHINGA O MUA	Vent Holes in Pattern
MOMO	Shield, 2-Piece
RAUPAPA	40-CBS
MOMO TAE	Surface Mount
TE ROA - WHĀNUI	1.500" (38.10mm)
TEITEI - WHĀNUI	0.400" (10.16mm)
WHAKAAHUATANGA TAIPITOPITO	RF Shield Shield, 2-Piece 1.500" (38.10mm) X 1.500" (38.10mm) Vent Holes in Pattern Surface Mount

Ngā tūtohu e hāngai ana

Leader Tech Inc. 40-CBSAD-1.5X1.5X0.4	40-CBSAD-1.5X1.5X0.4 Kaiwhiwhi	40-CBSAD-1.5X1.5X0.4 Kaiwhakarato
40-CBSAD-1.5X1.5X0.4 Utu	40-CBSAD-1.5X1.5X0.4 Pikitia	40-CBSAD-1.5X1.5X0.4 Whakaahua
40-CBSAD-1.5X1.5X0.4 PDF Datasheet	40-CBSAD-1.5X1.5X0.4 Download Datasheet	Tuhinga 40-CBSAD-1.5X1.5X0.4
40-CBSAD-1.5X1.5X0.4 Stock	Hokona 40-CBSAD-1.5X1.5X0.4	Hokona Leader Tech Inc. 40-CBSAD-1.5X1.5X0.4
Leader Tech Inc. 40-CBSAD-1.5X1.5X0.4	Leader Tech Inc. Kaiwhakarato	Leader Tech Inc. Kaiwhiwhi
Leader Tech Inc. 40-CBSAD-1.5X1.5X0.4		

Ngā Hua e hāngai ana

<p>40-CBSF-1.0X1.5X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 40-CBSF-1.0X1.5X0.4--40S03--CIRC I roto i te taonga: 5730 pcs</p> <p>RFQ</p>	<p>40-CBSAD-1.0X1.5X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 40-CBSAD-1.0X1.5X0.4--40S36--CIR I roto i te taonga: 7619 pcs</p> <p>RFQ</p>
<p>40-CBSFND-0.75X0.75X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 40-CBSFND-0.75X0.75X0.4--40S38-- I roto i te taonga: 3151 pcs</p> <p>RFQ</p>	<p>40-CBSA-5.75X6.0X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 40 SERIES CBS SHIELD ASSEMBLY I roto i te taonga: 2986 pcs</p> <p>RFQ</p>
<p>40-CBSFN-1.75X4.0X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 40-CBSFN-1.75X4.0X0.5--40S42--CI I roto i te taonga: 3418 pcs</p> <p>RFQ</p>	<p>40-CBSFN-3.5X4.75X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 40-CBSFN-3.5X4.75X0.40--40S37--C I roto i te taonga: 3219 pcs</p> <p>RFQ</p>
<p>40-CBSF-0.5X1.0X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 40-CBSF-0.5X1.0X0.4--40S44--CIRC I roto i te taonga: 8485 pcs</p> <p>RFQ</p>	<p>40-CBSADSV-1.25X1.75X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 40-CBSADSV-1.25X1.75X0.4--40S23- I roto i te taonga: 3456 pcs</p> <p>RFQ</p>
<p>40-CBSA-5.5X6.0X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 40 SERIES CBS SHIELD ASSEMBLY I roto i te taonga: 3778 pcs</p> <p>RFQ</p>	<p>40-CBSA-5.75X5.75X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 40 SERIES CBS SHIELD ASSEMBLY I roto i te taonga: 2695 pcs</p> <p>RFQ</p>
<p>40-CBSA-6.0X6.0X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 40 SERIES CBS SHIELD ASSEMBLY I roto i te taonga: 3262 pcs</p> <p>RFQ</p>	<p>40-CBSA-5.5X5.75X0.4 Kaihanga: Leader Tech Inc. Whakaahuatanga: 40 SERIES CBS SHIELD ASSEMBLY I roto i te taonga: 3526 pcs</p> <p>RFQ</p>