



51-CBSA-2.0X4.75X0.5

Tau Wae:	51-CBSA-2.0X4.75X0.5
Kaihanga / Waitohu:	Leader Tech Inc.
Whakaahuatanga hua	51 SERIES CBS SHIELD ASSEMBLY -
Ngā Rauemi:	51-CBSA-2.0X4.75X0.5.pdf
RoHS Tūnga	Whakahaerehia te kore utu / RoHS
Waehe Stock	4514 pcs stock
Tuhinga mai i	Hong Kong
Te Ara Tuhi	DHL/Fedex/TNT/UPS/EMS

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o 51-CBSA-2.0X4.75X0.5

TAU WAE	51-CBSA-2.0X4.75X0.5
KAIHANGA	Leader Tech Inc.
WHAKAAHUATANGA	51 SERIES CBS SHIELD ASSEMBLY -
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
HE RAHINGA KEI TE WĀTEA	4514 pcs
PEPA RARAUNGA	51-CBSA-2.0X4.75X0.5.pdf
WHĀNUI - WHĀNUI	2.000" (50.80mm)
TUHINGA O MUA	Vent Holes in Pattern
MOMO	Shield, 2-Piece
RAUPAPA	50-CBS
PACKAGING	Bulk
ĒTAHI INGOA	51-CBSA-2.0X4.75X0.4 51-CBSA-2.0X4.75X0.4-ND
MOMO TAE	Through Hole
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
TE ROA - WHĀNUI	4.750" (120.65mm)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
TEITEI - WHĀNUI	0.500" (12.70mm)
WHAKAAHUATANGA TAIPITOPITO	RF Shield Shield, 2-Piece 2.000" (50.80mm) X 4.750" (120.65mm) Vent Holes in Pattern Through Hole

Ngā tūtohu e hāngai ana

Leader Tech Inc. 51-CBSA-2.0X4.75X0.5	51-CBSA-2.0X4.75X0.5 Kaiwhiwhi	51-CBSA-2.0X4.75X0.5 Kaiwhakarato
51-CBSA-2.0X4.75X0.5 Utu	51-CBSA-2.0X4.75X0.5 Pikitia	51-CBSA-2.0X4.75X0.5 Whakaahua
51-CBSA-2.0X4.75X0.5 PDF Datasheet	51-CBSA-2.0X4.75X0.5 Download Datasheet	Tuhinga 51-CBSA-2.0X4.75X0.5
51-CBSA-2.0X4.75X0.5 Stock	Hokona 51-CBSA-2.0X4.75X0.5	Hokona Leader Tech Inc. 51-CBSA-2.0X4.75X0.5
Leader Tech Inc. 51-CBSA-2.0X4.75X0.5	Leader Tech Inc. Kaiwhakarato	Leader Tech Inc. Kaiwhiwhi
Leader Tech Inc. 51-CBSA-2.0X4.75X0.5		

Ngā Hua e hāngai ana

<p>51-CBSA-2.0X5.0X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 51 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 4232 pcs</p> <p>RFQ</p>	<p>51-CBSA-2.0X3.25X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 51 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 4829 pcs</p> <p>RFQ</p>
<p>51-CBSA-2.0X6.0X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 51 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 3690 pcs</p> <p>RFQ</p>	<p>51-CBSA-2.0X4.0X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 51 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 4665 pcs</p> <p>RFQ</p>
<p>51-CBSA-2.0X5.75X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 51 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 4160 pcs</p> <p>RFQ</p>	<p>51-CBSA-2.0X3.5X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 51 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 4197 pcs</p> <p>RFQ</p>
<p>51-CBSA-2.0X4.5X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 51 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 4195 pcs</p> <p>RFQ</p>	<p>51-CBSA-2.0X5.25X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 51 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 4016 pcs</p> <p>RFQ</p>
<p>51-CBSA-2.0X4.25X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 51 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 3673 pcs</p> <p>RFQ</p>	<p>51-CBSA-2.0X3.75X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 51 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 3835 pcs</p> <p>RFQ</p>
<p>51-CBSA-2.0X5.5X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 51 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 3951 pcs</p> <p>RFQ</p>	<p>51-CBSA-2.25X2.25X0.5 Kaihanga: Leader Tech Inc. Whakaahuatanga: 51 SERIES CBS SHIELD ASSEMBLY - I roto i te taonga: 5046 pcs</p> <p>RFQ</p>