



ADI (Analog Devices, Inc.)

ADCLK954BCPZ

Tau Wae:

ADCLK954BCPZ

Kaihanga / Waitohu:

ADI (Analog Devices, Inc.)

Whakaahuatanga hua

IC CLK BUF 2:12 4.8GHZ 40LFCSP

Ngā Rauemi:

ADCLK954BCPZ.pdf

RoHS Tūnga

Whakahaerehia te kore utu / RoHS

Waehere Stock

6873 pcs stock

Tuhinga mai i

Hong Kong

Te Ara Tuhi

DHL/Fedex/TNT/UPS/EMS



TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o ADCLK954BCPZ

TAU WAE	ADCLK954BCPZ
KAIHANGA	ADI (Analog Devices, Inc.)
WHAKAAHUATANGA	IC CLK BUF 2:12 4.8GHZ 40LFCSP
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
HE RAHINGA KEI TE WĀTEA	6873 pcs
PEPA RARAUNGA	ADCLK954BCPZ.pdf
TUHINGA O MUA	2.97 V ~ 3.63 V
MOMO	Fanout Buffer (Distribution), Multiplexer
PŪRERE PŪRERE WHAKARATO	40-LFCSP-VQ (6x6)
RAUPAPA	SiGe
RATONGA - WHAKAURU: WHAKAPUTA	2:12
PACKAGING	Tray
PAA / CASE	40-VFQFN Exposed Pad, CSP
WHAKAPUTA	LVPECL
TAE MAHI	-40°C ~ 85°C
TUHINGA O MUA	1
MOMO TAE	Surface Mount
TAUMATA WHAKAARO MOE (MSL)	3 (168 Hours)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
WHAKAURU	CMOS, LVDS, LVPECL
TAUTANGA - MAX	4.8GHz
MOTUHAKE - WHAKAURU: WHAKAPUTA	Yes/Yes
WHAKAAHUATANGA TAIPITOPITO	Clock Fanout Buffer (Distribution), Multiplexer IC 2:12 4.8GHz 40-VFQFN Exposed Pad, CSP
TAU WAE TUAKIRI	ADCLK954

Ngā tūtohu e hāngai ana

ADI (Analog Devices, Inc.) ADCLK954BCPZ	ADCLK954BCPZ Kaihiwhi	ADCLK954BCPZ Kaiwhakarato
ADCLK954BCPZ Utu	ADCLK954BCPZ Pikitia	ADCLK954BCPZ Whakaahua
ADCLK954BCPZ PDF Datasheet	ADCLK954BCPZ Download Datasheet	Tuhinga ADCLK954BCPZ
ADCLK954BCPZ Stock	Hokona ADCLK954BCPZ	Hokona ADI (Analog Devices, Inc.) ADCLK954BCPZ
ADI (Analog Devices, Inc.) ADCLK954BCPZ	ADI (Analog Devices, Inc.) Kaiwhakarato	ADI (Analog Devices, Inc.) Kaihiwhi
ADI (Analog Devices, Inc.) ADCLK954BCPZ	AD ADCLK954BCPZ	ADI (Analog Devices, Inc.) ADCLK954BCPZ
Analog Devices Inc. ADCLK954BCPZ	Analog Devices, Inc. ADCLK954BCPZ	

Ngā Hua e hāngai ana

<p>ADCMP350YKS-REEL7 Kaihanga: ADI (Analog Devices, Inc.) Whakaahuatanga: IC COMP/REF OD ACTIVE LOW SC70-4 I roto i te taonga: 3467 pcs</p> <p>RFQ</p>	<p>ADCMP354YKS-REEL7 Kaihanga: ADI (Analog Devices, Inc.) Whakaahuatanga: IC COMP/REF OD ACTIVE HI SC70-4 I roto i te taonga: 5334 pcs</p> <p>RFQ</p>
<p>ADCLK954BCPZ-REEL7 Kaihanga: ADI (Analog Devices, Inc.) Whakaahuatanga: IC CLK BUF 2:12 4.8GHZ 40LFCSP I roto i te taonga: 9372 pcs</p> <p>RFQ</p>	<p>ADCMP350YKSZ-REEL7 Kaihanga: ADI (Analog Devices, Inc.) Whakaahuatanga: IC COMP/REF OD ACTIVE LOW SC70-4 I roto i te taonga: 226920 pcs</p> <p>RFQ</p>
<p>ADCMP341YRZJ-REEL7 Kaihanga: ADI (Analog Devices, Inc.) Whakaahuatanga: IC COMP/REF OD ACTIVE HI SC70-4 I roto i te taonga: 33035 pcs</p> <p>RFQ</p>	<p>ADCLK950/PCBZ Kaihanga: ADI (Analog Devices, Inc.) Whakaahuatanga: BOARD EVALUATION FOR ADCLK950 I roto i te taonga: 433 pcs</p> <p>RFQ</p>
<p>ADCLK948BCPZ Kaihanga: ADI (Analog Devices, Inc.) Whakaahuatanga: IC CLK BUFFER 2:8 4.8GHZ 32LFCSP I roto i te taonga: 8286 pcs</p> <p>RFQ</p>	<p>ADCLK950BCPZ-REEL7 Kaihanga: ADI (Analog Devices, Inc.) Whakaahuatanga: IC CLK BUF 2:10 4.8GHZ 40LFCSP I roto i te taonga: 12403 pcs</p> <p>RFQ</p>
<p>ADCLK954/PCBZ Kaihanga: ADI (Analog Devices, Inc.) Whakaahuatanga: KIT EVAL CLK BUFF ADCLK954 I roto i te taonga: 494 pcs</p> <p>RFQ</p>	<p>ADCMP343YRZJ-REEL7 Kaihanga: ADI (Analog Devices, Inc.) Whakaahuatanga: IC COMP/REF OD ACTIVE HI SC70-4 I roto i te taonga: 78209 pcs</p> <p>RFQ</p>
<p>ADCLK948BCPZ-REEL7 Kaihanga: ADI (Analog Devices, Inc.) Whakaahuatanga: IC CLK BUFFER 2:8 4.8GHZ 32LFCSP I roto i te taonga: 15954 pcs</p> <p>RFQ</p>	<p>ADCLK950BCPZ Kaihanga: ADI (Analog Devices, Inc.) Whakaahuatanga: IC CLK BUF 2:10 4.8GHZ 40LFCSP I roto i te taonga: 7912 pcs</p> <p>RFQ</p>

