



TDK Corporation

HHM1763B2

Tau Wae:

HHM1763B2

Kaihanga / Waitohu:

TDK Corporation

Whakaahuatanga hua

BALUN 880MHZ-960MHZ 50/150 0603

Ngā Rauemi:

[HHM1763B2.pdf](#)

RoHS Tūnga

Whakahaerehia te kore utu / RoHS

Waehere Stock

72443 pcs stock

Tuhinga mai i

Hong Kong

Te Ara Tuhi

DHL/Fedex/TNT/UPS/EMS

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o HHM1763B2

TAU WAE	HHM1763B2
KAIHANGA	TDK Corporation
WHAKAAHUATANGA	BALUN 880MHZ-960MHZ 50/150 0603
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
HE RAHINGA KEI TE WĀTEA	72443 pcs
PEPA RARAUNGA	HHM1763B2.pdf
RAUPAPA	HHM
HOKI HOKI (MIN)	10dB
RAWEHANGA PUTANGA	180° ±10°
PACKAGING	Cut Tape (CT)
PAA / CASE	0603 (1608 Metric)
ĒTAHI INGOA	445-6867-1
MOMO TAE	Surface Mount
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
KO TE WHAKAKORE I TE MAHINGA (MAX)	1.4dB
HAAPAPA - NGA HAUARO / WHAKATIKA	50 / 150 Ohm
MAHINGA RAWE	880MHz ~ 960MHz
WHAKAAHUATANGA TAIPITOPITO	RF Balun 880MHz ~ 960MHz 50 / 150 Ohm 0603 (1608 Metric)

Ngā tūtohu e hāngai ana

TDK Corporation HHM1763B2	HHM1763B2 Kaiwhiwhi	HHM1763B2 Kaiwhakarato
HHM1763B2 Utu	HHM1763B2 Pikitia	HHM1763B2 Whakaahua
HHM1763B2 PDF Datasheet	HHM1763B2 Download Datasheet	Tuhinga HHM1763B2
HHM1763B2 Stock	Hokona HHM1763B2	Hokona TDK Corporation HHM1763B2
TDK Corporation HHM1763B2	TDK Corporation Kaiwhakarato	TDK Corporation Kaiwhiwhi
TDK Corporation HHM1763B2		

Ngā Hua e hāngai ana

<p>HHM1727D1 Kaihanga: TDK Corporation Whakaahuatanga: BALUN 3.3GHZ-3.9GHZ 50/50 0603 I roto i te taonga: 238503 pcs</p> <p>RFQ</p>	<p>HHM1791A1 Kaihanga: TDK Corporation Whakaahuatanga: BALUN 2.5GHZ-2.7GHZ 50/100 0603 I roto i te taonga: 455498 pcs</p> <p>RFQ</p>
<p>HHM1776B2 Kaihanga: TDK Corporation Whakaahuatanga: BALUN 824MHZ-894MHZ 50/50 0603 I roto i te taonga: 57084 pcs</p> <p>RFQ</p>	<p>HHM1902A1 Kaihanga: TDK Corporation Whakaahuatanga: BALUN 2.4GHZ-2.5GHZ 50/50 0402 I roto i te taonga: 189528 pcs</p> <p>RFQ</p>
<p>HHM1749S1 Kaihanga: TDK Corporation Whakaahuatanga: BALUN 1.71-1.99GHZ 50/100 0603 I roto i te taonga: 800377 pcs</p> <p>RFQ</p>	<p>HHM1733B1 Kaihanga: TDK Corporation Whakaahuatanga: BALUN 4.9GHZ-5.95GHZ 50/50 0603 I roto i te taonga: 144005 pcs</p> <p>RFQ</p>
<p>HHM1732B1 Kaihanga: TDK Corporation Whakaahuatanga: BALUN 4.9GHZ-5.95GHZ 50/100 0603 I roto i te taonga: 273182 pcs</p> <p>RFQ</p>	<p>HHM1731F1 Kaihanga: TDK Corporation Whakaahuatanga: BALUN 1.71-1.88GHZ 50/200 0603 I roto i te taonga: 821085 pcs</p> <p>RFQ</p>
<p>HHM1775D1 Kaihanga: TDK Corporation Whakaahuatanga: BALUN 3.1GHZ-4.9GHZ 50/100 0805 I roto i te taonga: 261546 pcs</p> <p>RFQ</p>	<p>HHM1776B3 Kaihanga: TDK Corporation Whakaahuatanga: BALUN 880MHZ-960MHZ 50/50 0603 I roto i te taonga: 188262 pcs</p> <p>RFQ</p>
<p>HHM1779B1 Kaihanga: TDK Corporation Whakaahuatanga: BALUN 2.11-2.17GHZ 50/100 0603 I roto i te taonga: 261529 pcs</p> <p>RFQ</p>	<p>HHM1752A2 Kaihanga: TDK Corporation Whakaahuatanga: BALUN 4.9GHZ-5.95GHZ 50/200 0603 I roto i te taonga: 115644 pcs</p> <p>RFQ</p>