

N/A

DGS35-3LN01024

Tau Wae:	DGS35-3LN01024
Kaihanga / Waitohu:	N/A
Whakaahuatanga hua	ROTARY ENCODR INCREMENT 1024PPR
Ngā Rauemi:	
Waehere Stock	190 pcs stock
Tuhinga mai i	Hong Kong
Te Ara Tuhi	DHL/Fedex/TNT/UPS/EMS

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o DGS35-3LN01024

TAU WAE	DGS35-3LN01024
KAIHANGA	N/A
WHAKAAHUATANGA	ROTARY ENCODR INCREMENT 1024PPR
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	
HE RAHINGA KEI TE WĀTEA	190 pcs
PEPA RARAUNGA	
TUHINGA O MUA	8 V ~ 24 V
KĀHUA WHAKAMUTUNGA	Cable
RAUPAPA	-
KO TE ROTATIONAL LIFE (CYCLES MIN)	-
PULSES IA REVOLUTION	1024
MOMO PUTANGA	-
ĒTAHI INGOA	1057443
WHAKATAKOTORANGA	User Selectable
MOMO TAE	Chassis Mount
MOMO KUPUTUHI	Incremental
TUHINGA	No
HANGAIA KI TE WHAKAWHITI	No
MOMO KAIHOKO	Hole for Shaft

Ngā tūtohu e hāngai ana

DGS35-3LN01024	DGS35-3LN01024 Kaihiwhi	DGS35-3LN01024 Kaiwhakarato
DGS35-3LN01024 Utu	DGS35-3LN01024 Pikitia	DGS35-3LN01024 Whakaahua
DGS35-3LN01024 PDF Datasheet	DGS35-3LN01024 Download Datasheet	Tuhinga DGS35-3LN01024
DGS35-3LN01024 Stock	Hokona DGS35-3LN01024	Hokona DGS35-3LN01024
DGS35-3LN01024	Kaiwhakarato	Kaihiwhi

Ngā Hua e hāngai ana

	<p>DGS35-3LL01024</p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 1024PPR I roto i te taonga: 183 pcs</p> <p>RFQ</p>		<p>DGS35-3LL05000</p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 5000PPR I roto i te taonga: 219 pcs</p> <p>RFQ</p>
	<p>DGS35-3LK02048</p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 2048PPR I roto i te taonga: 207 pcs</p> <p>RFQ</p>		<p>DGS35-4H402500</p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 2500PPR I roto i te taonga: 229 pcs</p> <p>RFQ</p>
	<p>DGS35-3L405000</p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 5000PPR I roto i te taonga: 185 pcs</p> <p>RFQ</p>		<p>DGS35-4H401024</p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 1024PPR I roto i te taonga: 247 pcs</p> <p>RFQ</p>
	<p>DGS35-4H210000</p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 10000PPR I roto i te taonga: 196 pcs</p> <p>RFQ</p>		<p>DGS35-3L404096</p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 4096PPR I roto i te taonga: 217 pcs</p> <p>RFQ</p>
	<p>DGS35-4HK16384</p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 16384PPR I roto i te taonga: 189 pcs</p> <p>RFQ</p>		<p>DGS35-4H402048</p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 2048PPR I roto i te taonga: 228 pcs</p> <p>RFQ</p>
	<p>DGS35-4H404096</p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 4096PPR I roto i te taonga: 189 pcs</p> <p>RFQ</p>		<p>DGS35-3L402048</p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 2048PPR I roto i te taonga: 215 pcs</p> <p>RFQ</p>

