

N/A

### DGS35-YHN10000

Tau Wae:	DGS35-YHN10000
Kaihanga / Waitohu:	N/A
Whakaahuatanga hua	ROTARY ENCODR INCREMENT 10000PPR
Ngā Rauemi:	
Waehere Stock	180 pcs stock
Tuhinga mai i	Hong Kong
Te Ara Tuhi	DHL/Fedex/TNT/UPS/EMS

**TONO MO TE WHAKAHUA**

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

#### Ngā whakaaturanga o DGS35-YHN10000

TAU WAE	DGS35-YHN10000
KAIHANGA	N/A
WHAKAAHUATANGA	ROTARY ENCODR INCREMENT 10000PPR
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	
HE RAHINGA KEI TE WĀTEA	180 pcs
PEPA RARAUNGA	
TUHINGA O MUA	5V
KĀHUA WHAKAMUTUNGA	Cable
RAUPAPA	-
KO TE ROTATIONAL LIFE (CYCLES MIN)	-
PULSES IA REVOLUTION	10000
MOMO PUTANGA	-
ĒTAHI INGOA	1056872
WHAKATAKOTORANGA	User Selectable
MOMO TAE	Chassis Mount
MOMO KUPUTUHI	Incremental
TUHINGA	No
HANGAIA KI TE WHAKAWHITI	No
MOMO KAIHOKO	Hole for Shaft

#### Ngā tūtohu e hāngai ana

DGS35-YHN10000	DGS35-YHN10000 Kaiwhiwhi	DGS35-YHN10000 Kaiwhakarato
DGS35-YHN10000 Utu	DGS35-YHN10000 Pikitia	DGS35-YHN10000 Whakaahua
DGS35-YHN10000 PDF Datasheet	DGS35-YHN10000 Download Datasheet	Tuhinga DGS35-YHN10000
DGS35-YHN10000 Stock	Hokona DGS35-YHN10000	Hokona DGS35-YHN10000
DGS35-YHN10000	Kaiwhakarato	Kaiwhiwhi

#### Ngā Hua e hāngai ana

	<p><b>DGS35-YHK02500</b></p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 2500PPR I roto i te taonga: 196 pcs</p> <p><b>RFQ</b></p>		<p><b>DGS35-LLK02048</b></p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 2048PPR I roto i te taonga: 181 pcs</p> <p><b>RFQ</b></p>
	<p><b>DGS35-YKK02048</b></p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 2048PPR I roto i te taonga: 175 pcs</p> <p><b>RFQ</b></p>		<p><b>DGS35-YKK16384</b></p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 16384PPR I roto i te taonga: 150 pcs</p> <p><b>RFQ</b></p>
	<p><b>DGS35-LLK03600</b></p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 3600PPR I roto i te taonga: 209 pcs</p> <p><b>RFQ</b></p>		<p><b>DGS35-YH208192</b></p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 8192PPR I roto i te taonga: 194 pcs</p> <p><b>RFQ</b></p>
	<p><b>DGS35-YK410000</b></p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 10000PPR I roto i te taonga: 177 pcs</p> <p><b>RFQ</b></p>		<p><b>DGS35-YHK05000</b></p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 5000PPR I roto i te taonga: 225 pcs</p> <p><b>RFQ</b></p>
	<p><b>DGS35-YH401024</b></p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 1024PPR I roto i te taonga: 249 pcs</p> <p><b>RFQ</b></p>		<p><b>DGS35-YK216384</b></p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 16384PPR I roto i te taonga: 165 pcs</p> <p><b>RFQ</b></p>
	<p><b>DGS35-YK201024</b></p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 1024PPR I roto i te taonga: 181 pcs</p> <p><b>RFQ</b></p>		<p><b>DGS35-YK402048</b></p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 2048PPR I roto i te taonga: 200 pcs</p> <p><b>RFQ</b></p>