

BOURNS®	Bourns, Inc.
----------------	---------------------



PEC09-2115K-S0012

Tau Wae:	PEC09-2115K-S0012
Kaihanga / Waitohu:	Bourns, Inc.
Whakaahuatanga hua	ROTARY ENCODER MECHANICAL 12PPR
Ngā Rauemi:	PEC09-2115K-S0012.pdf
RoHS Tūnga	Whakahaerehia te kore utu / RoHS
Waehere Stock	49845 pcs stock
Tuhinga mai i	Hong Kong
Te Ara Tuhi	DHL/Fedex/TNT/UPS/EMS

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o PEC09-2115K-S0012

TAU WAE	PEC09-2115K-S0012
KAIHANGA	Bourns, Inc.
WHAKAAHUATANGA	ROTARY ENCODER MECHANICAL 12PPR
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
HE RAHINGA KEI TE WĀTEA	49845 pcs
PEPA RARAUNGA	PEC09-2115K-S0012.pdf
TUHINGA O MUA	-
KĀHUA WHAKAMUTUNGA	PC Pin
RAUPAPA	PEC09
KO TE ROTATIONAL LIFE (CYCLES MIN)	30K
PULSES IA REVOLUTION	12
MOMO PUTANGA	Quadrature (Incremental)
WHAKATAKOTORANGA	Right Angle
MOMO TAE	Panel, PCB Through Hole
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
MOMO KUPUTUHI	Mechanical
TUHINGA	Yes
HANGAIA KI TE WHAKAWHITI	Yes
MOMO KAIHOKO	6mm Dia Knurled End

Ngā tūtohu e hāngai ana

Bourns, Inc. PEC09-2115K-S0012	PEC09-2115K-S0012 Kaiwhiwhi	PEC09-2115K-S0012 Kaiwhakarato
PEC09-2115K-S0012 Utu	PEC09-2115K-S0012 Pikitia	PEC09-2115K-S0012 Whakaahua
PEC09-2115K-S0012 PDF Datasheet	PEC09-2115K-S0012 Download Datasheet	Tuhinga PEC09-2115K-S0012
PEC09-2115K-S0012 Stock	Hokona PEC09-2115K-S0012	Hokona Bourns, Inc. PEC09-2115K-S0012
Bourns, Inc. PEC09-2115K-S0012	Bourns, Inc. Kaiwhakarato	Bourns, Inc. Kaiwhiwhi
Bourns, Inc. PEC09-2115K-S0012	Bourns Inc. PEC09-2115K-S0012	J.W. Miller / Bourns PEC09-2115K-S0012

Ngā Hua e hāngai ana

<p>PEC09-2015K-N0015 Kaihanga: Bourns, Inc. Whakaahuatanga: ROTARY ENCODER I roto i te taonga: 83743 pcs</p> <p>RFQ</p>	<p>PEC09-2020F-S0015 Kaihanga: Bourns, Inc. Whakaahuatanga: ROTARY ENCODER MECHANICAL 15PPR I roto i te taonga: 45548 pcs</p> <p>RFQ</p>
<p>PEC09-2115F-S0012 Kaihanga: Bourns, Inc. Whakaahuatanga: ROTARY ENCODER I roto i te taonga: 53675 pcs</p> <p>RFQ</p>	<p>PEC09-2025K-N0015 Kaihanga: Bourns, Inc. Whakaahuatanga: ROTARY ENCODER MECHANICAL 15PPR I roto i te taonga: 89921 pcs</p> <p>RFQ</p>
<p>PEC09-2115K-N0012 Kaihanga: Bourns, Inc. Whakaahuatanga: ROTARY ENCODER MECHANICAL 12PPR I roto i te taonga: 80944 pcs</p> <p>RFQ</p>	<p>PEC09-2120K-T0012 Kaihanga: Bourns, Inc. Whakaahuatanga: ROTARY ENCODER MECHANICAL 12PPR I roto i te taonga: 50849 pcs</p> <p>RFQ</p>
<p>PEC09-2215F-N0012 Kaihanga: Bourns, Inc. Whakaahuatanga: ROTARY ENCODER MECHANICAL 12PPR I roto i te taonga: 60350 pcs</p> <p>RFQ</p>	<p>PEC09-2120K-S0012 Kaihanga: Bourns, Inc. Whakaahuatanga: ROTARY ENCODER I roto i te taonga: 50570 pcs</p> <p>RFQ</p>
<p>PEC09-2025F-N0015 Kaihanga: Bourns, Inc. Whakaahuatanga: ROTARY ENCODER MECHANICAL 15PPR I roto i te taonga: 74593 pcs</p> <p>RFQ</p>	<p>PEC09-2215F-T0012 Kaihanga: Bourns, Inc. Whakaahuatanga: ROTARY ENCODER MECHANICAL 12PPR I roto i te taonga: 57222 pcs</p> <p>RFQ</p>
<p>PEC09-2120F-S0012 Kaihanga: Bourns, Inc. Whakaahuatanga: ROTARY ENCODER MECHANICAL 12PPR I roto i te taonga: 32171 pcs</p> <p>RFQ</p>	<p>PEC09-2125K-N0012 Kaihanga: Bourns, Inc. Whakaahuatanga: ROTARY ENCODER MECHANICAL 12PPR I roto i te taonga: 75285 pcs</p> <p>RFQ</p>