

N/A

DGS35-4L201024

Tau Wae:	DGS35-4L201024
Kaihanga / Waitohu:	N/A
Whakaahuatanga hua	ROTARY ENCODR INCREMENT 1024PPR
Ngā Rauemi:	
Waehere Stock	199 pcs stock
Tuhinga mai i	Hong Kong
Te Ara Tuhi	DHL/Fedex/TNT/UPS/EMS

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o DGS35-4L201024

TAU WAE	DGS35-4L201024
KAIHANGA	N/A
WHAKAAHUATANGA	ROTARY ENCODR INCREMENT 1024PPR
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	
HE RAHINGA KEI TE WĀTEA	199 pcs
PEPA RARAUNGA	
TUHINGA O MUA	8 V ~ 24 V
KĀHUA WHAKAMUTUNGA	Cable
RAUPAPA	-
KO TE ROTATIONAL LIFE (CYCLES MIN)	-
PULSES IA REVOLUTION	1024
MOMO PUTANGA	-
ĒTAHI INGOA	1083320
WHAKATAKOTORANGA	User Selectable
MOMO TAE	Chassis Mount
MOMO KUPUTUHI	Incremental
TUHINGA	No
HANGAIA KI TE WHAKAWHITI	No
MOMO KAIHOKO	Hole for Shaft

Ngā tūtohu e hāngai ana

DGS35-4L201024	DGS35-4L201024 Kaiwhiwhi	DGS35-4L201024 Kaiwhakarato
DGS35-4L201024 Utu	DGS35-4L201024 Pikitia	DGS35-4L201024 Whakaahua
DGS35-4L201024 PDF Datasheet	DGS35-4L201024 Download Datasheet	Tuhinga DGS35-4L201024
DGS35-4L201024 Stock	Hokona DGS35-4L201024	Hokona DGS35-4L201024
DGS35-4L201024	Kaiwhakarato	Kaiwhiwhi

Ngā Hua e hāngai ana

	<p>DGS35-4KL16384</p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 16384PPR I roto i te taonga: 171 pcs</p> <p>RFQ</p>		<p>DGS35-5HM01024</p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 1024PPR I roto i te taonga: 234 pcs</p> <p>RFQ</p>
	<p>DGS35-4LN10000</p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 10000PPR I roto i te taonga: 141 pcs</p> <p>RFQ</p>		<p>DGS35-4LK08192</p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 8192PPR I roto i te taonga: 174 pcs</p> <p>RFQ</p>
	<p>DGS35-5HL04096</p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 4096PPR I roto i te taonga: 185 pcs</p> <p>RFQ</p>		<p>DGS35-4KM10000</p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 10000PPR I roto i te taonga: 154 pcs</p> <p>RFQ</p>
	<p>DGS35-4KK04096</p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 4096PPR I roto i te taonga: 190 pcs</p> <p>RFQ</p>		<p>DGS35-4KL01024</p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 1024PPR I roto i te taonga: 186 pcs</p> <p>RFQ</p>
	<p>DGS35-4KN01024</p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 1024PPR I roto i te taonga: 177 pcs</p> <p>RFQ</p>		<p>DGS35-5H202048</p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 2048PPR I roto i te taonga: 182 pcs</p> <p>RFQ</p>
	<p>DGS35-5HL00120</p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENTAL 120PPR I roto i te taonga: 191 pcs</p> <p>RFQ</p>		<p>DGS35-4KN10000</p> <p>Kaihanga: N/A Whakaahuatanga: ROTARY ENCODR INCREMENT 10000PPR I roto i te taonga: 153 pcs</p> <p>RFQ</p>

