



RAFI

1.30290.0310100

Tau Wae: 1.30290.0310100
 Kaihanga / Waitohu: RAFI
 Whakaahuatanga hua: CONFIG SW BODY PUSHBUT NON-ILLUM
 Ngā Rauemi: [1.1.30290.0310100.pdf](#)
[2.1.30290.0310100.pdf](#)
 RoHs Tūnga: Whakahaerehia te kore utu / RoHS
 Waehere Stock: 2487 pcs stock
 Tuhinga mai i: Hong Kong
 Te Ara Tuhi: DHL/Fedex/TNT/UPS/EMS

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o 1.30290.0310100

TAU WAE	1.30290.0310100
KAIHANGA	RAFI
WHAKAAHUATANGA	CONFIG SW BODY PUSHBUT NON-ILLUM
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
HE RAHINGA KEI TE WĀTEA	2487 pcs
PEPA RARAUNGA	1.1.30290.0310100.pdf 2.1.30290.0310100.pdf
MOMO	Maintained
RAUPAPA	RAFIX 30 FS
E HIAHIA ANA	Contact Block(s)
PIHANGA WHAKAPAE PAEPAE	30.3mm (Round)
ĒTAHI INGOA	1.30.290.031/0100 1302900310100 1715-1336
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
WHAKAAHUATANGA	Non-Illuminated
WHAKAAHUATANGA TAIPITOPITO	Configurable Switch Body Pushbutton, Round Non-Illuminated
MOMO KAIHOKO	Pushbutton, Round
(TĪPAKOHIA TUATAHI, KA WHAKAMAHAIA NGĀ TAEKA) RARAUNGA WHAKAMAHAIA	Rafix 30 FS

Ngā tūtohu e hāngai ana

RAFI 1.30290.0310100	1.30290.0310100 Kaiwhiwhi	1.30290.0310100 Kaiwhakarato
1.30290.0310100 Utu	1.30290.0310100 Pikitia	1.30290.0310100 Whakaahua
1.30290.0310100 PDF Datasheet	1.30290.0310100 Download Datasheet	Tuhinga 1.30290.0310100
1.30290.0310100 Stock	Hokona 1.30290.0310100	Hokona RAFI 1.30290.0310100
RAFI 1.30290.0310100	RAFI Kaiwhakarato	RAFI Kaiwhiwhi
RAFI 1.30290.0310100	RAFI USA 1.30290.0310100	

Ngā Hua e hāngai ana

<p>1.30290.0212600 Kaihanga: RAFI Whakaahuatanga: CONFIG SW BODY PUSHBUTTON ILLUM I roto i te taonga: 3921 pcs</p> <p>RFQ</p>	<p>1.30290.9210000 Kaihanga: RAFI Whakaahuatanga: CONFIG SW BODY PUSHBUTTON ILLUM I roto i te taonga: 3543 pcs</p> <p>RFQ</p>
<p>1.30290.0210100 Kaihanga: RAFI Whakaahuatanga: CONFIG SW BODY PUSHBUT NON-ILLUM I roto i te taonga: 4308 pcs</p> <p>RFQ</p>	<p>1.30290.0212300 Kaihanga: RAFI Whakaahuatanga: CONFIG SW BODY PUSHBUTTON ILLUM I roto i te taonga: 3631 pcs</p> <p>RFQ</p>
<p>1.30290.0312300 Kaihanga: RAFI Whakaahuatanga: CONFIG SW BODY PUSHBUTTON ILLUM I roto i te taonga: 3027 pcs</p> <p>RFQ</p>	<p>1.30290.0312500 Kaihanga: RAFI Whakaahuatanga: CONFIG SW BODY PUSHBUTTON ILLUM I roto i te taonga: 2634 pcs</p> <p>RFQ</p>
<p>1.30290.0212400 Kaihanga: RAFI Whakaahuatanga: CONFIG SW BODY PUSHBUTTON ILLUM I roto i te taonga: 4112 pcs</p> <p>RFQ</p>	<p>1.30290.0312400 Kaihanga: RAFI Whakaahuatanga: CONFIG SW BODY PUSHBUTTON ILLUM I roto i te taonga: 2883 pcs</p> <p>RFQ</p>
<p>1.30290.0312200 Kaihanga: RAFI Whakaahuatanga: CONFIG SW BODY PUSHBUTTON ILLUM I roto i te taonga: 2787 pcs</p> <p>RFQ</p>	<p>1.30290.0212500 Kaihanga: RAFI Whakaahuatanga: CONFIG SW BODY PUSHBUTTON ILLUM I roto i te taonga: 4385 pcs</p> <p>RFQ</p>
<p>1.30290.0212200 Kaihanga: RAFI Whakaahuatanga: CONFIG SW BODY PUSHBUTTON ILLUM I roto i te taonga: 4318 pcs</p> <p>RFQ</p>	<p>1.30290.0312600 Kaihanga: RAFI Whakaahuatanga: CONFIG SW BODY PUSHBUTTON ILLUM I roto i te taonga: 3145 pcs</p> <p>RFQ</p>