

RAFI

RAFI

1.20126.4020000

Tau Wae: 1.20126.4020000
 Kaihanga / Waitohu: RAFI
 Whakaahuatanga hua: CONTACT BLOCK SPST-NO 0.1A 35V
 PDF 1.1.20126.4020000.pdf
 PDF 2.1.20126.4020000.pdf
 Ngā Rauemi: Whakahaerehia te kore utu / RoHS
 RoHS Tūnga
 Waehe Stock: 7366 pcs stock
 Tuhinga mai i: Hong Kong
 Te Ara Tuhi: DHL/Fedex/TNT/UPS/EMS



TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o 1.20126.4020000

| | |
|------------------------------------------------------------------|----------------------------------------------------|
| TAU WAE | 1.20126.4020000 |
| KAIHANGA | RAFI |
| WHAKAAHUATANGA | CONTACT BLOCK SPST-NO 0.1A 35V |
| WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA | Whakahaerehia te kore utu / RoHS |
| HE RAHINGA KEI TE WĀTEA | 7366 pcs |
| PEPA RARAUNGA | 1.1.20126.4020000.pdf 2.1.20126.4020000.pdf |
| KĀHUA WHAKAMUTUNGA | PC Pin |
| RAUPAPA | RAFIX 22 FS |
| E HIAHIA ANA | Switch Body |
| ĒTAHI INGOA | 1.20.126.402/0000 1201264020000 1715-1144 |
| TAUMATA WHAKAARO MOE (MSL) | 1 (Unlimited) |
| WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA | Lead free / RoHS Compliant |
| WHAKAAHUATANGA TAIPITOPITO | Configurable Contact Block SPST-NO 0.1A @ 35VAC/DC |
| WHAKAPĀ ATU @ WHAKAOHO | 0.1A @ 35VAC/DC |
| TAKAHANGA | SPST-NO |
| (TĪPAKOHIA TUATAHI, KA WHAKAMAHIA NGĀ TAEKA) RARAUNGA WHAKAMAHIA | Rafix 22 FS |

Ngā tūtohu e hāngai ana

| | | |
|-------------------------------|------------------------------------|------------------------------|
| RAFI 1.20126.4020000 | 1.20126.4020000 Kaiwhiwhi | 1.20126.4020000 Kaiwhakarato |
| 1.20126.4020000 Utu | 1.20126.4020000 Pikitia | 1.20126.4020000 Whakaahua |
| 1.20126.4020000 PDF Datasheet | 1.20126.4020000 Download Datasheet | Tuhinga 1.20126.4020000 |
| 1.20126.4020000 Stock | Hokona 1.20126.4020000 | Hokona RAFI 1.20126.4020000 |
| RAFI 1.20126.4020000 | RAFI Kaiwhakarato | RAFI Kaiwhiwhi |
| RAFI 1.20126.4020000 | RAFI USA 1.20126.4020000 | |

Ngā Hua e hāngai ana

| | |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <p>1.20126.3059000 Kaihanga: RAFI Whakaahuatanga: CONTACT BLOCK DPST-NO 3A 120V I roto i te taonga: 5017 pcs RFQ</p> | <p>1.20126.4039000 Kaihanga: RAFI Whakaahuatanga: CONTACT BLOCK SPST 0.1A 35V I roto i te taonga: 4594 pcs RFQ</p> |
| <p>1.20126.3049000 Kaihanga: RAFI Whakaahuatanga: CONTACT BLOCK DPST-NC 3A 120V I roto i te taonga: 4866 pcs RFQ</p> | <p>1.20126.4049000 Kaihanga: RAFI Whakaahuatanga: CONTACT BLOCK DPST-NC 0.1A 35V I roto i te taonga: 4487 pcs RFQ</p> |
| <p>1.20126.3050000 Kaihanga: RAFI Whakaahuatanga: CONTACT BLOCK DPST-NO 3A 120V I roto i te taonga: 5181 pcs RFQ</p> | <p>1.20126.4010000 Kaihanga: RAFI Whakaahuatanga: CONTACT BLOCK SPST-NC 0.1A 35V I roto i te taonga: 9362 pcs RFQ</p> |
| <p>1.20126.3040000 Kaihanga: RAFI Whakaahuatanga: CONTACT BLOCK DPST-NC 3A 120V I roto i te taonga: 4930 pcs RFQ</p> | <p>1.20126.4029000 Kaihanga: RAFI Whakaahuatanga: CONTACT BLOCK SPST-NO 0.1A 35V I roto i te taonga: 8762 pcs RFQ</p> |
| <p>1.20126.3039000 Kaihanga: RAFI Whakaahuatanga: CONTACT BLOCK SPST 3A 120V I roto i te taonga: 4922 pcs RFQ</p> | <p>1.20126.4040000 Kaihanga: RAFI Whakaahuatanga: CONTACT BLOCK DPST-NC 0.1A 35V I roto i te taonga: 5997 pcs RFQ</p> |
| <p>1.20126.4050000 Kaihanga: RAFI Whakaahuatanga: CONTACT BLOCK DPST-NO 0.1A 35V I roto i te taonga: 4890 pcs RFQ</p> | <p>1.20126.4030000 Kaihanga: RAFI Whakaahuatanga: CONTACT BLOCK SPST 0.1A 35V I roto i te taonga: 5648 pcs RFQ</p> |