

crydom Crydom

HD4875-10

Tau Wae:	HD4875-10
Kaihanga / Waitohu:	Crydom
Whakaahuatanga hua	SSR RELAY SPST-NO 75A 48-530V
	1.HD4875-10.pdf
	2.HD4875-10.pdf
	3.HD4875-10.pdf
Ngā Rauemi:	Whakahaerehia te kore utu / RoHS
RoHs Tūnga	1004 pcs stock
Waehere Stock	Hong Kong
Tuhinga mai i	DHL/Fedex/TNT/UPS/EMS
Te Ara Tuhi	

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o HD4875-10

TAU WAE	HD4875-10
KAIHANGA	Crydom
WHAKAAHUATANGA	SSR RELAY SPST-NO 75A 48-530V
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
HE RAHINGA KEI TE WĀTEA	1004 pcs
PEPA RARAUNGA	1.HD4875-10.pdf 2.HD4875-10.pdf 3.HD4875-10.pdf
NGAOHIHI - TAE	48V ~ 530V
MOMOTUHI - WHAKAURU	3 ~ 32VDC
KĀHUA WHAKAMUTUNGA	Screw Terminal
PŪRERE PŪRERE WHAKARATO	-
RAUPAPA	HD48
PACKAGING	Bulk
PAA / CASE	Hockey Puck
MOMO PUTANGA	AC
ĒTAHI INGOA	CC2308 HD4875-10-ND
MOMO TAE	Chassis Mount
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
TAUMAHĪ KAUTE	75A
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
WHAKAAHUATANGA TAIPITOPITO	Solid State Relay SPST-NO (1 Form A) Hockey Puck
TAKAHANGA	SPST-NO (1 Form A)

Ngā tūtohu e hāngai ana

Crydom HD4875-10	HD4875-10 Kaiwhiwhi	HD4875-10 Kaiwhakarato
HD4875-10 Utu	HD4875-10 Pikitia	HD4875-10 Whakaahua
HD4875-10 PDF Datasheet	HD4875-10 Download Datasheet	Tuhinga HD4875-10
HD4875-10 Stock	Hokona HD4875-10	Hokona Crydom HD4875-10
Crydom HD4875-10	Crydom Kaiwhakarato	Crydom Kaiwhiwhi
Crydom HD4875-10	AMI SEMICONDUCTOR HD4875-10	Crydom Co. HD4875-10
Sensata Technologies – Crydom HD4875-10		

Ngā Hua e hāngai ana

<p>HD4875G-10 Kaihanga: Crydom Whakaahuatanga: RELAY SSR 530VAC/75A DC I roto i te taonga: 894 pcs</p> <p>RFQ</p>	<p>HD4875 Kaihanga: Crydom Whakaahuatanga: SSR RELAY SPST-NO 75A 48-530V I roto i te taonga: 835 pcs</p> <p>RFQ</p>
<p>HD4850PGH Kaihanga: Crydom Whakaahuatanga: RELAY SSR 530VAC/50A DC I roto i te taonga: 1107 pcs</p> <p>RFQ</p>	<p>HD4875G Kaihanga: Crydom Whakaahuatanga: RELAY SSR 530VAC/75A DC I roto i te taonga: 918 pcs</p> <p>RFQ</p>
<p>HD4875KT-10 Kaihanga: Crydom Whakaahuatanga: RELAY SSR 530VAC/75A DC I roto i te taonga: 1072 pcs</p> <p>RFQ</p>	<p>HD4850PGHT Kaihanga: Crydom Whakaahuatanga: RELAY SSR 530VAC/50A DC I roto i te taonga: 1090 pcs</p> <p>RFQ</p>
<p>HD4890 Kaihanga: Crydom Whakaahuatanga: SSR RELAY SPST-NO 90A 48-530V I roto i te taonga: 959 pcs</p> <p>RFQ</p>	<p>HD4875K-10 Kaihanga: Crydom Whakaahuatanga: RELAY SSR 530VAC/75A DC I roto i te taonga: 1090 pcs</p> <p>RFQ</p>
<p>HD4850T Kaihanga: Crydom Whakaahuatanga: RELAY SSR 530VAC/50A DC I roto i te taonga: 1736 pcs</p> <p>RFQ</p>	<p>HD4850P Kaihanga: Crydom Whakaahuatanga: RELAY SSR 530VAC/50A DC I roto i te taonga: 1494 pcs</p> <p>RFQ</p>
<p>HD4890-10 Kaihanga: Crydom Whakaahuatanga: SSR RELAY SPST-NO 90A 48-530V I roto i te taonga: 893 pcs</p> <p>RFQ</p>	<p>HD4850S Kaihanga: Crydom Whakaahuatanga: RELAY SSR 530VAC/50A DC I roto i te taonga: 1569 pcs</p> <p>RFQ</p>