

<b>BOURNS®</b>	<b>Bourns, Inc.</b>
----------------	---------------------

### 3315P-001-016L

Tau Wae:

3315P-001-016L

Kaihanga / Waitohu:

Bourns, Inc.

Whakaahuatanga hua

ROTARY ENCODER MECHANICAL 16PPR

Ngā Rauemi:

3315P-001-016L.pdf

RoHS Tūnga

Whakahaerehia te kore utu / RoHS

Waehere Stock

46063 pcs stock

Tuhinga mai i

Hong Kong

Te Ara Tuhi

DHL/Fedex/TNT/UPS/EMS

**TONO MO TE WHAKAHUA**

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

#### Ngā whakaaturanga o 3315P-001-016L

TAU WAE	3315P-001-016L
KAIHANGA	Bourns, Inc.
WHAKAAHUATANGA	ROTARY ENCODER MECHANICAL 16PPR
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
HE RAHINGA KEI TE WĀTEA	46063 pcs
PEPA RARAUNGA	3315P-001-016L.pdf
TUHINGA O MUA	-
KĀHUA WHAKAMUTUNGA	PC Pin
RAUPAPA	3315
KO TE ROTATIONAL LIFE (CYCLES MIN)	25K
PULSES IA REVOLUTION	16
MOMO PUTANGA	Quadrature (Incremental)
WHAKATAKOTORANGA	Vertical
MOMO TAE	Panel, PCB Through Hole
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
MOMO KUPUTUHI	Mechanical
TUHINGA	No
HANGAIA KI TE WHAKAWHITI	No
MOMO KAIHOKO	1/8" Dia Slotted End

#### Ngā tūtohu e hāngai ana

Bourns, Inc. 3315P-001-016L	3315P-001-016L Kaiwhiwhi	3315P-001-016L Kaiwhakarato
3315P-001-016L Utu	3315P-001-016L Pikitia	3315P-001-016L Whakaahua
3315P-001-016L PDF Datasheet	3315P-001-016L Download Datasheet	Tuhinga 3315P-001-016L
3315P-001-016L Stock	Hokona 3315P-001-016L	Hokona Bourns, Inc. 3315P-001-016L
Bourns, Inc. 3315P-001-016L	Bourns, Inc. Kaiwhakarato	Bourns, Inc. Kaiwhiwhi
Bourns, Inc. 3315P-001-016L	Bourns Inc. 3315P-001-016L	J.W. Miller / Bourns 3315P-001-016L

#### Ngā Hua e hāngai ana

<p><b>3315P-125-016L</b> Kaihanga: Bourns, Inc. Whakaahuatanga: ENCODER - 9MM SQ I roto i te taonga: 49331 pcs</p> <p><b>RFQ</b></p>	<p><b>3315P-025-006L</b> Kaihanga: Bourns, Inc. Whakaahuatanga: ROTARY ENCODER MECHANICAL 6PPR I roto i te taonga: 27027 pcs</p> <p><b>RFQ</b></p>
<p><b>3315C-111-016L</b> Kaihanga: Bourns, Inc. Whakaahuatanga: ROTARY ENCODER MECHANICAL 16PPR I roto i te taonga: 26735 pcs</p> <p><b>RFQ</b></p>	<p><b>3315C-102-016L</b> Kaihanga: Bourns, Inc. Whakaahuatanga: ROTARY ENCODER MECHANICAL 16PPR I roto i te taonga: 22726 pcs</p> <p><b>RFQ</b></p>
<p><b>3315R-101-016L</b> Kaihanga: Bourns, Inc. Whakaahuatanga: ROTARY ENCODER MECHANICAL 16PPR I roto i te taonga: 39623 pcs</p> <p><b>RFQ</b></p>	<p><b>3315C-102-006L</b> Kaihanga: Bourns, Inc. Whakaahuatanga: ROTARY ENCODER MECHANICAL 6PPR I roto i te taonga: 23549 pcs</p> <p><b>RFQ</b></p>
<p><b>3315C-125-016L</b> Kaihanga: Bourns, Inc. Whakaahuatanga: ROTARY ENCODER MECHANICAL 16PPR I roto i te taonga: 4256 pcs</p> <p><b>RFQ</b></p>	<p><b>3315P-001-006L</b> Kaihanga: Bourns, Inc. Whakaahuatanga: ROTARY ENCODER MECHANICAL 6PPR I roto i te taonga: 33187 pcs</p> <p><b>RFQ</b></p>
<p><b>3315P-025-016L</b> Kaihanga: Bourns, Inc. Whakaahuatanga: ROTARY ENCODER MECHANICAL 16PPR I roto i te taonga: 43287 pcs</p> <p><b>RFQ</b></p>	<p><b>3315R-102-016L</b> Kaihanga: Bourns, Inc. Whakaahuatanga: ROTARY ENCODER MECHANICAL 16PPR I roto i te taonga: 31201 pcs</p> <p><b>RFQ</b></p>
<p><b>3315C-101-016L</b> Kaihanga: Bourns, Inc. Whakaahuatanga: ROTARY ENCODER MECHANICAL 16PPR I roto i te taonga: 29809 pcs</p> <p><b>RFQ</b></p>	<p><b>3315R-025-016L</b> Kaihanga: Bourns, Inc. Whakaahuatanga: ROTARY ENCODER MECHANICAL 16PPR I roto i te taonga: 4619 pcs</p> <p><b>RFQ</b></p>