

Johanson Technology

2450BM14A0004T

Tau Wae:	2450BM14A0004T
Kaihanga / Waitohu:	Johanson Technology
Whakaahuatanga hua	BALUN MATCHED EIA0603
Ngā Rauemi:	Whakahaerehia te kore utu / RoHS
RoHS Tūnga	5614 pcs stock
Waehere Stock	Hong Kong
Tuhinga mai i	DHL/Fedex/TNT/UPS/EMS
Te Ara Tuhi	

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o 2450BM14A0004T

TAU WAE	2450BM14A0004T
KAIHANGA	Johanson Technology
WHAKAAHUATANGA	BALUN MATCHED EIA0603
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
HE RAHINGA KEI TE WĀTEA	5614 pcs
PEPA RARAUNGA	
RAUPAPA	*
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
WHAKAAHUATANGA TAIPITOPITO	RF Balun

Ngā tūtohu e hāngai ana

Johanson Technology 2450BM14A0004T	2450BM14A0004T Kaiwhiwhi	2450BM14A0004T Kaiwhakarato
2450BM14A0004T Utu	2450BM14A0004T Pikitia	2450BM14A0004T Whakaahua
2450BM14A0004T PDF Datasheet	2450BM14A0004T Download Datasheet	Tuhinga 2450BM14A0004T
2450BM14A0004T Stock	Hokona 2450BM14A0004T	Hokona Johanson Technology 2450BM14A0004T
Johanson Technology 2450BM14A0004T	Johanson Technology Kaiwhakarato	Johanson Technology Kaiwhiwhi
Johanson Technology 2450BM14A0004T	Johanson 2450BM14A0004T	Johanson Technology Inc. 2450BM14A0004T

Ngā Hua e hāngai ana

<p>2450BL15K050E Kaihanga: Johanson Technology Whakaahuatanga: BALUN 2.4GHZ-2.5GHZ 50/50 0805 I roto i te taonga: 3803 pcs</p> <p style="text-align: center; background-color: #ccc; padding: 2px 5px; font-weight: bold;">RFQ</p>	<p>2450BM14E0003T Kaihanga: Johanson Technology Whakaahuatanga: BALUN 2.4GHZ-2.5GHZ 0603 I roto i te taonga: 409063 pcs</p> <p style="text-align: center; background-color: #ccc; padding: 2px 5px; font-weight: bold;">RFQ</p>
<p>2450BM14G0011T Kaihanga: Johanson Technology Whakaahuatanga: BALUN 2.4GHZ-2.5GHZ 0603 I roto i te taonga: 174728 pcs</p> <p style="text-align: center; background-color: #ccc; padding: 2px 5px; font-weight: bold;">RFQ</p>	<p>2450BM15A0006E Kaihanga: Johanson Technology Whakaahuatanga: BALUN 2.45GHZ STLC2690 MATCHED I roto i te taonga: 6487 pcs</p> <p style="text-align: center; background-color: #ccc; padding: 2px 5px; font-weight: bold;">RFQ</p>
<p>2450BM14B0001T Kaihanga: Johanson Technology Whakaahuatanga: BALUN 2.45 GHZ TI CC2430 0603 I roto i te taonga: 6941 pcs</p> <p style="text-align: center; background-color: #ccc; padding: 2px 5px; font-weight: bold;">RFQ</p>	<p>2450BL15K100E Kaihanga: Johanson Technology Whakaahuatanga: BALUN 2.4GHZ-2.5GHZ 50/100 0805 I roto i te taonga: 322482 pcs</p> <p style="text-align: center; background-color: #ccc; padding: 2px 5px; font-weight: bold;">RFQ</p>
<p>2450BM07A0004T Kaihanga: Johanson Technology Whakaahuatanga: BALUN MATCHED EIA0402 I roto i te taonga: 361466 pcs</p> <p style="text-align: center; background-color: #ccc; padding: 2px 5px; font-weight: bold;">RFQ</p>	<p>2450BM08B0003T Kaihanga: Johanson Technology Whakaahuatanga: BALUN 2.4GHZ-2.5GHZ 50/50 5SMD I roto i te taonga: 163137 pcs</p> <p style="text-align: center; background-color: #ccc; padding: 2px 5px; font-weight: bold;">RFQ</p>
<p>2450BL15B200E Kaihanga: Johanson Technology Whakaahuatanga: BALUN 2.4GHZ-2.5GHZ 50/200 0805 I roto i te taonga: 934216 pcs</p> <p style="text-align: center; background-color: #ccc; padding: 2px 5px; font-weight: bold;">RFQ</p>	<p>2450BM15A0002E Kaihanga: Johanson Technology Whakaahuatanga: BALUN 2.4GHZ-2.5GHZ 0805 I roto i te taonga: 111154 pcs</p> <p style="text-align: center; background-color: #ccc; padding: 2px 5px; font-weight: bold;">RFQ</p>
<p>2450BM14E0007T Kaihanga: Johanson Technology Whakaahuatanga: BALUN 2.4GHZ-2.5GHZ 0603 I roto i te taonga: 237675 pcs</p> <p style="text-align: center; background-color: #ccc; padding: 2px 5px; font-weight: bold;">RFQ</p>	<p>2450BM14A0002T Kaihanga: Johanson Technology Whakaahuatanga: BALUN 2.4GHZ-2.5GHZ 0603 I roto i te taonga: 102454 pcs</p> <p style="text-align: center; background-color: #ccc; padding: 2px 5px; font-weight: bold;">RFQ</p>