



AVX Corporation

CP0805B1765AWTR

Tau Wae:	CP0805B1765AWTR
Kaihanga / Waitohu:	AVX Corporation
Whakaahuatanga hua	RF DIR COUPLER 1.765GHZ 0805
Ngā Rauemi:	CP0805B1765AWTR.pdf
RoHS Tūnga	Kei roto nga rangatira / RoHS kaore i te ture
Waehere Stock	260989 pcs stock
Tuhinga mai i	Hong Kong
Te Ara Tuhi	DHL/Fedex/TNT/UPS/EMS

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o CP0805B1765AWTR

TAU WAE	CP0805B1765AWTR
KAIHANGA	AVX Corporation
WHAKAAHUATANGA	RF DIR COUPLER 1.765GHZ 0805
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Kei roto nga rangatira / RoHS kaore i te ture
HE RAHINGA KEI TE WĀTEA	260989 pcs
PEPA RARAUNGA	CP0805B1765AWTR.pdf
PŪRERE PŪRERE WHAKARATO	0805
RAUPAPA	-
HOKI HOKI	-
MANA - MAX	3W
PACKAGING	Tape & Reel (TR)
PAA / CASE	0805 (2012 Metric)
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Contains lead / RoHS non-compliant
WHAKAMOTU	-
TE HAINATANGA WHAKATAUNGA	-
RAUTANGA	1.765GHz
WHAKAAHUATANGA TAIPITOPITO	RF Directional Coupler 1.765GHz 3W 0805 (2012 Metric)
HONONGA TAE	-
HE MOMO HOAHOA	Standard
NGA TONO	-

Ngā tūtohu e hāngai ana

AVX Corporation CP0805B1765AWTR	CP0805B1765AWTR Kaihiwhi	CP0805B1765AWTR Kaiwhakarato
CP0805B1765AWTR Utu	CP0805B1765AWTR Pikitia	CP0805B1765AWTR Whakaahua
CP0805B1765AWTR PDF Datasheet	CP0805B1765AWTR Download Datasheet	Tuhinga CP0805B1765AWTR
CP0805B1765AWTR Stock	Hokona CP0805B1765AWTR	Hokona AVX Corporation CP0805B1765AWTR
AVX Corporation CP0805B1765AWTR	AVX Corporation Kaiwhakarato	AVX Corporation Kaihiwhi
AVX Corporation CP0805B1765AWTR	AVX Corporation [MIL] CP0805B1765AWTR	

Ngā Hua e hāngai ana

<p>CP0805B1842BWTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLR 1.805-1.88GHZ 0805 I roto i te taonga: 303740 pcs</p> <p>RFQ</p>	<p>CP0805B1441CWTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPL 1.429-1.453GHZ 0805 I roto i te taonga: 259823 pcs</p> <p>RFQ</p>
<p>CP0805B1747BWTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLR 1.71-1.785GHZ 0805 I roto i te taonga: 310234 pcs</p> <p>RFQ</p>	<p>CP0805B1842CWTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLR 1.805-1.88GHZ 0805 I roto i te taonga: 244149 pcs</p> <p>RFQ</p>
<p>CP0805B1441AWTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPL 1.429-1.453GHZ 0805 I roto i te taonga: 244663 pcs</p> <p>RFQ</p>	<p>CP0805B1880CWTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.85-1.91GHZ 0805 I roto i te taonga: 254080 pcs</p> <p>RFQ</p>
<p>CP0805B1747CWTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLR 1.71-1.785GHZ 0805 I roto i te taonga: 268194 pcs</p> <p>RFQ</p>	<p>CP0805B1747AWTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLR 1.71-1.785GHZ 0805 I roto i te taonga: 306143 pcs</p> <p>RFQ</p>
<p>CP0805B1842AWTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLR 1.805-1.88GHZ 0805 I roto i te taonga: 242457 pcs</p> <p>RFQ</p>	<p>CP0805B1880AWTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.85-1.91GHZ 0805 I roto i te taonga: 252234 pcs</p> <p>RFQ</p>
<p>CP0805B1880BWTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.85-1.91GHZ 0805 I roto i te taonga: 306200 pcs</p> <p>RFQ</p>	<p>CP0805B1741AWTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.741GHZ 0805 I roto i te taonga: 273580 pcs</p> <p>RFQ</p>