



ADI (Analog Devices, Inc.)

## LTC5582HDD#PBF

Tau Wae:

LTC5582HDD#PBF

Kaihanga / Waitohu:

ADI (Analog Devices, Inc.)

Whakaahuatanga hua

IC RF DETECT 40MHZ-10GHZ 10DFN

Ngā Rauemi:

 LTC5582HDD#PBF.pdf

Waehere Stock

5188 pcs stock

Tuhinga mai i

Hong Kong


Te Ara Tuhi

DHL/Fedex/TNT/UPS/EMS

**TONO MO TE WHAKAHUA**

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

## Ngā whakaaturanga o LTC5582HDD#PBF

|   |  |
|---|--|
| TAU WAE                                 | LTC5582HDD#PBF   |
| KAIHANGA                                | ADI (Analog Devices, Inc.)   |
| WHAKAAHUATANGA                          | IC RF DETECT 40MHZ-10GHZ 10DFN   |
| WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA |  |
| HE RAHINGA KEI TE WĀTEA                 | 5188 pcs   |
| PEPA RARAUNGA                           |  LTC5582HDD#PBF.pdf |
| TUHINGA O MUA                           | 3.1 V ~ 3.5 V  |
| PŪRERE PŪRERE WHAKARATO                 | 10-DFN (3x3)   |
| RAUPAPA                                 | -  |
| MOMO RF                                 | CDMA, LTE, W-CDMA, WiMAX   |
| PACKAGING                               | Tube   |
| PAA / CASE                              | 10-WFDFN Exposed Pad   |
| TAUMATA WHAKAARO MOE (MSL)              | 1 (Unlimited)  |
| RANUNGA WHAKAURU                        | -57dBm ~ 2dBm  |
| RAUTANGA                                | 40MHz ~ 10GHz  |
| WHAKAAHUATANGA TAIPITOPITO              | RF Detector IC CDMA, LTE, W-CDMA, WiMAX 40MHz ~ 10GHz -57dBm ~ 2dBm ±0.5dB 10-WFDFN Exposed Pad        |
| I TEIE NEI - TE TUKU                    | 41.6mA   |
| TE TIKA                                 | ±0.5dB   |

## Ngā tūtohu e hāngai ana

|   |   |  |
|---|---|--|
| ADI (Analog Devices, Inc.) LTC5582HDD#PBF | LTC5582HDD#PBF Kaiwhiwhi                | LTC5582HDD#PBF Kaiwhakarato                      |
| LTC5582HDD#PBF Utu                        | LTC5582HDD#PBF Pikitia                  | LTC5582HDD#PBF Whakaahua                         |
| LTC5582HDD#PBF PDF Datasheet              | LTC5582HDD#PBF Download Datasheet       | Tuhinga LTC5582HDD#PBF                           |
| LTC5582HDD#PBF Stock                      | Hokona LTC5582HDD#PBF                   | Hokona ADI (Analog Devices, Inc.) LTC5582HDD#PBF |
| ADI (Analog Devices, Inc.) LTC5582HDD#PBF | ADI (Analog Devices, Inc.) Kaiwhakarato | ADI (Analog Devices, Inc.) Kaiwhiwhi             |
| ADI (Analog Devices, Inc.) LTC5582HDD#PBF | AD LTC5582HDD#PBF                       | ADI (Analog Devices, Inc.) LTC5582HDD#PBF        |
| Analog Devices Inc. LTC5582HDD#PBF        | Analog Devices, Inc. LTC5582HDD#PBF     |  |

## Ngā Hua e hāngai ana

|  |   |
|--|---|
|  <p><b>LTC5576IUF#PBF</b><br/>Kaihanga: ADI (Analog Devices, Inc.)<br/>Whakaahuatanga: IC MIXER DOWN CONVERTER 16QFN<br/>I roto i te taonga: 5112 pcs</p> <p><b>RFQ</b></p>    |  <p><b>LTC5582IDD#TRPBF</b><br/>Kaihanga: ADI (Analog Devices, Inc.)<br/>Whakaahuatanga: IC RF DETECT 40MHZ-10GHZ 10DFN<br/>I roto i te taonga: 5406 pcs</p> <p><b>RFQ</b></p> |
|  <p><b>LTC5577IUF#TRPBF</b><br/>Kaihanga: ADI (Analog Devices, Inc.)<br/>Whakaahuatanga: IC MIXER DOWN CONVERTER 16QFN<br/>I roto i te taonga: 9894 pcs</p> <p><b>RFQ</b></p>  |  <p><b>LTC5583IUF#PBF</b><br/>Kaihanga: ADI (Analog Devices, Inc.)<br/>Whakaahuatanga: IC RF DETECT 40MHZ-6GHZ 24QFN<br/>I roto i te taonga: 5154 pcs</p> <p><b>RFQ</b></p>    |
|  <p><b>LTC5576IUF#TRPBF</b><br/>Kaihanga: ADI (Analog Devices, Inc.)<br/>Whakaahuatanga: IC MIXER DOWN CONVERTER 16QFN<br/>I roto i te taonga: 10996 pcs</p> <p><b>RFQ</b></p> |  <p><b>LTC5577IUF</b><br/>Kaihanga: ADI (Analog Devices, Inc.)<br/>Whakaahuatanga: IC POWER MANAGEMENT<br/>I roto i te taonga: 4656 pcs</p> <p><b>RFQ</b></p>                  |
|  <p><b>LTC5583IUF#TRPBF</b><br/>Kaihanga: ADI (Analog Devices, Inc.)<br/>Whakaahuatanga: IC RF DETECT 40MHZ-6GHZ 24QFN<br/>I roto i te taonga: 9163 pcs</p> <p><b>RFQ</b></p>  |  <p><b>LTC5584IUF#PBF</b><br/>Kaihanga: ADI (Analog Devices, Inc.)<br/>Whakaahuatanga: RF DEMOD IC 30MHZ-1.4GHZ 24QFN<br/>I roto i te taonga: 7918 pcs</p> <p><b>RFQ</b></p>   |
|  <p><b>LTC5582HDD#TRPBF</b><br/>Kaihanga: ADI (Analog Devices, Inc.)<br/>Whakaahuatanga: IC RF DETECT 40MHZ-10GHZ 10DFN<br/>I roto i te taonga: 9777 pcs</p> <p><b>RFQ</b></p> |  <p><b>LTC5576IUF</b><br/>Kaihanga: ADI (Analog Devices, Inc.)<br/>Whakaahuatanga: IC POWER MANAGEMENT<br/>I roto i te taonga: 5467 pcs</p> <p><b>RFQ</b></p>                  |
|  <p><b>LTC5582IDD#PBF</b><br/>Kaihanga: ADI (Analog Devices, Inc.)<br/>Whakaahuatanga: IC RF DETECT 40MHZ-10GHZ 10DFN<br/>I roto i te taonga: 6212 pcs</p> <p><b>RFQ</b></p>   |  <p><b>LTC5577IUF#PBF</b><br/>Kaihanga: ADI (Analog Devices, Inc.)<br/>Whakaahuatanga: IC MIXER DOWN CONVERTER 16QFN<br/>I roto i te taonga: 6999 pcs</p> <p><b>RFQ</b></p>    |