



Abracon Corporation

APAE1575R2540AADBE-T

Tau Wae:	APAE1575R2540AADBE-T
Kaihanga / Waitohu:	Abracon Corporation
Whakaahuatanga hua	RF ANT 1.575GHZ CER PATCH PIN
	1.APAE1575R2540AADBE-T.pdf
	2.APAE1575R2540AADBE-T.pdf
	3.APAE1575R2540AADBE-T.pdf
Ngā Rauemi:	Whakahaerehia te kore utu / RoHS
RoHs Tūnga	54381 pcs stock
Waehere Stock	Hong Kong
Tuhinga mai i	DHL/Fedex/TNT/UPS/EMS
Te Ara Tuhi	

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

Ngā whakaaturanga o APAE1575R2540AADBE-T

TAU WAE	APAE1575R2540AADBE-T
KAIHANGA	Abracon Corporation
WHAKAAHUATANGA	RF ANT 1.575GHZ CER PATCH PIN
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
HE RAHINGA KEI TE WĀTEA	54381 pcs
PEPA RARAUNGA	1.APAE1575R2540AADBE-T.pdf 2.APAE1575R2540AADBE-T.pdf 3.APAE1575R2540AADBE-T.pdf
VSWR	2.32
WHAKAMUTUNGA	Pin
RAUPAPA	-
HOKI HOKI	-
PACKAGING	Tray
ĒTAHI INGOA	535-11942 APAE1575R2540AADBET
TUHINGA O MUA	1
MOMO TAE	Adhesive
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
TIAKI INGOA	-
TEITEI (MAX)	0.181" (4.60mm)
HUA	4.5dBic
MAHINGA RAWE	1.569GHz ~ 1.577GHz
RANGAHAU RŌPŪ	UHF (1 GHz ~ 2 GHz)
TAUTANGA (POARI / PAE)	1.575GHz
NGĀ ĀHUATANGA	-
WHAKAAHUATANGA TAIPITOPITO	1.575GHz GPS Ceramic Patch RF Antenna 1.569GHz ~ 1.577GHz 4.5dBic Pin Adhesive
NGA TONO	GPS
MOMO ANTENNA	Ceramic Patch

Ngā tūtohu e hāngai ana

Abracon Corporation APAE1575R2540AADBE-T	APAE1575R2540AADBE-T Kaiwhiwhi	APAE1575R2540AADBE-T Kaiwhakarato
APAE1575R2540AADBE-T Utu	APAE1575R2540AADBE-T Pikitia	APAE1575R2540AADBE-T Whakaahua
APAE1575R2540AADBE-T PDF Datasheet	APAE1575R2540AADBE-T Download Datasheet	Tuhinga APAE1575R2540AADBE-T
APAE1575R2540AADBE-T Stock	Hokona APAE1575R2540AADBE-T	Hokona Abracon Corporation APAE1575R2540AADBE-T
Abracon Corporation APAE1575R2540AADBE-T	Abracon Corporation Kaiwhakarato	Abracon Corporation Kaiwhiwhi
Abracon Corporation APAE1575R2540AADBE-T	Abracon LLC APAE1575R2540AADBE-T	

Ngā Hua e hāngai ana

<p>APAE868R2540JBDB2-T Kaihanga: Abracon Corporation Whakaahuatanga: RF ANT 868MHZ CER PATCH PIN ADH I roto i te taonga: 17283 pcs</p> <p>RFQ</p>	<p>APAE1575R1820ABDC1-T Kaihanga: Abracon Corporation Whakaahuatanga: RF ANT 1.575GHZ CER PATCH PIN I roto i te taonga: 48743 pcs</p> <p>RFQ</p>
<p>APAE1575R1840BADB1F-T Kaihanga: Abracon Corporation Whakaahuatanga: RF ANT 1.575GHZ CER PATCH PIN I roto i te taonga: 56029 pcs</p> <p>RFQ</p>	<p>APAE1621R2540ABDD1-T Kaihanga: Abracon Corporation Whakaahuatanga: RF ANT 2.3GHZ CER PATCH PIN I roto i te taonga: 16849 pcs</p> <p>RFQ</p>
<p>APAE1590R2540AKDB1-T Kaihanga: Abracon Corporation Whakaahuatanga: RF ANT 1.575/1.602GHZ CER PATCH I roto i te taonga: 53918 pcs</p> <p>RFQ</p>	<p>APAE2338L2540DDB1-T Kaihanga: Abracon Corporation Whakaahuatanga: RF ANT 2.3GHZ CER PATCH PIN ADH I roto i te taonga: 44029 pcs</p> <p>RFQ</p>
<p>APAE1575R1840AADB7-T Kaihanga: Abracon Corporation Whakaahuatanga: RF ANT 1.575GHZ CER PATCH PIN I roto i te taonga: 49157 pcs</p> <p>RFQ</p>	<p>APAE1575R1540AZDB2F-T Kaihanga: Abracon Corporation Whakaahuatanga: RF ANT 1.575GHZ CER PATCH PIN I roto i te taonga: 55021 pcs</p> <p>RFQ</p>
<p>APAE1590R1350AKDB5-T Kaihanga: Abracon Corporation Whakaahuatanga: RF ANT 1.575/1.602GHZ CER PATCH I roto i te taonga: 73042 pcs</p> <p>RFQ</p>	<p>APAE1575R2520ABDD7-T Kaihanga: Abracon Corporation Whakaahuatanga: RF ANT 1.575GHZ CER PATCH PIN I roto i te taonga: 47585 pcs</p> <p>RFQ</p>
<p>APAE1575R2040ABDD2-T Kaihanga: Abracon Corporation Whakaahuatanga: RF ANT 1.575GHZ CER PATCH PIN I roto i te taonga: 57016 pcs</p> <p>RFQ</p>	<p>APAE1575R2540BBDB1-T Kaihanga: Abracon Corporation Whakaahuatanga: RF ANT 1.575GHZ CER PATCH PIN I roto i te taonga: 52577 pcs</p> <p>RFQ</p>