





AVX Corporation


CP0603D1034AWTR

Tau Wae:	CP0603D1034AWTR
Kaihanga / Waitohu:	AVX Corporation
Whakaahuatanga hua	RF DIR COUPLER 1.034GHZ 0603
Ngā Rauemi:	 CP0603D1034AWTR.pdf
RoHS Tūnga	 Kei roto nga rangatira / RoHS kaore i te ture
Waeheere Stock	346227 pcs stock
Tuhinga mai i	Hong Kong
Te Ara Tuhi	DHL/Fedex/TNT/UPS/EMS

TONO MO TE WHAKAHUA

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.


Ngā whakaaturanga o CP0603D1034AWTR

TAU WAE	CP0603D1034AWTR
KAIHANGA	AVX Corporation
WHAKAAHUATANGA	RF DIR COUPLER 1.034GHZ 0603
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Kei roto nga rangatira / RoHS kaore i te ture
HE RAHINGA KEI TE WĀTEA	346227 pcs
PEPA RARAUNGA	 CP0603D1034AWTR.pdf
PŪRERE PŪRERE WHAKARATO	0603
RAUPAPA	-
HOKI HOKI	-
MANA - MAX	3W
PACKAGING	Tape & Reel (TR)
PAA / CASE	0603 (1608 Metric)
TAUMATA WHAKAARO MOE (MSL)	1 (Unlimited)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Contains lead / RoHS non-compliant
WHAKAMOTU	-
TE HAINATANGA WHAKATAUNGA	-
RAUTANGA	1.034GHz
WHAKAAHUATANGA TAIPITOPITO	RF Directional Coupler 1.034GHz 3W 0603 (1608 Metric)
HONONGA TAE	-
HE MOMO HOAHOA	Standard
NGA TONO	-

Ngā tūtohu e hāngai ana

AVX Corporation CP0603D1034AWTR	CP0603D1034AWTR Kaihiwhi	CP0603D1034AWTR Kaiwhakarato
CP0603D1034AWTR Utu	CP0603D1034AWTR Pikitia	CP0603D1034AWTR Whakaahua
CP0603D1034AWTR PDF Datasheet	CP0603D1034AWTR Download Datasheet	Tuhinga CP0603D1034AWTR
CP0603D1034AWTR Stock	Hokona CP0603D1034AWTR	Hokona AVX Corporation CP0603D1034AWTR
AVX Corporation CP0603D1034AWTR	AVX Corporation Kaiwhakarato	AVX Corporation Kaihiwhi
AVX Corporation CP0603D1034AWTR	AVX Corporation [MIL] CP0603D1034AWTR	

Ngā Hua e hāngai ana

 <p>CP0603D1880BWTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.85-1.91GHZ 0603 I roto i te taonga: 385891 pcs</p> <p>RFQ</p>	 <p>CP0603D0942AWTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 925-960MHZ 0603 I roto i te taonga: 444819 pcs</p> <p>RFQ</p>
 <p>CP0603D0902AWTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 890-915MHZ 0603 I roto i te taonga: 417000 pcs</p> <p>RFQ</p>	 <p>CP0603D0947AWTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 935-960MHZ 0603 I roto i te taonga: 366870 pcs</p> <p>RFQ</p>
 <p>CP0603D0881AWTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 869-894MHZ 0603 I roto i te taonga: 428382 pcs</p> <p>RFQ</p>	 <p>CP0603D1890BWTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.88-1.9GHZ 0603 I roto i te taonga: 385592 pcs</p> <p>RFQ</p>
 <p>CP0603D2442AWTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 2.4-2.484GHZ 0603 I roto i te taonga: 389294 pcs</p> <p>RFQ</p>	 <p>CP0603D1441AWTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 1.429-1.453GHZ 0603 I roto i te taonga: 344101 pcs</p> <p>RFQ</p>
 <p>CP0603D0880AWTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 880MHZ 0603 I roto i te taonga: 407479 pcs</p> <p>RFQ</p>	 <p>CP0603D3000AWTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 3GHZ 0603 I roto i te taonga: 429643 pcs</p> <p>RFQ</p>
 <p>CP0603D0897AWTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 880-915MHZ 0603 I roto i te taonga: 350727 pcs</p> <p>RFQ</p>	 <p>CP0603D2442BWTR Kaihanga: AVX Corporation Whakaahuatanga: RF DIR COUPLER 2.4-2.484GHZ 0603 I roto i te taonga: 390239 pcs</p> <p>RFQ</p>