



## HL8518\_1103929

Tau Wae: HL8518\_1103929  
 Kaihanga / Waitohu: Sierra Wireless  
 Whakaahuatanga hua: IC RF MODULE HSDPA  
 Ngā Rauemi:  
 RoHS Tūnga: Whakahaerehia te kore utu / RoHS  
 Waehere Stock: 1690 pcs stock  
 Tuhinga mai i: Hong Kong  
 Te Ara Tuhi: DHL/Fedex/TNT/UPS/EMS

**TONO MO TE WHAKAHUA**

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

### Ngā whakaaturanga o HL8518\_1103929

TAU WAE	HL8518_1103929
KAIHANGA	Sierra Wireless
WHAKAAHUATANGA	IC RF MODULE HSDPA
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
HE RAHINGA KEI TE WĀTEA	1690 pcs
PEPA RARAUNGA	
RAUPAPA	-
ĒTAHI INGOA	1103929 1645-1076 HL8518_1103929-ND
TAUMATA WHAKAARO MOE (MSL)	3 (168 Hours)
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant

### Ngā tūtohu e hāngai ana

Sierra Wireless HL8518_1103929	HL8518_1103929 Kaiwhiwhi	HL8518_1103929 Kaiwhakarato
HL8518_1103929 Utu	HL8518_1103929 Pikitia	HL8518_1103929 Whakaahua
HL8518_1103929 PDF Datasheet	HL8518_1103929 Download Datasheet	Tuhinga HL8518_1103929
HL8518_1103929 Stock	Hokona HL8518_1103929	Hokona Sierra Wireless HL8518_1103929
Sierra Wireless HL8518_1103929	Sierra Wireless Kaiwhakarato	Sierra Wireless Kaiwhiwhi
Sierra Wireless HL8518_1103929		

### Ngā Hua e hāngai ana

<p><b>HL8-2N-X</b>                  Kaihanga: Panduit                  Whakaahuatanga: CONN TERM RECT LUG 1-4 AWG #1/2                  I roto i te taonga: 2374 pcs</p> <p><b>RFQ</b></p>	<p><b>HL8548_1102810</b>                  Kaihanga: Sierra Wireless                  Whakaahuatanga: RF TXRX CELLULAR 3G (AT&amp;T)                  I roto i te taonga: 1605 pcs</p> <p><b>RFQ</b></p>
<p><b>HL8-1-X</b>                  Kaihanga: Panduit                  Whakaahuatanga: CONN TERM RECT LUG 1-4 AWG                  I roto i te taonga: 2542 pcs</p> <p><b>RFQ</b></p>	<p><b>HL8528_1102576</b>                  Kaihanga: Sierra Wireless                  Whakaahuatanga: MOD HL HSPA+ 1.8V                  I roto i te taonga: 3131 pcs</p> <p><b>RFQ</b></p>
<p><b>HL8548-G_1103969</b>                  Kaihanga: Sierra Wireless                  Whakaahuatanga: MOD HL HSDPA 3G W/GNSS                  I roto i te taonga: 1244 pcs</p> <p><b>RFQ</b></p>	<p><b>HL8-2-X</b>                  Kaihanga: Panduit                  Whakaahuatanga: CONN TERM RECT LUG 1-4 AWG #1/4                  I roto i te taonga: 2158 pcs</p> <p><b>RFQ</b></p>
<p><b>HL8528_1103960</b>                  Kaihanga: Sierra Wireless                  Whakaahuatanga: IC RF MODULE HSDPA                  I roto i te taonga: 2012 pcs</p> <p><b>RFQ</b></p>	<p><b>HL8548_1102648</b>                  Kaihanga: Sierra Wireless                  Whakaahuatanga: MOD HL HSPA+ PENTA 1.8V                  I roto i te taonga: 2404 pcs</p> <p><b>RFQ</b></p>
<p><b>HL8548-G_1102150</b>                  Kaihanga: Sierra Wireless                  Whakaahuatanga: 3G HSPA+ 2G PENTA-BAND GNSS AT&amp;T                  I roto i te taonga: 2190 pcs</p> <p><b>RFQ</b></p>	<p><b>HL8529_1103961</b>                  Kaihanga: Sierra Wireless                  Whakaahuatanga: MOD HL HSDPA 3G ATT                  I roto i te taonga: 2071 pcs</p> <p><b>RFQ</b></p>
<p><b>HL8518_1102589</b>                  Kaihanga: Sierra Wireless                  Whakaahuatanga: 3G HSPA+ 2G GPRS DUAL-BAND EU                  I roto i te taonga: 1850 pcs</p> <p><b>RFQ</b></p>	<p><b>HL8548_1102149</b>                  Kaihanga: Sierra Wireless                  Whakaahuatanga: 3G HSPA+ 2G PENTA-BAND MOD AT&amp;T                  I roto i te taonga: 6419 pcs</p> <p><b>RFQ</b></p>