




RAFI

## 5.00100.1950000

Tau Wae:	5.00100.1950000
Kaihanga / Waitohu:	RAFI
Whakaahuatanga hua	CONTACT BLOCK SPST-NO 0.1A 35V
Ngā Rauemi:	
RoHS Tūnga	 Whakahaerehia te kore utu / RoHS
Waehere Stock	6086 pcs stock
Tuhinga mai i	Hong Kong
Te Ara Tuhi	DHL/Fedex/TNT/UPS/EMS

[TONO MO TE WHAKAHUA](#)

Ko te whakaahua he tohu. Tirohia nga korero mo nga taipitopito hua.

## Ngā whakaaturanga o 5.00100.1950000

TAU WAE	5.00100.1950000
KAIHANGA	RAFI
WHAKAAHUATANGA	CONTACT BLOCK SPST-NO 0.1A 35V
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Whakahaerehia te kore utu / RoHS
HE RAHINGA KEI TE WĀTEA	6086 pcs
PEPA RARAUNGA	
KĀHUA WHAKAMUTUNGA	Solder, Quick Connect - 0.250" (6.3mm)
RAUPAPA	RAFIX 22 QR
E HIAHIA ANA	Switch Body
ĒTAHI INGOA	5.00.100.195/0000 5001001950000
WHAKAHAERE TOKO WHAKAHAERE / ROHS TŪNGA	Lead free / RoHS Compliant
WHAKAAHUATANGA TAIPITOPITO	Configurable Contact Block SPST-NO 0.1A @ 35VAC/DC
WHAKAPĀ ATU @ WHAKAOHO	0.1A @ 35VAC/DC
TAKAHANGA	SPST-NO

## Ngā tūtohu e hāngai ana

RAFI 5.00100.1950000	5.00100.1950000 Kaiwhiwhi	5.00100.1950000 Kaiwhakarato
5.00100.1950000 Utu	5.00100.1950000 Pikitia	5.00100.1950000 Whakaahua
5.00100.1950000 PDF Datasheet	5.00100.1950000 Download Datasheet	Tuhinga 5.00100.1950000
5.00100.1950000 Stock	Hokona 5.00100.1950000	Hokona RAFI 5.00100.1950000
RAFI 5.00100.1950000	RAFI Kaiwhakarato	RAFI Kaiwhiwhi
RAFI 5.00100.1950000	RAFI USA 5.00100.1950000	

## Ngā Hua e hāngai ana

 <p><b>5.00100.2210100</b> Kaihanga: RAFI Whakaahuatanga: CONTACT BLOCK DPST-NC 0.1A 35V I roto i te taonga: 2356 pcs</p> <p><a href="#">RFQ</a></p>	 <p><b>5.00100.2210000</b> Kaihanga: RAFI Whakaahuatanga: CONTACT BLOCK DPST-NC 0.1A 35V I roto i te taonga: 1952 pcs</p> <p><a href="#">RFQ</a></p>
 <p><b>5.00100.1930000</b> Kaihanga: RAFI Whakaahuatanga: CONTACT BLOCK SPST-NC 0.1A 35V I roto i te taonga: 7169 pcs</p> <p><a href="#">RFQ</a></p>	 <p><b>5.00100.1940000</b> Kaihanga: RAFI Whakaahuatanga: CONTACT BLOCK SPST-NC 10A 125V I roto i te taonga: 8829 pcs</p> <p><a href="#">RFQ</a></p>
 <p><b>5.00100.2240100</b> Kaihanga: RAFI Whakaahuatanga: CONTACT BLOCK DPST-NC 0.1A 35V I roto i te taonga: 1882 pcs</p> <p><a href="#">RFQ</a></p>	 <p><b>5.00100.1630000</b> Kaihanga: RAFI Whakaahuatanga: CONTACT BLOCK SPST 0.1A 35V I roto i te taonga: 6317 pcs</p> <p><a href="#">RFQ</a></p>
 <p><b>5.00100.1620000</b> Kaihanga: RAFI Whakaahuatanga: CONTACT BLOCK DPST-NO 0.1A 35V I roto i te taonga: 6590 pcs</p> <p><a href="#">RFQ</a></p>	 <p><b>5.00100.2270000</b> Kaihanga: RAFI Whakaahuatanga: CONTACT BLOCK DPST-NC 3A 120V I roto i te taonga: 1562 pcs</p> <p><a href="#">RFQ</a></p>
 <p><b>5.00100.1960000</b> Kaihanga: RAFI Whakaahuatanga: CONTACT BLOCK SPST-NO 10A 125V I roto i te taonga: 7863 pcs</p> <p><a href="#">RFQ</a></p>	 <p><b>5.00100.1640000</b> Kaihanga: RAFI Whakaahuatanga: CONTACT BLOCK SPST-NC 0.1A 35V I roto i te taonga: 8744 pcs</p> <p><a href="#">RFQ</a></p>
 <p><b>5.00100.2340100</b> Kaihanga: RAFI Whakaahuatanga: CONTACT BLOCK SPST 0.1A 35V I roto i te taonga: 1832 pcs</p> <p><a href="#">RFQ</a></p>	 <p><b>5.00100.1650000</b> Kaihanga: RAFI Whakaahuatanga: CONTACT BLOCK SPST-NO 0.1A 35V I roto i te taonga: 9309 pcs</p> <p><a href="#">RFQ</a></p>